

Chico Creek - Mud Creek - Units 2 North and 3 Unacceptable - Inactive	Unit 2 North - Mud Creek Above Sycamore Creek (CM2B)		Unit 3 - Sycamore Creek, Right Bank (CM3A)						
Operations and Maintenance Manuals	M	M							
Emergency Supplies and Equipment	M	M							
Flood Preparedness and Training	M	M							
Unwanted Vegetation Growth	U	U							
Sod Cover	N/A	N/A							
Encroachments	U	U							
Closure Structures	N/A	N/A							
Slope Stability	A	A							
Erosion/Bank Caving	M	M							
Settlement	A	A							
Depressions/Rutting	U	U							
Cracking	A	M							
Animal Control	U	U							
Culverts/Discharge Pipes	N/A	N/A							
Riprap Revetments & Bank Protection	N/A	N/A							
Revetments other than Riprap	N/A	N/A							
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A							
Seepage	A	M							
Segment & System Ratings/PL 84-99 Eligibility									<u>Legend</u>
Likely Prevents Performance In Next Flood Event									A Acceptable
Serious deficiency noted in past inspections has not been corrected within the established timeframe									M Minimally Acceptable
Not Likely to Prevent Performance In Next Flood Event									U Unacceptable
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility									April 25, 2011
									Rev: 7/12/2012