

City of Marysville - Units 1, 2, 3 Minimally Acceptable-Active							
	Unit 1 Jack Slough	Unit 2 Feather River	Unit 3 Yuba River				
Operations and Maintenance Manuals	M	M	M				
Emergency Supplies and Equipment	A	A	A				
Flood Preparedness and Training	M	M	M				
Unwanted Vegetation Growth	U	U	U				
Sod Cover	A	A	A				
Encroachments	U	U	U				
Closure Structures	A	A	A				
Slope Stability	U	A	M				
Erosion/Bank Caving	M	M	M				
Settlement	A	A	A				
Depressions/Rutting	A	A	A				
Cracking	A	A	A				
Animal Control	M	M	M				
Culverts/Discharge Pipes	NA	NA	NA				
Riprap Revetments & Bank Protection	NA	NA	M				
Revetments other than Riprap	NA	NA	NA				
Underseepage Relief Wells/Toe Drainage Systems	NA	NA	NA				
Seepage	A	A	A				
Segment & System Ratings/PL 84-99 Eligibility				<u>Legend</u>			
Likely Prevents Performance In Next Flood Event				A	Acceptable		
Serious deficiency noted in past inspections has not been corrected within the established timeframe				M	Minimally Acceptable		
Likely Prevents Performance In Next Flood Event (Framework)				U	Unacceptable		
Not Likely to Prevent Performance In Next Flood Event				N/A	Not Applicable		
Not Likely to Prevent Performance In Next Flood Event (Framework)							
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility					February 9, 2011		