

## Elder Creek Left Bank, Unit 4 East Unacceptable - Inactive

Elder Creek - Tehama  
County - Unit 4 East,  
Left Bank Below  
Gerber Levee (ELD1)

General Items	
Operations and Maintenance Manuals	M
Emergency Supplies and Equipment	M
Flood Preparedness and Training	M
Levee Embankment Items	
Vegetation Growth	U
Sod Cover	U
Encroachments	U
Closure Structures	N/A
Slope Stability	M
Erosion/Bank Caving	U
Settlement	A
Depressions/Rutting	M
Cracking	A
Animal Control	U
Culverts/Discharge Pipes	N/A
Riprap Revetments & Bank Protection	U
Revetments other than Riprap	N/A
Underseepage Relief Wells/Toe Drainage Systems	N/A
Seepage	A

Segment & System Ratings/PL 84-99 Eligibility

Likely Prevents Performance In Next Flood Event

Serious deficiency noted in past inspections has not been corrected within the established timeframe

Not Likely to Prevent Performance In Next Flood Event

The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility

### Legend

A	Acceptable
M	Minimally Acceptable
U	Unacceptable
N/A	Not Applicable

June 10, 2011