

		System LSJLD-Units 2,25 Unacceptable - Inactive		LSJLD- U 2 San Joaquin River left bank (L002)		LSJLD- U 25, Salt Slough (L025)					
General	Operations and Maintenance Manuals	A	A								
	Emergency Supplies and Equipment	A	A								
	Flood Preparedness and Training	A	A								
Levee Embankments	Unwanted Vegetation Growth	U	U								
	Sod Cover	NA	NA								
	Encroachments	U	U								
	Closure Structures	NA	NA								
	Slope Stability	A	A								
	Erosion/Bank Caving	U	A								
	Settlement	M	A								
	Depressions/Rutting	U	A								
	Cracking	A	A								
	Animal Control	M	A								
	Culverts/Discharge Pipes	NA	NA								
	Riprap Revetments & Bank Protection	NA	NA								
	Revetments other than Riprap	NA	NA								
	Underseepage Relief Wells/Toe Drainage Systems	NA	NA								
Seepage	M	M									
Flood Damage Reduction Channels	Vegetation and Obstructions	A	A								
	Shoaling	A	A								
	Encroachments	A	A								
	Erosion	A	A								
	Concrete Surfaces	NA	NA								
	Tilting, Sliding, or Settlement of Concrete	NA	NA								
	Foundation of Concrete Structures	NA	NA								
	Slab and Monolith Joints	NA	NA								
	Flap Gates/Flap Valves/Pinch Valves	NA	NA								
	Riprap Revetments & Banks	NA	NA								
	Revetments other than Riprap	NA	NA								
										<u>Legend</u>	
Likely Prevents Performance In Next Flood Event/Inactive										A Acceptable	
Serious deficiency noted in past inspections has not been corrected within the established timeframe										M Minimally Acceptable	
Not Likely to Prevent Performance In Next Flood Event/Active										U Unacceptable	
										N/A Not Applicable	
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Eligibility										1/27/2012	