

		System								
		LSJLD-Units 1, 6, and 11 Minimally Acceptable - Active			LSJLD- U 1 San Joaquin R rt bnk below Mariposa Byp (L01B)	LSJLD- U6 Deep Sligh left bank below Mariposa Byp (L06A)	LSJLD-U 11 Mariposa Bypass north levee (L011)			
General	Operations and Maintenance Manuals	A	A	A						
	Emergency Supplies and Equipment	A	A	A						
	Flood Preparedness and Training	A	A	A						
Levee Embankments	Unwanted Vegetation Growth	U	M	U						
	Sod Cover	NA	NA	NA						
	Encroachments	U	U	U						
	Closure Structures	NA	NA	NA						
	Slope Stability	A	M	A						
	Erosion/Bank Caving	A	M	A						
	Settlement	A	A	A						
	Depressions/Rutting	U	A	A						
	Cracking	A	A	A						
	Animal Control	M	M	A						
	Culverts/Discharge Pipes	NA	NA	NA						
	Riprap Revetments & Bank Protection	NA	NA	NA						
	Revetments other than Riprap	NA	NA	NA						
	Underseepage Relief Wells/Toe Drainage Systems	NA	NA	NA						
Seepage	A	A	A							
Flood Damage Reduction Channels	Vegetation and Obstructions	A	M	A						
	Shoaling	A	A	A						
	Encroachments	A	U	M						
	Erosion	A	A	A						
	Concrete Surfaces	NA	A	U						
	Tilting, Sliding, or Settlement of Concrete	NA	NA	M						
	Foundation of Concrete Structures	NA	NA	NA						
	Slab and Monolith Joints	NA	NA	NA						
	Flap Gates/Flap Valves/Pinch Valves	NA	NA	NA						
	Riprap Revetments & Banks	NA	NA	NA						
Revetments other than Riprap	NA	NA	NA							
								Legend		
Likely Prevents Performance In Next Flood Event/Inactive								A	Acceptable	
Serious deficiency noted in past inspections has not been corrected within the established timeframe								M	Minimally Acceptable	
Not Likely to Prevent Performance In Next Flood Event/Active								U	Unacceptable	
								N/A	Not Applicable	
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Eligibility										