

**Maintenance Area 13 Unit 2 North -
Cherokee Canal Left Bank
Unacceptable - Inactive**

Unit 2 north, Cherokee Canal left bank
(M13G)

Unit 2, Cottonwood Creek right bank (M13J)

General Items		
Operations and Maintenance Manuals	M	M
Emergency Supplies and Equipment	A	A
Flood Preparedness and Training	A	A
Levee Embankment Items		
Vegetation Growth	U	U
Sod Cover	NA	M
Encroachments	U	U
Closure Structures	N/A	N/A
Slope Stability	M	A
Erosion/Bank Caving	M	M
Settlement	A	A
Depressions/Rutting	U	A
Cracking	M	A
Animal Control	U	U
Culverts/Discharge Pipes	N/A	N/A
Riprap Revetments & Bank Protection	A	N/A
Revetments other than Riprap	N/A	N/A
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A
Seepage	A	A

Segment & System Ratings/PL 84-99 Eligibility

Likely Prevents Performance In Next Flood Event

Serious deficiency noted in past inspections has not been corrected within the established timeframe

Not Likely to Prevent Performance In Next Flood Event

The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility

Legend

A	Acceptable
M	Minimally Acceptable
U	Unacceptable
N/A	Not Applicable