

		System Middle Creek Right Bank - Unit 2 Unacceptable - Inactive								
		Middle Creek- Lake Co- U 2 right bank abv Scotts C (MC2B)								
General	Operations and Maintenance Manuals	A	A							
	Emergency Supplies and Equipment	A	A							
	Flood Preparedness and Training	A	A							
Levee Embankments	Unwanted Vegetation Growth	U	U							
	Sod Cover	NA	NA							
	Encroachments	U	U							
	Closure Structures	NA	NA							
	Slope Stability	A	A							
	Erosion/Bank Caving	A	A							
	Settlement	A	A							
	Depressions/Rutting	A	A							
	Cracking	A	A							
	Animal Control	A	A							
	Culverts/Discharge Pipes	NA	NA							
	Riprap Revetments & Bank Protection	NA	NA							
	Revetments other than Riprap	NA	NA							
	Underseepage Relief Wells/Toe Drainage Systems	NA	NA							
Seepage	A	A								
Flood Damage Reduction Channels	Vegetation and Obstructions	A	A							
	Shoaling	A	A							
	Encroachments	A	A							
	Erosion	A	A							
	Concrete Surfaces	NA	NA							
	Tilting, Sliding, or Settlement of Concrete	NA	NA							
	Foundation of Concrete Structures	NA	NA							
	Slab and Monolith Joints	NA	NA							
	Flap Gates/Flap Valves/Pinch Valves	NA	NA							
	Riprap Revetments & Banks	NA	NA							
Revetments other than Riprap	NA	NA								
Legend										
Likely Prevents Performance In Next Flood Event/Inactive										
Serious deficiency noted in past inspections has not been corrected within the established timeframe										
Not Likely to Prevent Performance In Next Flood Event/Active										
The worst rating is used to determine the overall segment & system ratings and PL 84-99 Eligibility										
		A	Acceptable							
		M	Minimally Acceptable							
		U	Unacceptable							
		N/A	Not Applicable							