

		System Middle Creek Left Bank - Unit 1 North Unacceptable - Inactive									
				Middle Creek- Lake Co- U 1 north left bank (MC1A)		Middle Creek - Lake Co - U 4 Alley Creek right bank (MC04)					
General	Operations and Maintenance Manuals	A	A								
	Emergency Supplies and Equipment	A	A								
	Flood Preparedness and Training	A	A								
Levee Embankments	Unwanted Vegetation Growth	U	U								
	Sod Cover	NA	NA								
	Encroachments	U	U								
	Closure Structures	NA	NA								
	Slope Stability	A	A								
	Erosion/Bank Caving	A	A								
	Settlement	A	A								
	Depressions/Rutting	M	M								
	Cracking	A	A								
	Animal Control	A	A								
	Culverts/Discharge Pipes	NA	NA								
	Riprap Revetments & Bank Protection	NA	NA								
	Revetments other than Riprap	NA	NA								
	Underseepage Relief Wells/Toe Drainage Systems	NA	NA								
Seepage	A	A									
Flood Damage Reduction Channels	Vegetation and Obstructions	A	A								
	Shoaling	A	A								
	Encroachments	A	A								
	Erosion	A	A								
	Concrete Surfaces	NA	NA								
	Tilting, Sliding, or Settlement of Concrete	NA	NA								
	Foundation of Concrete Structures	NA	NA								
	Slab and Monolith Joints	NA	NA								
	Flap Gates/Flap Valves/Pinch Valves	NA	NA								
	Riprap Revetments & Banks	NA	NA								
Revetments other than Riprap	NA	NA									
										Legend	
Likely Prevents Performance In Next Flood Event/Inactive										A Acceptable	
Serious deficiency noted in past inspections has not been corrected within the established timeframe										M Minimally Acceptable	
Not Likely to Prevent Performance In Next Flood Event/Active										U Unacceptable	
The worst rating is used to determine the overall segment & system ratings and PL 84-99 Eligibility										N/A Not Applicable	