

System Middle Creek Left Bank - Unit 1 at Clear Lake Unacceptable - Inactive		Middle Creek- Lake Co- U 1 left bank at Clear Lake (MC1D)								
General	Operations and Maintenance Manuals	A								
	Emergency Supplies and Equipment	A								
	Flood Preparedness and Training	A								
Levee Embankments	Unwanted Vegetation Growth	U								
	Sod Cover	NA								
	Encroachments	U								
	Closure Structures	NA								
	Slope Stability	A								
	Erosion/Bank Caving	A								
	Settlement	U								
	Depressions/Rutting	M								
	Cracking	A								
	Animal Control	A								
	Culverts/Discharge Pipes	NA								
	Riprap Revetments & Bank Protection	NA								
	Revetments other than Riprap	NA								
	Underseepage Relief Wells/Toe Drainage Systems	NA								
Seepage	A									
Flood Damage Reduction Channels	Vegetation and Obstructions	A								
	Shoaling	A								
	Encroachments	A								
	Erosion	A								
	Concrete Surfaces	NA								
	Tilting, Sliding, or Settlement of Concrete	NA								
	Foundation of Concrete Structures	NA								
	Slab and Monolith Joints	NA								
	Flap Gates/Flap Valves/Pinch Valves	NA								
	Riprap Revetments & Banks	NA								
	Revetments other than Riprap	NA								
Legend										
Likely Prevents Performance In Next Flood Event/Inactive										
Serious deficiency noted in past inspections has not been corrected within the established timeframe										
Not Likely to Prevent Performance In Next Flood Event/Active										
The worst rating is used to determine the overall segment & system ratings and PL 84-99 Eligibility										
A Acceptable M Minimally Acceptable U Unacceptable N/A Not Applicable										