

System 5 Mormon Slough - Right Bank - Unit 15 East Unacceptable -Inactive		Unit 15 East, Right Bank (MSL5)							
Operations and Maintenance Manuals	M								
Emergency Supplies and Equipment	M								
Flood Preparedness and Training	M								
Unwanted Vegetation Growth	U								
Sod Cover	U								
Encroachments	U								
Closure Structures	N/A								
Slope Stability	U								
Erosion/Bank Caving	A								
Settlement	A								
Depressions/Rutting	M								
Cracking	U								
Animal Control	U								
Culverts/Discharge Pipes	N/A								
Riprap Revetments & Bank Protection	N/A								
Revetments other than Riprap	U								
Underseepage Relief Wells/Toe Drainage Systems	N/A								
Seepage	A								
Segment & System Ratings/PL 84-99 Eligibility		<u>Legend</u>							
Likely Prevents Performance In Next Flood Event		A Acceptable							
Serious deficiency noted in past inspections has not been corrected within the established timeframe		M Minimally Acceptable							
Not Likely to Prevent Performance In Next Flood Event		U Unacceptable							
		N/A Not Applicable							
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility									
									November 3, 2011