

**North Fork Feather River at Chester,  
east levee  
Unacceptable Inactive**

North Fork Feather River at  
Chester, east levee (FRC2)

Operations and Maintenance Manuals	A				
Emergency Supplies and Equipment	A				
Flood Preparedness and Training	A				
Unwanted Vegetation Growth	U				
Sod Cover	NA				
Encroachments	U				
Closure Structures	NA				
Slope Stability	A				
Erosion/Bank Caving	A				
Settlement	A				
Depressions/Rutting	M				
Cracking	A				
Animal Control	A				
Culverts/Discharge Pipes	NA				
Riprap Revetments & Bank Protection	NA				
Revetments other than Riprap	NA				
Underseepage Relief Wells/Toe Drainage Systems	NA				
Seepage	A				

**Segment & System Ratings/PL 84-99 Eligibility**

Likely Prevents Performance In Next Flood Event/Inactive

Serious deficiency noted in past inspections has not been corrected within the established timeframe

Not Likely to Prevent Performance In Next Flood Event/Active

Legend

- A Acceptable
- M Minimally Acceptable
- U Unacceptable
- N/A Not Applicable

The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Eligibility

12-Jul-11