

**Putah Creek Unit 1 - Yolo Bypass -
Willow Slough Unit 2
Unacceptable-Inactive**

Willow Slough Bypass -
Unit 2, Right Bank
(WBP2)

Yolo Bypass - West
Levee - Unit 4 (YBW4)

Putah Creek - Unit 1,
Left Bank (PUT1)

General Items

Operations and Maintenance Manuals	A	A	A
Emergency Supplies and Equipment	A	A	A
Flood Preparedness and Training	A	A	A

Levee Embankment Items

Vegetation Growth	U	U	U
Sod Cover	U	A	A
Encroachments	U	U	U
Closure Structures	N/A	N/A	N/A
Slope Stability	M	A	U
Erosion/Bank Caving	U	U	U
Settlement	M	M	M
Depressions/Rutting	U	U	U
Cracking	U	U	U
Animal Control	M	M	M
Culverts/Discharge Pipes	N/A	N/A	N/A
Riprap Revetments & Bank Protection	M	M	M
Revetments other than Riprap	N/A	U	N/A
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	N/A
Seepage	A	A	A

Floodwalls

Unwanted Vegetation Growth	N/A	N/A	U
Encroachments	N/A	N/A	U
Closure Structures	N/A	N/A	N/A
Concrete Surfaces	N/A	N/A	N/A
Tilting, Sliding or Settlement of Concrete Structures	N/A	N/A	A
Foundation of Concrete Structures	N/A	N/A	A
Monolith Joints	N/A	N/A	A
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	U
Seepage	N/A	N/A	A

Segment & System Ratings/PL 84-99 Eligibility

Likely Prevents Performance In Next Flood Event

Serious deficiency noted in past inspections has not been corrected within the established timeframe

Not Likely to Prevent Performance In Next Flood Event

The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility

Legend

- A Acceptable
- M Minimally Acceptable
- U Unacceptable
- N/A Not Applicable