

**RD 0524 & 0544 Roberts Island -
Levee System
Unacceptable/Inactive**

RD 0524 - Middle Roberts Island

RD 0544 - Upper Roberts Island,
Unit 1 San Joaquin River left bank

RD 0544 - Upper Roberts Island,
Unit 2 Old River

Operations and Maintenance Manuals	A	A	A
Emergency Supplies and Equipment	M	M	M
Flood Preparedness and Training	M	M	M
Unwanted Vegetation Growth	U	U	U
Sod Cover	U	U	U
Encroachments	U	U	U
Closure Structures	NA	NA	NA
Slope Stability	M	M	M
Erosion/Bank Caving	U	U	A
Settlement	U	U	A
Depressions/Rutting	U	U	A
Cracking	A	A	A
Animal Control	U	U	U
Culverts/Discharge Pipes	NA	NA	NA
Riprap Revetments & Bank Protection	NA	NA	M
Revetments other than Riprap	NA	NA	NA
Underseepage Relief Wells/Toe Drainage Systems	NA	NA	NA
Seepage	A	A	A
Overall Rating	U	U	U

Item Rating Classification	Time to Fix Before Becoming Inactive
Likely to Prevent the system from performing as intended during the next flood event.	Red issues cause the system to become inactive immediately.
Serious deficiency noted in a past inspection has not been corrected within the established	Pink issues have already exceeded previous timeline for repair,
Not likely to prevent the system from performing as intended during the next flood event.	2 years from date of this letter unless otherwise specified.
The worst rating is used to determine the overall segment and system ratings and PL 84-99 Rehabilitation Assistance Eligibility.	