

RD 0784 - Plumas Lakes Basin
Minimally Acceptable - Active

MA 8, Yuba River (PLUM)

Unit 1, Yuba River (PLU1)

Unit 2, Feather River (PLU2)

Unit 3 West, Bear River below Union Pacific Interceptor (PLU3)

Unit 4, Best Slough - Union Pacific Interceptor Right Bank (PLU4)

General Items

Operations and Maintenance Manuals	A	A	A	A	A				
Emergency Supplies and Equipment	A	A	A	A	A				
Flood Preparedness and Training	A	A	A	A	A				

Levee Embankment Items

Vegetation Growth	U	U	M	U	U				
Sod Cover	A	A	A	A	A				
Encroachments	U	U	U	U	U				
Closure Structures	N/A	A	N/A	N/A	N/A				
Slope Stability	M	M	A	A	U				
Erosion/Bank Caving	A	A	A	A	U				
Settlement	M	M	M	M	M				
Depressions/Rutting	U	U	U	M	M				
Cracking	A	A	A	A	U				
Animal Control	U	A	A	A	A				
Culverts/Discharge Pipes	N/A	N/A	N/A	N/A	N/A				
Riprap Revetments & Bank Protection	N/A	A	N/A	A	A				
Revetments other than Riprap	N/A	N/A	N/A	N/A	N/A				
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	U	U	N/A				
Seepage	A	A	A	A	A				

Segment & System Ratings/PL 84-99 Eligibility

Legend

- A Acceptable
- M Minimally Acceptable
- U Unacceptable
- N/A Not Applicable

Likely Prevents Performance In Next Flood Event
Serious deficiency noted in past inspections has not been corrected within the established timeframe
Not Likely to Prevent Performance In Next Flood Event

The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility