

**Surplus Canal Right Bank- Salt Lake
City, UT Levee System
Unacceptable-Inactive**

Surplus Canal Right Bank
(IRD2)

General Items	
Operations and Maintenance Manuals	A
Emergency Supplies and Equipment	A
Flood Preparedness and Training	M
Levee Embankment Items	
Unwanted Vegetation Growth	U
Sod Cover	U
Encroachments	U
Closure Structures	N/A
Slope Stability	M
Erosion/Bank Caving	M
Settlement	M
Depressions/Rutting	U
Cracking	A
Animal Control	M
Culverts/Discharge Pipes	N/A
Riprap Revetments & Bank Protection	U
Revetments other than Riprap	N/A
Underseepage Relief Wells/Toe Drainage Systems	N/A
Seepage	A

Segment & System Ratings/PL 84-99 Eligibility

- Likely Prevents Performance In Next Flood Event
- Serious deficiency noted in past inspections has not been corrected within the established timeframe
- Not Likely to Prevent Performance In Next Flood Event

The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility

Legend	
A	Acceptable
M	Minimally Acceptable
U	Unacceptable
N/A	Not Applicable