

**Feather River Right Bank – Sutter  
Bypass East Bank Levee System  
Unacceptable-Inactive**

Feather River – Hamilton West Levee – South of Afterbay Outflow Dam	Maintenance Area 07	Reclamation District 777 Live Oak – Maintenance Area 16	Levee District 9 – Sutter County	Levee District 1 – Sutter County	Maintenance Area 03	Sutter Bypass – East Levee – South of Wadsworth Canal	Wadsworth Canal – Unit 1, Left Bank	Interceptor Canal – Unit 1, East Canal
--	---------------------	--	----------------------------------	----------------------------------	---------------------	--	-------------------------------------	--

Operations and Maintenance Manuals	M	M	M	M	M	M	M	M	M
Emergency Supplies and Equipment	A	A	A	M	A	A	A	A	A
Flood Preparedness and Training	A	A	A	M	A	A	A	A	A
Unwanted Vegetation Growth	U	U	U	U	U	U	U	U	U
Sod Cover	N/A	M	M	M	M	M	M	M	A
Encroachments	U	U	U	U	U	U	U	U	U
Closure Structures	U	N/A	N/A	A	A	N/A	N/A	A	N/A
Slope Stability	M	U	A	U	M	M	M	A	M
Erosion/Bank Caving	A	U	U	U	U	U	U	U	U
Settlement	A	A	A	A	A	A	A	A	A
Depressions/Rutting	U	U	M	U	M	M	U	M	U
Cracking	A	A	A	A	A	A	A	A	A
Animal Control	A	M	M	M	M	M	M	M	M
Culverts/Discharge Pipes	N/A	N/A	N/A	N/A	N/A	N/A	U	N/A	N/A
Riprap Revetments & Bank Protection	N/A	M	N/A	N/A	M	M	M	N/A	N/A
Revetments other than Riprap	A	N/A	N/A	U	M	N/A	M	N/A	N/A
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	N/A	N/A	U	N/A	N/A	N/A	N/A
Seepage	A	A	A	A	A	A	A	A	A

Segment & System Ratings/PL 84-99 Eligibility	<b>Legend</b>
Likely Prevents Performance In Next Flood Event	A Acceptable
Serious deficiency noted in past inspections has not been corrected within the established timeframe	M Minimally Acceptable
Not Likely to Prevent Performance In Next Flood Event	U Unacceptable
	N/A Not Applicable
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility	