

System 1 Bear Creek - Units 7 West and 21 Unacceptable - Active		Unit 7 West, Bear Creek Right Bank Below Pixley Slough (BC01)		Unit 21, Pixley Slough Right Bank (BC09)						
Operations and Maintenance Manuals	M	M								
Emergency Supplies and Equipment	M	M								
Flood Preparedness and Training	M	M								
Unwanted Vegetation Growth	U	U								
Sod Cover	U	U								
Encroachments	U	U								
Closure Structures	N/A	N/A								
Slope Stability	M	M								
Erosion/Bank Caving	M	U								
Settlement	A	A								
Depressions/Rutting	M	U								
Cracking	A	U								
Animal Control	U	U								
Culverts/Discharge Pipes	N/A	N/A								
Riprap Revetments & Bank Protection	U	U								
Revetments other than Riprap	N/A	N/A								
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A								
Seepage	A	A								
Segment & System Ratings/PL 84-99 Eligibility						<u>Legend</u>				
Likely Prevents Performance In Next Flood Event						A Acceptable				
Serious deficiency noted in past inspections has not been corrected within the established timeframe						M Minimally Acceptable				
Likely Prevents Performance In Next Flood Event (Framework)						U Unacceptable				
Not Likely to Prevent Performance In Next Flood Event						N/A Not Applicable				
Not Likely to Prevent Performance In Next Flood Event (Framework)										
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility						August 4, 2011				