

<p style="text-align: center;"><b>System 1</b>  <b>Mormon Slough - Calaveras River</b>  <b>Right Bank - RD 2074</b>  <b>Unacceptable - Inactive</b></p>	<p style="text-align: center;">Unit 15 West, Calaveras River Right Bank (MSL1)</p>	<p style="text-align: center;">RD 2074 - Sargent-Barnhardt Tract - Unit 1, Stockton Deep Water Channel (SBT1)</p>	<p style="text-align: center;">RD 2074 - Sargent-Barnhardt Tract - Unit 2, Tennile Slough (SBT2)</p>	<p style="text-align: center;">RD 2074 - Sargent-Barnhardt Tract - Unit 3, Fourmile Slough (SBT3)</p>					
Operations and Maintenance Manuals	M	M	M	M					
Emergency Supplies and Equipment	M	M	M	M					
Flood Preparedness and Training	M	M	M	M					
Unwanted Vegetation Growth	U	U	U	U					
Sod Cover	U	U	U	U					
Encroachments	U	U	U	U					
Closure Structures	N/A	N/A	N/A	N/A					
Slope Stability	M	A	A	A					
Erosion/Bank Caving	U	A	A	A					
Settlement	M	A	A	A					
Depressions/Rutting	U	M	M	A					
Cracking	U	A	M	M					
Animal Control	U	U	M	M					
Culverts/Discharge Pipes	N/A	N/A	N/A	N/A					
Riprap Revetments & Bank Protection	U	N/A	N/A	N/A					
Revetments other than Riprap	N/A	N/A	N/A	N/A					
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	N/A	N/A					
Seepage	A	A	A	A					
Segment & System Ratings/PL 84-99 Eligibility					<u>Legend</u>				
Likely Prevents Performance In Next Flood Event					A     Acceptable				
Serious deficiency noted in past inspections has not been corrected within the established timeframe					M     Minimally Acceptable				
Not Likely to Prevent Performance In Next Flood Event					U     Unacceptable				
					N/A    Not Applicable				
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility									
									August 4, 2011