

System 2 Bear Creek - Units 7, 22 and 23 Unacceptable - Inactive	Unit 7, Bear Creek Right Bank Above Pixley Slough (BC02)			Unit 22, Pixley Slough Left Bank (BC10)			Unit 23, Spur Levee Along RR Tracks, Bear Creek Right Bank (BC11)						
Operations and Maintenance Manuals	M	M	M										
Emergency Supplies and Equipment	M	M	M										
Flood Preparedness and Training	M	M	M										
Unwanted Vegetation Growth	U	U	U										
Sod Cover	M	U	N/A										
Encroachments	U	U	U										
Closure Structures	N/A	N/A	N/A										
Slope Stability	M	M	M										
Erosion/Bank Caving	M	U	A										
Settlement	A	A	A										
Depressions/Rutting	U	M	U										
Cracking	U	M	M										
Animal Control	U	U	U										
Culverts/Discharge Pipes	N/A	N/A	N/A										
Riprap Revetments & Bank Protection	U	U	N/A										
Revetments other than Riprap	N/A	N/A	N/A										
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	N/A										
Seepage	A	A	A										
Segment & System Ratings/PL 84-99 Eligibility													
Likely Prevents Performance In Next Flood Event													
Serious deficiency noted in past inspections has not been corrected within the established timeframe													
Not Likely to Prevent Performance In Next Flood Event													
	<p><u>Legend</u></p> <p>A Acceptable</p> <p>M Minimally Acceptable</p> <p>U Unacceptable</p> <p>N/A Not Applicable</p>												
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility													
August 4, 2011													