

System 4 Bear Creek - Unit 8, West of I-5 Unacceptable - Inactive		Unit 8, Bear Creek Left Bank West of I-5 (BC18)							
Operations and Maintenance Manuals	M								
Emergency Supplies and Equipment	M								
Flood Preparedness and Training	M								
Unwanted Vegetation Growth	U								
Sod Cover	M								
Encroachments	U								
Closure Structures	N/A								
Slope Stability	A								
Erosion/Bank Caving	M								
Settlement	A								
Depressions/Rutting	M								
Cracking	A								
Animal Control	U								
Culverts/Discharge Pipes	N/A								
Riprap Revetments & Bank Protection	N/A								
Revetments other than Riprap	N/A								
Underseepage Relief Wells/Toe Drainage Systems	N/A								
Seepage	A								
Segment & System Ratings/PL 84-99 Eligibility		<u>Legend</u>							
Likely Prevents Performance In Next Flood Event		A Acceptable							
Serious deficiency noted in past inspections has not been corrected within the established timeframe		M Minimally Acceptable							
Likely Prevents Performance In Next Flood Event (Framework)		U Unacceptable							
Not Likely to Prevent Performance In Next Flood Event		N/A Not Applicable							
Not Likely to Prevent Performance In Next Flood Event (Framework)									
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility									
									November 29, 2010