

System 5 Bear Creek - Units 8, 25 and 27 Unacceptable - Inactive	Unit 8, Bear Creek Left Bank Below Mosher Creek (BC04)		Units 25 and 27, Mosher Creek Left Bank (BC12)						
Operations and Maintenance Manuals	M	M							
Emergency Supplies and Equipment	M	M							
Flood Preparedness and Training	M	M							
Unwanted Vegetation Growth	U	U							
Sod Cover	U	U							
Encroachments	U	U							
Closure Structures	N/A	N/A							
Slope Stability	M	M							
Erosion/Bank Caving	M	U							
Settlement	A	A							
Depressions/Rutting	U	U							
Cracking	U	U							
Animal Control	U	U							
Culverts/Discharge Pipes	N/A	N/A							
Riprap Revetments & Bank Protection	U	A							
Revetments other than Riprap	N/A	N/A							
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A							
Seepage	A	A							
Segment & System Ratings/PL 84-99 Eligibility					<u>Legend</u>				
Likely Prevents Performance In Next Flood Event					A Acceptable				
Serious deficiency noted in past inspections has not been corrected within the established timeframe					M Minimally Acceptable				
Not Likely to Prevent Performance In Next Flood Event					U Unacceptable				
					N/A Not Applicable				
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility									
									November 29, 2010