

System 6
Bear Creek - Units 8, 24, 26 and 9
Unacceptable - Inactive

	Unit 8, Bear Creek Left Bank Above Mosher Creek (BC05)	Units 24 and 26, Mosher Creek Right Bank (BC13)	Unit 9, Paddy Creek Left Bank (BC14)					
Operations and Maintenance Manuals	M	M	M					
Emergency Supplies and Equipment	M	M	M					
Flood Preparedness and Training	M	M	M					
Unwanted Vegetation Growth	U	U	U					
Sod Cover	M	U	U					
Encroachments	U	U	U					
Closure Structures	N/A	N/A	N/A					
Slope Stability	M	M	M					
Erosion/Bank Caving	M	M	M					
Settlement	A	A	A					
Depressions/Rutting	U	U	U					
Cracking	U	U	A					
Animal Control	U	U	U					
Culverts/Discharge Pipes	N/A	N/A	N/A					
Riprap Revetments & Bank Protection	U	A	U					
Revetments other than Riprap	N/A	N/A	N/A					
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	N/A					
Seepage	A	A	A					

Segment & System Ratings/PL 84-99 Eligibility

- Likely Prevents Performance In Next Flood Event
- Serious deficiency noted in past inspections has not been corrected within the established timeframe
- Not Likely to Prevent Performance In Next Flood Event

Legend

- A Acceptable
- M Minimally Acceptable
- U Unacceptable
- N/A Not Applicable

The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility

November 1, 2011