

System 7 Bear Creek - Units 8 , 10 and 11 Unacceptable - Inactive		Unit 8 East, Bear Creek Left Bank Above Paddy Creek (BC06)		Units 10 and 11, Paddy Creek Right Bank (BC15)						
Operations and Maintenance Manuals	M	M								
Emergency Supplies and Equipment	M	M								
Flood Preparedness and Training	M	M								
Unwanted Vegetation Growth	U	U								
Sod Cover	U	U								
Encroachments	U	U								
Closure Structures	N/A	N/A								
Slope Stability	U	M								
Erosion/Bank Caving	M	M								
Settlement	A	A								
Depressions/Rutting	U	U								
Cracking	A	A								
Animal Control	U	U								
Culverts/Discharge Pipes	N/A	N/A								
Riprap Revetments & Bank Protection	U	U								
Revetments other than Riprap	N/A	N/A								
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A								
Seepage	A	A								
Segment & System Ratings/PL 84-99 Eligibility										
Likely Prevents Performance In Next Flood Event										
Serious deficiency noted in past inspections has not been corrected within the established timeframe										
Not Likely to Prevent Performance In Next Flood Event										
<p style="text-align: right;"><u>Legend</u></p> <p>A Acceptable</p> <p>M Minimally Acceptable</p> <p>U Unacceptable</p> <p>N/A Not Applicable</p>										
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility										
November 1, 2011										