

System 8 Bear Creek - Units 12 South, 10 and 13 Unacceptable - Inactive	Unit 13, Middle Paddy Creek Left Bank (BC08)			Unit 10 East, South Paddy Creek Right Bank (BC16)			Unit 12 South, Paddy Creek Left Bank (BC17)		
Operations and Maintenance Manuals	M	M	M						
Emergency Supplies and Equipment	M	M	M						
Flood Preparedness and Training	M	M	M						
Unwanted Vegetation Growth	U	U	U						
Sod Cover	N/A	N/A	N/A						
Encroachments	U	U	U						
Closure Structures	N/A	N/A	N/A						
Slope Stability	A	A	A						
Erosion/Bank Caving	M	A	M						
Settlement	A	A	A						
Depressions/Rutting	A	A	A						
Cracking	A	A	A						
Animal Control	U	U	U						
Culverts/Discharge Pipes	N/A	N/A	N/A						
Riprap Revetments & Bank Protection	U	U	U						
Revetments other than Riprap	N/A	N/A	N/A						
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	N/A						
Seepage	A	A	A						
Segment & System Ratings/PL 84-99 Eligibility							<u>Legend</u>		
Likely Prevents Performance In Next Flood Event							A	Acceptable	
Serious deficiency noted in past inspections has not been corrected within the established timeframe							M	Minimally Acceptable	
Not Likely to Prevent Performance In Next Flood Event							U	Unacceptable	
							N/A	Not Applicable	
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility								August 4, 2011	