

Site Name	Waterway	River Mile	Levee Mile	Bank	Levee Maintaining Agency	Economic Impact Area	Erosion Status	Year Added	Site Length (ft)	Berm Width (ft)	Erosion Mechanism(s)	Revetment Details	Veg Variance Required?	Encroachment Details	Site History	2017 Field Notes
FHR 12.3 R	Feather River	12.3	0	R	Maintenance Area 3	Yuba City	Under Construction	2015	177	15	Toe Scour	None	Likely	None	2013 - Minor toe scour causing gradual erosion of bank slope. Site is within ecological reserve.	Under construction. work in progress.
FHR 12.8 R	Feather River	12.8	0	R	Maintenance Area 3	Yuba City	Under Construction	2015	293	15	Toe Scour	None	Likely	None	2013 - Minor toe scour causing gradual erosion into the bank slope.	Under construction. work in progress.
SAC 71.3 R	Sacramento River	71.3	0	R	RD 1600 - Mull District	Elkhorn	Under Construction	1997	522	25	Toe Scour, Fluvial	None	Likely	None	2000 - Very cohesive vertical bank. 2003 - Some minor new erosion. 2006 - Some minor erosion in old pockets. 2009 - Minimal new erosion. 2011 - Multiple new erosion pockets and a few new tree popouts.	New erosion pocket and fresh toe erosion. Site is currently under construction.
WPC 0.1 R	Western Pacific Interceptor Canal	1.6	0	R	RD 784 - Plumas Lake	Arboga	Under Construction	2017	31,652	0			Unlikely	Pipe		Entire levee was under construction.
									32,644							