

		<b>System</b> <b>Pit River at Alturas, right bank - E of town</b> <b>Unacceptable - Inactive</b>		North Fork Pit River - right bank - E of town (ALT1)							
<b>General</b>	Operations and Maintenance Manuals	A									
	Emergency Supplies and Equipment	A									
	Flood Preparedness and Training	A									
<b>Levee Embankments</b>	Unwanted Vegetation Growth	A									
	Sod Cover	NA									
	Encroachments	U									
	Closure Structures	NA									
	Slope Stability	A									
	Erosion/Bank Caving	A									
	Settlement	A									
	Depressions/Rutting	M									
	Cracking	A									
	Animal Control	A									
	Culverts/Discharge Pipes	NA									
	Riprap Revetments & Bank Protection	NA									
	Revetments other than Riprap	NA									
	Underseepage Relief Wells/Toe Drainage Systems	NA									
	Seepage	A									
<b>Flood Damage Reduction Channels</b>	Vegetation and Obstructions	A									
	Shoaling	A									
	Encroachments	U									
	Erosion	A									
	Concrete Surfaces	NA									
	Tilting, Sliding, or Settlement of Concrete	NA									
	Foundation of Concrete Structures	NA									
	Slab and Monolith Joints	NA									
	Flap Gates/Flap Valves/Pinch Valves	NA									
	Riprap Revetments & Banks	NA									
	Revetments other than Riprap	NA									
Likely Prevents Performance In Next Flood Event/Inactive											
Serious deficiency noted in past inspections has not been corrected within the established timeframe											
Not Likely to Prevent Performance In Next Flood Event/Active											
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Eligibility											
<b>Legend</b> A    Acceptable M    Minimally Acceptable U    Unacceptable N/A    Not Applicable											
1/27/2012											