System 3
Mormon Slough - Calaveras, Diverting Canal Left Bank
Unacceptable - Inactive

	Unit 16 West, Calaveras River Left Bank (MSL6)	Unit 16, Stockton Diverting Canal Left Bank (MSL7)	Unit 16, Mormon Slough Left Bank Above Stockton Diverting Canal (MSL8)	Unit 18, Potter Creek Left Bank (MSLP)					
Operations and Maintenance Manuals	M	M	M	M					
Emergency Supplies and Equipment	M	M	M	M					
Flood Preparedness and Training	M	M	M	M					
Unwanted Vegetation Growth	U	U	U	U					
Sod Cover	U	U	M	M					
Encroachments	U	U	U	U					
Closure Structures	N/A	N/A	N/A	N/A					
Slope Stability	M	A	A	A					
Erosion/Bank Caving	U	A	A	A					
Settlement	A	A	A	A					
Depressions/Rutting	U	U	M	M					
Cracking	M	U	U	M					
Animal Control	U	U	M	M					
Culverts/Discharge Pipes	N/A	N/A	N/A	N/A					
Riprap Revetments & Bank Protection	A	U	U	N/A					
Revetments other than Riprap	N/A	N/A	N/A	N/A					
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	N/A	N/A					
Seepage	A	A	A	A					

Segment & System Ratings/PL 84-99 Eligibility

Likely Prevents Performance In Next Flood Event

Serious deficiency noted in past inspections has not been corrected within the established timeframe

Not Likely to Prevent Performance In Next Flood Event

The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility

Legend

A	Acceptable
M	Minimally Acceptable
U	Unacceptable
N/A	Not Applicable