TABLE OF CONTENTS

1. INTRODUCTION 1
2. SITE DESCRIPTION 1
3. DESCRIPTION OF ALTERNATIVES 2
4. LEVEE AND FOUNDATION CONDITIONS 3
5. ANALYSIS AND RESULTS 4
6. CONCLUSIONS AND RECOMMENDATIONS 4
7. REFERENCES 6

LIST OF TABLES

Table 1 Flood Control Features Upstream of the Federal Levee System
Table 2 Foundation Conditions from Soil Survey Report

LIST OF FIGURES

Figure 1 Slope Stability Analysis of RD 1000 Levee
Figure 2 Remedial Repair for RD 1000 Levee
Figure 3 Typical New Levee Section
Figure 4 Typical Levee Raising Section

TABLE OF CONTENTS

GEOTECHNICAL REPORTS

Additional Documents

Levees Downstream of Sacramento Bypass Hydraulic Mitigation Designs

1.0 Introduction 1
2.0 Hydraulic Mitigation Area Fixes 1

a. Index Area 1R 1
b. Index Area 3 2
c. Index Area 1L 4

Folsom Dam Embankment Raise Analysis

1.0 Introduction 1
2.0 Existing Data 1
2.1 Embankment Geometry 1
2.2 Engineering Parameters 2

3.0 Embankment and Dike Designs 6
3.1 Right Wing Dam 6
3.2 Left Wing Dam 8
3.3 Mormon Island Auxiliary Dam 8
3.4 Dikes 9

4.0 Conclusions 9

Folsom Dam Borrow Site Analysis

1.0 Introduction 1

2.0 Potential Borrow Site 1
a. Aerojet 1
b. Within Reservoir 1
c. Auburn Cofferdam Runoff 2
d. Peninsula 2
e. Mississippi Bar 2
f. Old Borrow Site #4 2

3.0 Borrow Site Investigations 2

4.0 Results of Field Investigations 3
a. Mississippi Bar 3
b. Peninsula 4

5.0 Results of Laboratory Testing 4

6.0 Site Stratigraphy and Geotechnical Properties 4

7.0 Other Sites Investigated by SAFCA 4

8.0 Conclusions 5