

Knights Landing U2 - Yolo Bypass - Service Area 6 Levee System Unacceptable - Inactive	Knights Landing Ridge Cut - Unit 2, Left Bank (KNT2)	Service Area 6 - Yolo County - Sacramento River Right Bank Above Fremont Weir (S6YC)	Yolo Bypass - West Levee - Unit 1 (YBW1)
General Items			
Operations and Maintenance Manuals	M	M	M
Emergency Supplies and Equipment	A	A	A
Flood Preparedness and Training	A	A	A
Levee Embankment Items			
Unwanted Vegetation Growth	U	U	U
Sod Cover	A	U	A
Encroachments	U	U	U
Closure Structures	U	N/A	N/A
Slope Stability	U	U	M
Erosion/Bank Caving	U	U	U
Settlement	U	A	A
Depressions/Rutting	M	U	A
Cracking	U	U	U
Animal Control	U	U	U
Culverts/Discharge Pipes	N/A	N/A	N/A
Riprap Revetments & Bank Protection	N/A	M	M
Revetments other than Riprap	N/A	N/A	N/A
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	N/A
Seepage	A	A	M
Segment & System Ratings/PL 84-99 Eligibility			
Likely Prevents Performance In Next Flood Event			
Serious deficiency noted in past inspections has not been corrected within the established timeframe			
Not Likely to Prevent Performance In Next Flood Event			
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility			

Legend	
A	Acceptable
M	Minimally Acceptable
U	Unacceptable
N/A	Not Applicable

April 30, 2012