

Knights Landing – Service Area 6 - Yolo Bypass U1 Levee System Unacceptable - Inactive	Knights Landing Ridge Cut Unit 2	West Levee Yolo Bypass Unit 1	Service Area 6
	Operations and Maintenance Manuals	A	A
Emergency Supplies and Equipment	A	A	M
Flood Preparedness and Training	A	A	M
Unwanted Vegetation Growth	U	U	U
Sod Cover	N/A	N/A	N/A
Encroachments	U	U	U
Closure Structures	N/A	N/A	N/A
Slope Stability	A	A	M
Erosion/Bank Caving	U	U	M
Settlement	M	A	M
Depressions/Rutting	M	A	A
Cracking	A	A	A
Animal Control	M	M	M
Culverts/Discharge Pipes	N/A	N/A	N/A
Riprap Revetments & Bank Protection	N/A	N/A	N/A
Revetments other than Riprap	N/A	N/A	N/A
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	N/A
Seepage	A	A	A
Overall Segment Ratings	U	U	M

Item Rating Classification	Time to Fix Before Becoming Inactive
Not likely to prevent the system from performing as intended during the next flood event.	2 years from date of this letter unless otherwise specified.
Serious deficiency noted in a past inspection has not been corrected within the established timelines.	Pink issues have already exceeded their established timeline, causing the system to become inactive immediately.
Likely to prevent the system from performing as intended during the next flood event.	Red issues cause the system to become inactive immediately.

The worst rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility.