

# Report Card

RD 0001 and RD 2089 - Union Island	RD 2089 - Stark - Unit 1, Old River (STK1)	RD 2089 - Stark - Unit 2, Salmon Slough (STK2)	RD 0001 - Union Island (UISL)
	Unacceptable / Inactive		
Operations and Maintenance Manuals	A	A	A
Emergency Supplies and Equipment	A	A	A
Flood preparedness and Training	A	A	A
Unwanted Vegetation Growth	U	U	U
Sod Cover	NA	NA	NA
Encroachments	U	U	U
Closure structures	NA	NA	NA
Slope Stability	A	A	A
Erosion/Bank Caving	A	U	A
Settlement	U	M	A
Depressions/Rutting	M	U	A
Cracking	A	A	A
Animal Control	U	U	U
Culverts/Discharge Pipes	NA	NA	NA
Riprap Revetments & Bank Protection	NA	NA	NA
Revetments other than Riprap	NA	NA	NA
Underseepage Relief Wells/Toe Drainage Systems	NA	NA	NA
Seepage	A	A	A
Overall Segment Ratings	U	U	U

Item Rating Classification	Time to Fix before Becoming Inactive
Likely to prevent the system from performing as intended during the next flood event.	Red issues cause the system to become inactive immediately
Serious deficiency noted in a past inspection has not been corrected within the established timelines.	Pink issues have already exceeded previous timeline for repair, causing the system to become inactive immediately.
Not likely to prevent the system from performing as intended during the next flood event.	2 Years from Date of This letter unless otherwise specified.

The lowest rating is used to determine the overall segment system ratings and PL 84-99 Eligibility