

American River FCD - Dry Creek Right Bank, Unit 8 Minimally Acceptable-Active	Dry Creek Right Bank, Unit 8									
Operations and Maintenance Manuals	M									
Emergency Supplies and Equipment	A									
Flood Preparedness and Training	A									
Unwanted Vegetation Growth	A									
Sod Cover	A									
Encroachments	U									
Closure Structures	A									
Slope Stability	A									
Erosion/Bank Caving	A									
Settlement	A									
Depressions/Rutting	M									
Cracking	A									
Animal Control	M									
Culverts/Discharge Pipes	N/A									
Riprap Revetments & Bank Protection	A									
Revetments other than Riprap	A									
Underseepage Relief Wells/Toe Drainage Systems	A									
Seepage	A									
Segment & System Ratings/PL 84-99 Eligibility										
Likely Prevents Performance In Next Flood Event										
Serious deficiency noted in past inspections has not been corrected within the established timeframe										
Likely Prevents Performance In Next Flood Event (Framework)										
Not Likely to Prevent Performance In Next Flood Event										
Not Likely to Prevent Performance In Next Flood Event (Framework)										
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility										
							Legend			
							A	Acceptable		
							M	Minimally Acceptable		
							U	Unacceptable		
							N/A	Not Applicable		
							July 6, 2010			