

System Redmond Channel Project Minimally Acceptable - Active		Redmond Channel - Sevier County, UT (REDM)							
General	Operations and Maintenance Manuals	A							
	Emergency Supplies and Equipment	A							
	Flood Preparedness and Training	A							
Levee Embankments	Unwanted Vegetation Growth	U							
	Sod Cover	NA							
	Encroachments	U							
	Closure Structures	NA							
	Slope Stability	A							
	Erosion/Bank Caving	A							
	Settlement	A							
	Depressions/Rutting	M							
	Cracking	A							
	Animal Control	A							
	Culverts/Discharge Pipes	NA							
	Riprap Revetments & Bank Protection	NA							
	Revetments other than Riprap	NA							
	Underseepage Relief Wells/Toe Drainage Systems	NA							
Seepage	M								
Flood Damage Reduction Channels	Vegetation and Obstructions	M							
	Shoaling	A							
	Encroachments	M							
	Erosion	A							
	Concrete Surfaces	U							
	Tilting, Sliding, or Settlement of Concrete	NA							
	Foundation of Concrete Structures	NA							
	Slab and Monolith Joints	NA							
	Flap Gates/Flap Valves/Pinch Valves	U							
	Riprap Revetments & Banks	NA							
Revetments other than Riprap	NA								
<p><b>Likely Prevents Performance In Next Flood Event/Inactive</b></p> <p><b>Serious deficiency noted in past inspections has not been corrected within the established timeframe</b></p> <p><b>Not Likely to Prevent Performance In Next Flood Event/Active</b></p> <p>The lowest rating is used to determine the overall segment &amp; system ratings and PL 84-99 Eligibility</p>								<p><u>Legend</u></p> <p>A Acceptable</p> <p>M Minimally Acceptable</p> <p>U Unacceptable</p> <p>N/A Not Applicable</p>	