

APPENDIX C

MANIFESTS

AND WASTE ACCEPTANCE FORMS

Class II Manifests

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00058	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard/Hoff		6. US EPA ID Number Jim Damann CAD 9823523433		B. Transporter 1 Phone 925 6346850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a 1x End Dump, Bulk, Profile# 55034300 55098900 Hamilton Airfield, Class 2 soils T# 103			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month 10 Day 15 Year 02
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>Jim Damann</i>		Date Month 10 Day 15 Year 02
Printed/Typed Name Jim DAMANN			Signature		Date
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date
Printed/Typed Name			Signature		Date
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308	Manifest Document No. 00057	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949			Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		
5. Transporter 1 Company Name Dillard	6. US EPA ID Number CA 982 523433	A. State Transporter's ID		
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone 925 6346850		
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		C. State Transporter's ID		
10. US EPA ID Number CA D 981392732		D. Transporter 2 Phone		
11. WASTE DESCRIPTION		E. State Facility's ID		
a. Non-hazardous waste solid (soil with non-regulated contaminants)		F. Facility's Phone 925-449-6349		
12. Containers		13. Total Quantity	14. Unit Wt./Vol.	
No. Type				
001 DT		00018	Y	
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above		
11a. 1xEnd Dump, Bulk, Profile# 55034300 55098900 Hamilton Airfield, Class 2 soils T# 491				
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date Month Day Year 10 15 02
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name Richard K. Knight		Signature <i>Richard K. Knight</i>		Date Month Day Year 10 15 02
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature		Month Day Year
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA 000556308		Manifest Document No. 00056	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard/KUS		6. US EPA ID Number CA0982523433		B. Transporter 1 Phone 9256346850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CA D981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
			No.	Type	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			001	DT	00018 Y
b.					
c.					
d.					
3. Additional Descriptions for Materials Listed Above 11a. 1x End Dump, Bulk, Profile # 55034300 55098700 Hamilton Airfield, Class 2 soils TH T262			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month Day Year 10 15 02
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>Timothy Madden</i>		Date Month Day Year 10 15 02
Printed/Typed Name Timothy Madden			Signature		Date
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date
Printed/Typed Name			Signature		Date
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00055	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard/KVS		6. US EPA ID Number CAD 982523433		B. Transporter 1 Phone 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
11. WASTE DESCRIPTION				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
a. Non-hazardous waste solid (soil with non-regulated contaminants)			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
			No. 001	Type DT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 55098900 Hamilton Airfield, Class 2 soils T# T360				H. Handling Codes for Wastes Listed Above	
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month Day Year 10 15 02	
Printed/Typed Name GARY HOWARD				Signature <i>Gary Howard</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month Day Year 10 15 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date Month Day Year	
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date Month Day Year	
Printed/Typed Name				Signature	

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00054		2. Page 1 of 1	
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR			
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID			
5. Transporter 1 Company Name Cummings/RJM		6. US EPA ID Number ICAD981435621		B. Transporter 1 Phone 86613871842			
7. Transporter 2 Company Name RJM		8. US EPA ID Number		C. State Transporter's ID			
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number ICAD981392732		D. Transporter 2 Phone		E. State Facility's ID	
				F. Facility's Phone 925-449-6349			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No. Type		Unit Wt./Vol.	
a. Non-hazardous waste solid (soil with non-regulated contaminants)				001 DT		00018	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils CA 193206				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name RENEE ROSSA		Signature <i>R. Rossa</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FA

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00053	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CAD 981435621		B. Transporter 1 Phone 661 337 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils <i>T# 7H</i>			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month Day Year
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>Gino Lomonaco</i>		Date 10 15 02
Printed/Typed Name GINO LOMONACO			Signature		Month Day Year
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date 10 16 02
Printed/Typed Name			Signature		Month Day Year
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00052		2. Page 1 of 1	
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR			
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID		B. Transporter 1 Phone 661 387 1842	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CA D981435621		C. State Transporter's ID		D. Transporter 2 Phone	
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Facility's ID		F. Facility's Phone	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				10. US EPA ID Number CA D981392732		925-449-6349	
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)				No.	Type	00018	Y
				001	DT		
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils <i>T# 23</i>				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name JORGE CEJA		Signature <i>Jorge Ceja</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
19. Discrepancy Indication Space				Printed/Typed Name		Signature	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name		Signature	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00051	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CAD 981 435621		B. Transporter 1 Phone 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD 981 392732		D. Transporter 2 Phone	
11. WASTE DESCRIPTION				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
a. Non-hazardous waste solid (soil with non-regulated contaminants)			12. Containers		13. Total Quantity
			No.	Type	14. Unit WL/Vol.
			001	DT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils <i>TH 40</i>				H. Handling Codes for Wastes Listed Above	
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date Month Day Year 10 19 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name DAVE EVANKOVICH		Signature <i>[Signature]</i>		Date Month Day Year 10 19 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00050	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name D. Ward / Sturgeon		6. US EPA ID Number CA0982523433		B. Transporter 1 Phone 9256346850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit
			No.	Type	WT./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			001	DT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
11a. 1x End Dump. Bulk, Profile# 55034300 55078900					
Hamilton Airfield, Class 2 soils T# 223					
15. Special Handling Instructions and Additional Information					
<p>Caution: Wear appropriate protective clothing and respiratory protection when handling.</p> <p>All Volumes are Estimated Cummins Vacuum Service</p> <p>Site pick up address: Hamilton Airfield Novato CA</p>					
<p>16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.</p>					
Printed/Typed Name			Signature		Date
EDWARD KELLER			<i>Edward Keller</i>		Month Day Year 10 15 02
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature		Date
Printed/Typed Name			Signature		Month Day Year
Steve Tison			<i>Steve Tison</i>		10 15 02
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date
Printed/Typed Name			Signature		Month Day Year
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date
					Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type. (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00049	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard/Sturgeon & Sons		6. US EPA ID Number CAD 982523433		B. Transporter 1 Phone 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD 981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
11a. 1x End Dump, Bulk, Profile # 55034300 55098900					
Hamilton Airfield Class 2 soils TH 255					
15. Special Handling Instructions and Additional Information					
<p>Caution: Wear appropriate protective clothing and respiratory protection when handling.</p> <p>All Volumes are Estimated Cummings Vacuum Service</p> <p>Site pick up address: Hamilton Airfield Novato CA</p>					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month Day Year 10 15 02
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name JOHN TISON			Signature <i>John Tison</i>		Date Month Day Year 10 15 02
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name			Signature		Date Month Day Year
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00048		2. Page 1 of 1	
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR			
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID		B. Transporter 1 Phone 925 634 6850	
5. Transporter 1 Company Name Dillard / Sturgeon & Sons		6. US EPA ID Number CA D 982 523 433		C. State Transporter's ID		D. Transporter 2 Phone	
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Facility's ID		F. Facility's Phone 925-449-6349	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				10. US EPA ID Number CA D 981 392 732			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)				No.	Type	00018	Y
				001	DT		
b.							
c.							
d.							
3. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
11a. 1xEnd Dump. Bulk. Profile# 55034300 55098900							
Hamilton Airfield, Class 2 soils T# 224							
15. Special Handling Instructions and Additional Information							
<p>Caution: Wear appropriate protective clothing and respiratory protection when handling.</p> <p>All Volumes are Estimated Cummings Vacuum Service</p> <p>Site pick up address: Hamilton Airfield Novato CA</p>							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Ed Keller</i>		Date Month Day Year 10 15 02	
Printed/Typed Name Ed Keller				Signature		Date Month Day Year	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date Month Day Year	
Printed/Typed Name				Signature		Date Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00047	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard / Sturgeon & Son		6. US EPA ID Number CA0982523433		B. Transporter 1 Phone 925 634 6350	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 55098906 Hamilton Airfield, Class 2 soils T# 280			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month 10 Day 15 Year 02
17. Transporter 1 Acknowledgement of Receipt of Materials			Printed/Typed Name CHAMBERS		Date Month 10 Day 15 Year 02
			Signature <i>Chambers</i>		
18. Transporter 2 Acknowledgement of Receipt of Materials			Printed/Typed Name		Date
			Signature		
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00046		2. Page 1 of 1	
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR			
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID			
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number 435621 <i>ICAD981575473</i>		B. Transporter 1 Phone 9661-387-1842			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID			
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone 925-449-6349			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
				No.	Type		
a. Non-hazardous waste solid (soil with non-regulated contaminants)				001	DT	00018	Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 - Hamilton Airfield, Class 2 soils J# 37				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA.							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date 10/15/02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name GARY FLOWERS		Signature <i>Gary Flowers</i>	
						Date 10/15/02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
						Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name		Signature	
						Date	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00045	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CAD981435621		B. Transporter 1 Phone 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk. Profile# 55034300 Hamilton Airfield. Class 2 soils T # 2			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA Cummings Vacuum Service					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month Day Year 10 15 07
17. Transporter 1 Acknowledgement of Receipt of Materials			Printed/Typed Name SCOTT BALLARD		Date Month Day Year 10 15 07
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature <i>Scott Ballard</i>		Date Month Day Year
19. Discrepancy Indication Space			Printed/Typed Name		Date Month Day Year
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308	Manifest Document No. 00044	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949			Non-Haz Man# NR	
4. Generator's Phone (415 883-6386) Attn: Ed Keller		6. CAD US EPA ID Number 1981523433	A. State Transporter's ID	
5. Transporter 1 Company Name Dillard / K US		8. US EPA ID Number	B. Transporter 1 Phone 925 634 6850	
7. Transporter 2 Company Name			C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732	D. Transporter 2 Phone	
			E. State Facility's ID	
			F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)		No. Type		
		001 DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk. Profile# 55034300 55098900 Hamilton Airfield Class 2 soils TH + 265		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name GEORGE W. BURRELL		Signature <i>George W. Burrell</i>	Date Month Day Year 10 15 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00043	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name D. Ward / KVS		6. US EPA ID Number CAD981523433		B. Transporter 1 Phone 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
			No.	Type	
a. Non-hazardous waste solid (soil with non-regulated contaminants)			001	DT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
11a. 1xEnd Dump, Bulk, Profile# 55034300 59098900 Hamilton Airfield, Class 2 soils T# T284					
15. Special Handling Instructions and Additional Information					
<p>Caution: Wear appropriate protective clothing and respiratory protection when handling.</p> <p>All Volumes are Estimated Cummings Vacuum Service</p> <p>Site pick up address: Hamilton Airfield Novato CA</p>					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10 15 02	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name THOMAS JOHNSON				Month Day Year 10 15 02	
Signature <i>Thomas Johnson</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Month Day Year	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature					

GENERATOR

TRANSPORTER

FACILITY

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00042	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name D. Hard/KVS		6. US EPA ID Number CAD 981523433		B. Transporter 1 Phone 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
11. WASTE DESCRIPTION				E. State Facility's ID	
a. Non-hazardous waste solid (soil with non-regulated contaminants)				F. Facility's Phone 925-449-6349	
		12. Containers	13. Total Quantity	14. Unit Wt./Vol.	
		No.	Type		
		001	DT	00018	
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above	
11a. 1x End Dump, Bulk, Profile # 55054300 5018900					
Hamilton Airfield Class 2 soils T# + 286					
15. Special Handling Instructions and Additional Information					
<p>Caution: Wear appropriate protective clothing and respiratory protection when handling.</p> <p>All Volumes are Estimated Cummings Vacuum Service</p> <p>Site pick up address: Hamilton Airfield Novato CA</p>					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10 15 02	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name LARRY BROWN				Date Month Day Year 10 15 02	
Signature <i>Larry Brown</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Date Month Day Year	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature					

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000656308		Manifest Document No. 00041		2. Page 1 of 1	
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR			
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID		B. Transporter 1 Phone 725 638 6850	
5. Transporter 1 Company Name Dillard/KUS		6. US EPA ID Number CA0981523433		C. State Transporter's ID		D. Transporter 2 Phone	
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Facility's ID		F. Facility's Phone 925-449-6349	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				10. US EPA ID Number CA0981392732			
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity	14. Unit Wt./Vol.	
a. Non-hazardous waste solid (soil with non regulated contaminants)			001 DT		00018	Y	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11a. 1x End Dump, Bulk. Profile# 55034300 55098900 Hamilton Airfield Class 2 soils T#T247				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>[Signature]</i>		Date Month Day Year 10 15 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
19. Discrepancy Indication Space				Signature		Date	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00040	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard / KUS		6. US EPA ID Number CAD 481533433		B. Transporter 1 Phone 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
11a. 1xEnd Dump, Bulk, Profile# 55034300 55098900					
Hamilton Airfield, Class 2 soils T# T264					
15. Special Handling Instructions and Additional Information					
<p>Caution: Wear appropriate protective clothing and respiratory protection when handling.</p> <p>All Volumes are Estimated Cummings Vacuum Service</p> <p>Site pick up address: Hamilton Airfield Novato CA</p>					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month 10 Day 15 Year 02
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>Jerry Bryant</i>		Date Month 10 Day 15 Year 02
Printed/Typed Name JERRY BRYANT			Signature		Date
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date
Printed/Typed Name			Signature		Date
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR
 TRANSPORTER
 FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00039		2. Page 1 of 1					
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR							
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID							
5. Transporter 1 Company Name Dillard / KVS		6. US EPA ID Number CAD 981392732		B. Transporter 1 Phone 925 634 6850							
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID							
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD 981392732		D. Transporter 2 Phone		E. State Facility's ID					
				F. Facility's Phone 925-449-6349							
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity					
				No.		Type		Unit			
								Wt./Vol.			
				a. Non-hazardous waste solid (soil with non-regulated contaminants)		001 DT		00018		Y	
				b.							
c.											
d.											
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 55098900 Hamilton Airfield, Class 2 soils T# T361				H. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA											
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.											
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date 10 15 02					
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name H.L. COPE		Signature <i>[Signature]</i>					
						Date 10 15 02					
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature					
						Date					
19. Discrepancy Indication Space											
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name		Signature					
						Date					

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00038	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6886)		Attn: Ed Keller		A. State Transporter's ID 925 634 6850	
5. Transporter 1 Company Name Dillard / KVS		6. US EPA ID Number CAD982523433		B. Transporter 1 Phone	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				10. US EPA ID Number CAD981392732	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
3. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk. Profile# 55034300 55098900 Hamilton Airfield, Class 2 soils T# T283			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month 10 Day 15 Year 02
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>Randy Meth</i>		Date Month 10 Day 14 Year 02
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date
19. Discrepancy Indication Space			Signature		Date
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA 000556308		Manifest Document No. 00037	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name <i>Cummings S</i>		6. US EPA ID Number CA 981435627		B. Transporter 1 Phone 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CA D981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils <i>T# 76</i>			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month Day Year 10 15 02
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>Clifford Feetwell</i>		Date Month Day Year 10 15 02
Printed/Typed Name CLIFFORD FEETWELL			Signature		Date
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date
Printed/Typed Name			Signature		Date
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FA

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00036	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Williamard / KUS		6. US EPA ID Number CA0982523433		B. Transporter 1 Phone 9256746850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CA0981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk, Profile# 55034300 55098900 Hamilton Airfield, Class 2 soils T# T324			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date 10/19/07	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name Mike Mead				Signature <i>Mike Mead</i>	
				Date 10/19/07	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Signature	
				Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

LIQTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00035	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard / KVS		6. US EPA ID Number CAD982523433		B. Transporter 1 Phone 925 6346840	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
			No.	Type	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			001	DT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils T II T 243				H. Handling Codes for Wastes Listed Above	
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date Month Day Year 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name George Shepherd				Signature <i>George Shepherd</i>	
				Date Month Day Year 10 15 02	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Signature	
				Date Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00034	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CA0981435621		B. Transporter 1 Phone 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CA0981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils <i>T# 72</i>			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month Day Year 10/19/02
17. Transporter 1 Acknowledgement of Receipt of Materials			Printed/Typed Name <i>Mike Boss Sr</i>		Date Month Day Year 10/19/02
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature <i>[Signature]</i>		Date Month Day Year
19. Discrepancy Indication Space			Printed/Typed Name		Date Month Day Year
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00033	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Cummins		6. US EPA ID Number CAD 981435621		B. Transporter 1 Phone 6613871842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
11. WASTE DESCRIPTION				E. State Facility's ID	
a. Non-hazardous waste solid (soil with non-regulated contaminants)				F. Facility's Phone 925-449-6349	
				12. Containers	
				No.	Type
				001	DT
				13. Total Quantity 00018	
				14. Unit Wt./Vol. Y	
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils #44				H. Handling Codes for Wastes Listed Above	
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month Day Year 10 15 02	
Printed/Typed Name MARK D. KIRK				Signature <i>Mark D. Kirk</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month Day Year 10 15 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date Month Day Year	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FA

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00031	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Cummings		6. US EPA ID Number ICAD 981435621		B. Transporter 1 Phone 661 387 1342	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number ICAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils + # 77			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month 10 Day 15 Year 02
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>Robert Lawrence</i>		Date Month 10 Day 15 Year 02
Printed/Typed Name ROBERT LAWRENCE			Signature <i>Robert Lawrence</i>		Date
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date
Printed/Typed Name			Signature		Date
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00029	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard		6. US EPA ID Number CAD 987523433		B. Transporter 1 Phone 925 639 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
11a. 1xEnd Dump. Bulk, Profile# 55034300			H. Handling Codes for Wastes Listed Above		
Hamilton Airfield. Class 2 soils T# 091					
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10/15/02	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name RANDOLPH V. GICO				Date Month Day Year 10/15/02	
Signature <i>Randolph V. Gico</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Date Month Day Year	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature					

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00028	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID 925-6346850	
5. Transporter 1 Company Name Cummings Dillard		6. US EPA ID Number CA098143662		B. Transporter 1 Phone 661-387-1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				10. US EPA ID Number CAD981392732	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile # 55034300 55098900 Hamilton Airfield, Class 2 soils T# 191			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date 10/15/02	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name Steve M. Turner				Signature <i>Steve M. Turner</i>	
				Date 10/15/02	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Signature	
				Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308	Manifest Document No. 00027	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949			Non-Haz Man# NR	
4. Generator's Phone (415 883-6386) Attn: Ed Keller		6. US EPA ID Number CA066138712	A. State Transporter's ID	
5. Transporter 1 Company Name Cummings / RJM		8. US EPA ID Number	B. Transporter 1 Phone 661-3871342	
7. Transporter 2 Company Name			C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732	D. Transporter 2 Phone	
			E. State Facility's ID	
			F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)		No. Type		
		001 DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils XXXX CA 19320		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name ROSA		Signature <i>R. Rosa</i>	Date Month Day Year 10 16 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

CITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00026	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name <i>Cummings / LJB</i>		6. US EPA ID Number CAD 981435621		B. Transporter 1 Phone 661 377 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils T# 1937			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month Day Year 10 15 02	
Printed/Typed Name Larry Bohringer		Signature <i>Larry Bohringer</i>		Date Month Day Year 10 19 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

LIABILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00025		2. Page 1 of 1					
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man#							
4. Generator's Phone (415 883-6386) Attn: Ed Keller				NR							
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CAD981435621		A. State Transporter's ID							
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 6613871842							
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		C. State Transporter's ID							
				D. Transporter 2 Phone							
				E. State Facility's ID							
				F. Facility's Phone 925-449-6349							
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity		14. Unit Wt./Vol.			
				No.		Type					
				001		DT		00018		Y	
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk. Profile# 55034300 Hamilton Airfield, Class 2 soils <i>T# 34</i>				H. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA											
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.											
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 15 02					
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Gino Lomongo		Signature <i>Gino Lomongo</i>		Date Month Day Year 10 15 02			
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature		Date Month Day Year			
19. Discrepancy Indication Space											
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.											
Printed/Typed Name				Signature		Date Month Day Year					

GENERATOR

TRANSPORTER

FA

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00024	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number ICAD 981435621		B. Transporter 1 Phone 661 3571342	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number ICAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					
c.					
d.					
3. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk. Profile# 55034300 Hamilton Airfield Class 2 soils <i>T # 2</i>			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month 10 Day 15 Year 07
17. Transporter 1 Acknowledgement of Receipt of Materials			Printed/Typed Name SCOTT BALLARD		Date Month 10 Day 15 Year 07
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature <i>Scott Ballard</i>		Date
19. Discrepancy Indication Space			Printed/Typed Name		Date
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.			Signature		Date

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00023	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller			
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CA0981435621		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 861 387 1845	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield. Class 2 soils T# 40			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10 15 02	
Printed/Typed Name DAYEVANKOVICH				Signature <i>Dayevan Kovich</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10 15 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date	
Printed/Typed Name				Signature	

GENERATOR

TRANSPORTER

FA

LI

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00021	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CA0981435621		B. Transporter 1 Phone 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CA0981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils <i>#37</i>			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date 10 15 92	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name Gary Flowers				Signature <i>Gary Flowers</i>	
				Date	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Signature	
				Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA 000556308		Manifest Document No. 00020		2. Page 1 of 1	
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR			
4. Generator's Phone (415 883-6386) Attn: Ed Keller				A. State Transporter's ID			
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CAD 981435621		B. Transporter 1 Phone 661 387 1342			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				10. US EPA ID Number CAD 981392732		E. State Facility's ID	
				F. Facility's Phone 925-449-6349			
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity	14. Unit Wt./Vol.	
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No.	Type	00018	Y	
			001	DT			
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils <i>JA 76</i>				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 15 62	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Clifford Fretwell</i>		Date Month Day Year 10 15 02	
Printed/Typed Name CLIFFORD FRETWELL				Signature		Date	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature		Date	
Printed/Typed Name				Signature		Date	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00019	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CAD 981392732		B. Transporter 1 Phone 661 387 1342	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils T# 72			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name Mike Bosse Sr		Signature <i>Mike Bosse Sr</i>		Date 10 15 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00018	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man#	
4. Generator's Phone (415 883-6386) Attn: Ed Keller				NR	
5. Transporter 1 Company Name <i>Cummins Buss</i>		6. US EPA ID Number CAD 981435621		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 661 387 1847	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD 981392732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils <i>TA 44</i>			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10 15 02	
Printed/Typed Name <i>Mark D. Kirk</i>				Signature <i>Mark D. Kirk</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10 15 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date	
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date	
Printed/Typed Name				Signature	

GENERATOR

TRANSPORTER

F

LI

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00017	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CAD 981435621		B. Transporter 1 Phone 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils T# 45			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10 15 02	
Printed/Typed Name Dale Jamison				Signature <i>Dale Jamison</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10 15 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date	
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date	
Printed/Typed Name				Signature	
				Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00016		2. Page 1 of 1					
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR							
4. Generator's Phone (415 883-6386) Attn: Ed Keller											
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CA0981435621		A. State Transporter's ID							
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 661 387 1842		C. State Transporter's ID					
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				10. US EPA ID Number CAD981392732		E. State Facility's ID					
				F. Facility's Phone 925-449-6349							
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity					
				No.		Type		Unit			
								Wt./Vol.			
				001		DT		00018		Y	
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA T # 7:7				H. Handling Codes for Wastes Listed Above							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.											
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 15 02					
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Roger D Lawrence</i>		Date Month Day Year 10 15 02					
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date					
Printed/Typed Name				Signature		Month Day Year					
19. Discrepancy Indication Space											
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.											
Printed/Typed Name				Signature		Date Month Day Year					

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308	Manifest Document No. 00015	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949			Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		
5. Transporter 1 Company Name Cummings	6. US EPA ID Number CA098143621	A. State Transporter's ID		
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone 925 387 1842		
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		C. State Transporter's ID		
10. US EPA ID Number CA0981392732		D. Transporter 2 Phone		
11. WASTE DESCRIPTION		E. State Facility's ID		
a. Non-hazardous waste solid (soil with non-regulated contaminants)		F. Facility's Phone 925-449-6349		
		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
		No. Type		
		001 DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk. Profile# 55034300 Hamilton Airfield. Class 2 soils T# 34		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name Gino Lomonaco		Signature <i>Gino Lomonaco</i>	Date Month Day Year 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

FA

CITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAD000556308		Manifest Document No. 00014	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man#	
4. Generator's Phone (415 883-6386) Attn: Ed Keller				NR	
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CAD981435621		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 661 387 1842	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				C. State Transporter's ID	
10. US EPA ID Number CAD981392732				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit
			No.	Type	WT./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			001	DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils <i>JH 23</i>			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name JORGECETA		Signature <i>Jorgeceta</i>		Date Month Day Year 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00013	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CA 981435621		B. Transporter 1 Phone 667-387-1892	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
			No.	Type	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			001	DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 Hamilton Airfield, Class 2 soils + # 40				H. Handling Codes for Wastes Listed Above	
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month Day Year 10 14 02	
Printed/Typed Name DAVE EVANKOVICH				Signature <i>Dave Evankovich</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month Day Year 10 14 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date Month Day Year	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAD00556308		Manifest Document No. 00012	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man#	
4. Generator's Phone (415 883-6386) Attn: Ed Keller				NR	
5. Transporter 1 Company Name Dillard/KVS		6. US EPA ID Number CAD 982573433		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 925 634 6850	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				E. State Facility's ID	
10. US EPA ID Number CAD981392732				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit
			No.	Type	WT./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			001	DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk. Profile# 55034300 55098900 Hamilton Airfield, Class 2 soils T# T263			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month Day Year 10 14 02
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>Randy Metton</i>		Date Month Day Year 10 14 02
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date Month Day Year
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00011		2. Page 1 of 1	
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man#			
4. Generator's Phone (415 883-6386) Attn: Ed Keller				NR			
5. Transporter 1 Company Name Dillard/KVS		6. US EPA ID Number CAD982523433		A. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 9256346850		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID			
				F. Facility's Phone 925-449-6349			
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity		14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. Type				
			001 DT		00018		Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 55098900 Hamilton Airfield, Class 2 soils T# T 284				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Thomas Johnson</i>		Date Month Day Year 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00010	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man#	
4. Generator's Phone (415 883-6386) Attn: Ed Keller				NR	
5. Transporter 1 Company Name Edward KVS		6. US EPA ID Number CAD 982523433		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 926 634 8850	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				C. State Transporter's ID	
10. US EPA ID Number CAD 981392732				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk. Profile #55034300 55098900 Hamilton Airfield. Class 2 soils T# T 243			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10 14 02	
Printed/Typed Name George Shepherd				Signature <i>George Shepherd</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10 14 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type: (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00009		2. Page 1 of 1					
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR							
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID		B. Transporter 1 Phone 925 634 6850					
5. Transporter 1 Company Name Dillard / KVS		6. US EPA ID Number CA0982523433		C. State Transporter's ID		D. Transporter 2 Phone					
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Facility's ID		F. Facility's Phone 925-449-6349					
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				10. US EPA ID Number CAD981392732							
11. WASTE DESCRIPTION a. Non-hazardous waste solid (soil with non-regulated contaminants)				12. Containers		13. Total Quantity					
				No.		Type		Unit Wt./Vol.			
				001		DT		00018		Y	
				b.							
				c.							
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 55098900 Hamilton Airfield, Class 2 soils T# T 286				H. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA											
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.											
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 14 02					
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name LARRY BROWN		Signature <i>Larry Brown</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature					
19. Discrepancy Indication Space											
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.											
Printed/Typed Name				Signature		Date Month Day Year					

GENERATOR

TRANSPORTER

FACILITY

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA 000556308		Manifest Document No. 00008	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard / KVS		6. US EPA ID Number CAD 982623433		B. Transporter 1 Phone 925 634 850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD 981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1x End Dump, Bulk, Profile # 55034300 55028900 T # T265 Hamilton Airfield, Class 2 soils			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month Day Year 10 14 02	
Printed/Typed Name GEORGE W. BURRELL				Signature <i>George W. Burrell</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month Day Year 10 14 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00007	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415, 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard/KVS		6. US EPA ID Number CAD 982523433		B. Transporter 1 Phone 9256346850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
			No.	Type	
a. Non-hazardous waste solid (soil with non-regulated contaminants)			001	DT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55034300 55098900 Hamilton Airfield, Class 2 soils T#9324			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name Mike Mead		Signature <i>Mike Mead</i>		Date Month Day Year 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

CITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA 000556308		Manifest Document No. 00006	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield i Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard / KVS		6. US EPA ID Number ICA D982523433		B. Transporter 1 Phone 925 6346850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
			No.	Type	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			001	DT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile #55034300 54098900 Hamilton Airfield, Class 2 soils T# T247			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10 14 02	
Printed/Typed Name A BOSTICK				Signature <i>A Bostick</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date	
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date	
Printed/Typed Name				Signature	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00005	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard/KUS		6. US EPA ID Number CAD982923433		B. Transporter 1 Phone 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
11a. 1xEnd Dump, Bulk, Profile#55034300 55098900 Hamilton Airfield, Class 2 soils T#7361					
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date Month 10 Day 14 Year 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name HL Cope		Signature <i>HL Cope</i>		Date Month 10 Day 14 Year 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Date Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

CITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00004	2. Page 1 of 1	
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR		
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID		
5. Transporter 1 Company Name Dillard / KVS		6. US EPA ID No. CAD 982495205		B. Transporter 1 Phone 925 634 6850		
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID		
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone		
				E. State Facility's ID		
				F. Facility's Phone 925-449-6349		
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.	
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018	
b.						
c.						
d.						
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk. Profile #55034300 55098900 Hamilton Airfield, Class 2 soils T # T264			H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA						
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.						
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	Date Month 10 Day 14 Year 02	
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name TERRY BREANT				Signature <i>Terry Breant</i>	Date Month 10 Day 14 Year 02	
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name				Signature	Date	
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.						
Printed/Typed Name				Signature	Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00003	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard		6. US EPA ID Number CAD98252343		B. Transporter 1 Phone 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. 001	Type DT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1x End Dump, Bulk, Profile #55034300 55098900 55098900 Hamilton Airfield, Class 2 soils T# 691			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Cummings Vacuum Service Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month Day Year 10/14/02	
Printed/Typed Name JAMES GAINER				Signature <i>James Gainer</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month Day Year 10/14/02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 00002		2. Page 1 of 1	
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR			
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID			
5. Transporter 1 Company Name Dillard		6. US EPA ID Number CAD 982523433		B. Transporter 1 Phone 925 634 6850			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID			
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone 925-449-6349			
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity		14. Unit Wt./Vol.
a. Non-hazardous waste solid (soil with non-regulated contaminants)			No. Type		Quantity		Unit
			001 DT		00018		Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile #55034300 55034300 55098900 Hamilton Airfield, Class 2 soils F# 891				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Jim Nunes</i>		Date 10 19 02	
Printed/Typed Name JIM NUNES				Signature		Date 10 16 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAD 00556308		Manifest Document No. 00001		2. Page 1 of 1					
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR							
4. Generator's Phone (415) 883-6386		Attn: Ed Keller		A. State Transporter's ID		B. Transporter 1 Phone 925-634-6850					
5. Transporter 1 Company Name Dillard		6. US EPA ID Number CAD 982523433		C. State Transporter's ID		D. Transporter 2 Phone					
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Facility's ID		F. Facility's Phone					
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				10. US EPA ID Number CAD 981392732		925-449-6349					
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity					
				No.		Type		Unit			
								Wt./Vol.			
				001		DT		00018		Y	
a. Non-hazardous waste solid (soil with non-regulated contaminants)											
b.											
c.											
d.											
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile #55034300 <i>54098900</i> <i>55098900</i> Hamilton Airfield, Class 2 soils T # 491				H. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA											
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.											
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month 10 Day 14 Year 02					
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Richard K. Chai...</i>		Date Month 10 Day 14 Year 02					
Printed/Typed Name RICHARD K. CHAIGH...				Signature		Date					
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date					
Printed/Typed Name				Signature		Date					
19. Discrepancy Indication Space											
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.											
Printed/Typed Name				Signature		Date Month Day Year					

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308	Manifest Document No. 1005Z	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOUNTAIN VIEW, CA		MAIL: ATTN: DAN BUSHNELL		
4. Generator's Phone ((310) 342-9858)				
5. Transporter 1 Company Name Dillard / Hoyt	6. US EPA ID Number CAD982523433	A. State Transporter's ID		
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone (925) 634-6850		
9. Designated Facility Name and Site Address ALTA MOUNT LANDFILL 10840 ALTA MOUNT PASS ROAD LIVERMORE, CA 94550		C. State Transporter's ID		
10. US EPA ID Number CAD981382732		D. Transporter 2 Phone		
		E. State Facility's ID		
		F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf: 55098900)		No. 001 Type DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId. TEL 190		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POF 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month 10 Day 14 Year 02	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name SCOTT NATOW		Signature <i>Scott Natow</i>	Date Month 10 Day 14 Year 02	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature	Date	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

FA

CITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10051	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA		MAIL: ATTN: DAN BUSHWELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CAD 981435621		A. State Transporter's ID 661-387-1842	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone	
				C. State Transporter's ID	
				D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf: 55098900)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 55034300 IIb. IIc. T# 44 IIId.			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date 10/14/02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature <i>Mark D Kirk</i>		Date 10/14/02	
Printed/Typed Name MARK D KIRK		Signature		Date	
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date	
Printed/Typed Name		Signature		Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date	
				Month Day Year	

GENERATOR

TRANSPORTER

FA

ITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 5 5 6 3 0 8		Manifest Document No. 10050		2. Page, 1 of 1					
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA				MAIL: ATTN: DAN BUSHNELL							
4. Generator's Phone ((310) 342-9858)											
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CAD981435621		A. State Transporter's ID 6613871842							
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID							
				D. Transporter 2 Phone							
9. Designated Facility Name and Site Address ALTA MOUNT LANDFILL 10840 ALTA MOUNT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		E. State Facility's ID							
				F. Facility's Phone (925) 449-6349							
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity		14. Unit Wt./Vol.			
				No.		Type					
				a. NON HAZ SOIL, (pf: 55098900)		001 DT		00018		Y	
				b.							
				c.							
d.											
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above							
iia. 55098900 55034300 iib. iic. iid. T# 76											
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 POW 09-33859											
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.											
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date 10 14 02					
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Clifford Fretwell</i>		Date 10 14 02					
Printed/Typed Name CLIFFORD FRETWELL				Signature		Date					
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date					
Printed/Typed Name				Signature		Date					
19. Discrepancy Indication Space											
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.											
Printed/Typed Name				Signature		Date					
						Month Day Year					

GENERATOR

TRANSPORTER

FA

ITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 0049	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB FOYATO, CA					
4. Generator's Phone ((310) 342-9858					
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CAD 981 435621		A. State Transporter's ID 64 38 71842	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (p# 55098900)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 58034300 IIb. IIc. T# 37 IId.			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JUG# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date Month 10 Day 14 Year 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name Gary Flowers		Signature <i>Gary Flowers</i>		Date Month 10 Day 14 Year 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 100415	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		MAIL: ATTN: DAN BUSHWELL			
4. Generator's Phone ((310) 342-9858					
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CAD 981435621		A. State Transporter's ID 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTA MONT LANDFILL 10840 ALTA MONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD 981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOX HAZ SOIL, (p# 55098900)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIc. 55098900 55034308 IIb. IIc. IIId. TH 2			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 503-018 POC# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name SCOTT BALLARD				Signature <i>Scott Ballard</i>	
				Date 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Signature	
				Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	
				Date	

GENERATOR

TRANSPORTER

FA

CITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10047	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHWELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name Knarrings		6. US EPA ID Number CA D 9 8 1 4 3 5 6 2 1		A. State Transporter's ID 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone	
9. Designated Facility Name and Site Address ALTAMINT LANDFILL 10840 ALTAMINT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf: 55098900)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 58034300 IIb. IIc. II d. TH 45			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10 / 14 / 02	
Printed/Typed Name Dale Jamison				Signature <i>Dale Jamison</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10 / 14 / 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date	
Printed/Typed Name				Signature	
				Date	

GENERATOR FACILITY TRANSPORTER

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 0		Manifest Document No. 10046	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA					
4. Generator's Phone ((310) 342-9858					
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CAD981435621		A. State Transporter's ID 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf: 55098900)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
11a. 55098900 88084300 11b. 11c. 11d. T# 77					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 POK# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10 14 02	
Printed/Typed Name Keller D Lawrence				Signature <i>Keller D Lawrence</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10 14 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FA

ITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308	Manifest Document No. 10045	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA		MAIL : ATTN: DAN BUSHNELL		
4. Generator's Phone ((310) 342-9858				
5. Transporter 1 Company Name Dillard / Staff 's	6. US EPA ID Number CAD982523433	A. State Transporter's ID 925 634 639		
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone		
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		C. State Transporter's ID		
		D. Transporter 2 Phone		
		E. State Facility's ID		
		F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf: 55098900)		No. Type		
		001 DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above		
11a. 55098900				
11b. T# 143				
11c.				
11d.				
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name George Paquette		Signature <i>George Paquette</i>	Date Month Day Year 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10044	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MURATO, CA		MAIL: ATTN: DAE BUSHNELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name Dillard / Sheriff's		6. US EPA ID Number ICAD992623433		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 674-6850	
9. Designated Facility Name and Site Address ALTMONT LANDFILL 10840 ALTMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number ICAD981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.	
a. NOV HAE SOIL, (pt: 55098900)		No. 001	Type DT	Quantity 00018	Unit Wt./Vol. Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. T# 133 11d.			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JO# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date 10/14/02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature <i>Robert Frank</i>		Date 10/14/02	
Printed/Typed Name Robert Frank		Signature		Date	
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date	
Printed/Typed Name		Signature		Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date	
				Month Day Year	

GENERATOR SIGNATURE

TRANSPORTER SIGNATURE

FACILITY SIGNATURE

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 15043	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		MAIL: ATTN: DAVE BUSHNELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name Dillard		6. US EPA ID Number CAD982423433		A. State Transporter's ID 026 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10640 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. HOW HAW SOIL, (pf: 55098900)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IIc. J# 391 IIc.			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POC 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month Day Year 10 14 02	
Printed/Typed Name Lance Englebright				Signature <i>Lance Englebright</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month Day Year 10 14 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

INITIAL HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FA

ITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10047	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		MAIL:			
4. Generator's Phone ((310) 342-9858)		ATTN: DAN BUSHWELL			
5. Transporter 1 Company Name Dillard		6. US EPA ID Number CA0982523433		A. State Transporter's ID 925 6346850	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (p# 55098900)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId. T# 144			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 POF# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month 10 Day 14 Year 02	
Printed/Typed Name HAROLD HOLMAN				Signature <i>Harold Holman</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month 10 Day 14 Year 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date Month 10 Day 14 Year 02	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date Month 10 Day 14 Year 02	
Printed/Typed Name				Signature	

GENERATOR'S CERTIFICATION

TRANSPORTER'S CERTIFICATION

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10041	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHWELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name Dillard	6. US EPA ID Number CAD982523433	A. State Transporter's ID 925 634 4348		B. Transporter 1 Phone	
7. Transporter 2 Company Name	8. US EPA ID Number	C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		E. State Facility's ID	
		F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION		12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf: 55098900)		No.	Type		
		001	DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId. TH 091		H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name		Signature		Date	
EDWARD KELLER		<i>Edward Keller</i>		10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature		Date	
Ronaldoph V. Zico		<i>Ronaldoph V. Zico</i>		10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date	

NON-HAZARDOUS WASTE MANIFEST

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 0 0 5 5 6 3 0 8		Manifest Document No. 10040		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA				MAIL: ATTN: DAE BUSHNELL			
4. Generator's Phone ((310) 342-9858)							
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CAD 981436621		A. State Transporter's ID (661) 387-1847			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
				No. Type			
a. NON HAZ SOIL, (pf: 55096900)				001 DT		00018	Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
IJa. 55096900 55084300 IIb. IIc. IIId. T# 23							
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Jorge CETA		Signature <i>Jorge Ceta</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR TITLE OCCUPATIONAL

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 0 0 5 5 6 3 0 8		Manifest Document No. 10039	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA		MAIL:			
4. Generator's Phone ((310) 342-9858		ATTN: DAN BUSHNELL			
5. Transporter 1 Company Name Cummings		6. US EPA ID Number KAD 981435 621		A. State Transporter's ID 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10640 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. ROW HAS SOIL, (pf: 55098900)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 55034300 IIb. IIc. IIId. T# 40			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925)634-6850 DILLARD JOB# 583-016 POW 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>[Signature]</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10 14 02	
Printed/Typed Name DAVE EVANKOVICH				Signature <i>[Signature]</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10 14 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

GENERATOR

TRANSPORTER

FACILITY



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10038	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA 4. Generator's Phone ((310) 342-9858				MAIL: ATTN: DAN BUSHWELL	
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS.		6. US EPA ID Number CA0982523433		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 634-6850	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
a. NON HAZ SOIL, (pf: 55098900)			No.	Type	14. Unit Wt./Vol.
			00	DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId. T# T243			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POC# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10 14 02	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name George Shepherd				Date Month Day Year 10 14 02	
Signature <i>George Shepherd</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Date	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature					

GENERATOR

TRANSPORTER

F

CITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10037	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		MAIL: ATTN: DAN RUSHMELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name P. Hard / KVS		6. US EPA ID Number CAD 9825 23437		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 639 6250	
9. Designated Facility Name and Site Address ALAMONT LANDFILL 10640 ALAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD 98 1382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf: 55098900)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d. T # T 284			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10/14/02	
Printed/Typed Name THOMAS JOHNSON				Signature <i>Thomas Johnson</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10/14/02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

NON-HAZARDOUS WASTE GENERATOR SIGNATURE

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10036	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHWELL			
4. Generator's Phone ((310) 342-9858		6. US EPA ID Number ICAD 98252777		A. State Transporter's ID 925 634 6850	
5. Transporter 1 Company Name Dillard/KUS		8. US EPA ID Number		B. Transporter 1 Phone () -	
7. Transporter 2 Company Name		10. US EPA ID Number ICAD 981382732		C. State Transporter's ID	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		F. Facility's Phone (925) 449-6349		D. Transporter 2 Phone	
11. WASTE DESCRIPTION		12. Containers		13. Total Quantity	
a. NON HAZ SOIL, (pf: 55098900)		No. Type		14. Unit Wt./Vol.	
		001 DT		00018 Y	
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above			
11a. 55098900					
11b.					
11c.					
11d. T# T263					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-016 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name Randy Metton		Signature <i>Randy Metton</i>		Date 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name		Signature		Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date	

GENERATOR

TRANSPORTER

CITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10035	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name Dillard / KVS		6. US EPA ID Number CAD 9826 23433		A. State Transporter's ID 926346850	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone ()	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD 981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
			No.	Type	Unit Wt./Vol.
a. NOV HAZ SOIL, (p# 55098900)			001	DI	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
11a. 55098900					
11b.					
11c.					
11d.					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name LARRY BROWN		Signature <i>Larry Brown</i>		Date Month Day Year 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Date Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10034	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAW BUSHWELL			
4. Generator's Phone ((310) 342-9858		6. US EPA ID Number 925 CAD987673433		A. State Transporter's ID 925 634 6850	
5. Transporter 1 Company Name Dillard / KVS		8. US EPA ID Number		B. Transporter 1 Phone	
7. Transporter 2 Company Name				C. State Transporter's ID	
9. Designated Facility Name and Site Address ALTAHMET LANDFILL 10840 ALTAHMET PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf: 55098900)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. T# 11d. T265			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date Month 10 Day 14 Year 07	
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name GEORGE W BURRELL		Signature <i>George W Burrell</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Date Month 10 Day 14 Year 02	
19. Discrepancy Indication Space		Signature		Date	
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date Month 10 Day 14 Year 02	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 5 5 6 3 0 8		Manifest Document No. 10033	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHWELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name Dillard / KVS		6. US EPA ID Number CAD 982523433		A. State Transporter's ID 956346850	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone ()	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD 981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAS SOIL, (pf: 55098900)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IIId. TH T324			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925)634-6850 DILLARD JOB# 583-018 POF# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date 10/14/02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name Mike Megard				Signature <i>Mike Megard</i>	
				Date 10/14/02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Signature	
				Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	
				Month Day Year	

GENERATOR'S CERTIFICATION

TRANSPORTER'S CERTIFICATION

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10032	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858		5. Transporter 1 Company Name Dillard / KVS		6. US EPA ID Number ICAD982523433	
7. Transporter 2 Company Name		8. US EPA ID Number		A. State Transporter's ID 926346850	
9. Designated Facility Name and Site Address ALTA MOUNT LANDFILL 10840 ALTA MOUNT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		B. Transporter 1 Phone	
				C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf: 55098900)			No. Type		
			001 DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
IIa. 55098900 IIb. IIc. IId. T# T247					
15. Special Handling Instructions and Additional Information Emergency Contact (925)634-6850 DILLARD JOBS# 583-018 POC# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10 14 09	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name A. BOSTON				Month Day Year 10 14 09	
Signature <i>A. Boston</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Month Day Year	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature					

GENERATOR'S CERTIFICATION

TRANSPORTER'S CERTIFICATION

FACILITY'S CERTIFICATION

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10031	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name Dillard / KVS		6. State Facility ID Number 925 634 6950		A. State Transporter's ID 925 634 6950	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone ()	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (p# 55098900)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d. T# T264			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOE# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10/14/02	
Printed/Typed Name JERRY ROYAL				Signature <i>Jerry Royal</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10/19/02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10036	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		MAIL: ATTN: DAN BUSHWELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter Company Name Dillard / KVS		6. US EPA ID Number CAD 982523433		A. State Transporter's ID 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTAJONET LANDFILL 10840 ALTAJONET PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION		12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. MUD HAS SOIL, (p# 55098900)		No. Type		001 018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above			
IIa. 55098900 IIb. IIc. IIa. TA T361					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name H.L. COOK		Signature <i>H.L. Cook</i>		Date Month Day Year 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Date Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10029	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA				MAIL: ATTN: DAN BUSHWELL	
4. Generator's Phone ((310) 342-9858)		6. US EPA ID Number CAD 98 1435621		A. State Transporter's ID 661 387484	
5. Transporter 1 Company Name Cummings		8. US EPA ID Number		B. Transporter 1 Phone () -	
7. Transporter 2 Company Name		10. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		11. WASTE DESCRIPTION		D. Transporter 2 Phone	
		12. Containers		E. State Facility's ID	
		No. Type		F. Facility's Phone	
		CAD 98 1382732		(925) 449-6349	
a. NOV HAE SOIL, (pf: 55098900)		001 DT		00018	
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above	
IIa. 55098900 50034300 IIb. IIc. IId T# 44					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BYLLARD JUG# 583-018 POW 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10/14/02	
Printed/Typed Name MARK D. KYK				Signature <i>Mark D. Kyk</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10/14/02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR
TRANSPORTER
FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10028	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858					
5. Transporter 1 Company Name Dillard	6. US EPA ID Number CAD982623433	A. State Transporter's ID 925 634 6850		B. Transporter 1 Phone () -	
7. Transporter 2 Company Name	8. US EPA ID Number	C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTA MONT LANDFILL 10840 ALTA MONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION		12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf: 55098900)		No.	Type		
		001	DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above			
i. 55098900 ii. iii. iv. T# 191					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOSE 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date Month Day Year 10/14/02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name Steve M. Turner		Signature <i>Steve M. Turner</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.		Printed/Typed Name		Signature	
				Date Month Day Year	

GENERATOR CERTIFICATION

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10027	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL:			
4. Generator's Phone ((310) 342-9858)		ATTN: DAN BUSHNELL			
5. Transporter 1 Company Name Dillard / Hoyt		6. US EPA ID Number CA 0982523433		A. State Transporter's ID 925 6346850	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTAJONET LANDFILL 10840 ALTAJONET PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf: 55098900)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d.			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 POC 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date 10/4/02	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name SCOTT NATOW				Signature <i>Scott Natow</i>	
				Date 10/4/02	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Signature	
				Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

FA

CITY



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10026	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA		MAIL: ATTN: DAN BUSHMILL			
4. Generator's Phone ((310) 342-9858)		5. Transporter 1 Company Name Dillard		6. US EPA ID Number CA0982523433	
7. Transporter 2 Company Name		8. US EPA ID Number		A. State Transporter's ID 925 634 6850	
9. Designated Facility Name and Site Address ALTA MONT LANDFILL 10840 ALTA MONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0981382732		B. Transporter 1 Phone () -	
11. WASTE DESCRIPTION				C. State Transporter's ID	
a. ROW HAS SOIL, (pf: 55096900)		12. Containers		D. Transporter 2 Phone	
		No. Type		E. State Facility's ID	
b.		001 DT		F. Facility's Phone (925) 449-6349	
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
11a. 55098900 11b. 11c. 11d. T# 691					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POW 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month Day Year 10 14 02	
Printed/Typed Name JAMES COAINER				Signature <i>James Coainer</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month Day Year 10 14 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date Month Day Year	
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR INFORMATION

TRANSPORTER INFORMATION

FACILITY INFORMATION

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10025	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name Pillard		6. US EPA ID Number ICAD 982523433		A. State Transporter's ID 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number ICAD 981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf: 55098900)			No. 001	Type DT	Quantity 00018
					Unit Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId. T# 891			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JORG 563-016 POW 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	Date Month Day Year 10 14 102
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name Jim Nunes				Signature <i>Jim Nunes</i>	Date Month Day Year 10 14 102
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Signature	Date Month Day Year
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	Date Month Day Year

NON-HAZARDOUS WASTE GENERATOR



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10224	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN RUSHWELL			
4. Generator's Phone ((310) 342-9858					
5. Transporter 1 Company Name Dillard		6. US EPA ID Number CA 982523433		A. State Transporter's ID 634686 975-287-184	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone	
9. Designated Facility Name and Site Address ALTA MOUNT LANDFILL 10840 ALTA MOUNT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA D 981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf: 55098900)			No. Type		
			001 DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId. T# 491			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POF 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10 14 02	
Printed/Typed Name Richard CRAIGHEAD				Signature <i>Richard Craighead</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10 14 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date	
Printed/Typed Name				Signature	
				Date	

GENERATOR RECEIVED

TRANSPORTER RECEIVED

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10023	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone () 342-9858					
5. Transporter 1 Company Name <i>Edmundo Caballero</i>		6. US EPA ID Number CA0981435621		A. State Transporter's ID 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTA MOUNT LANDFILL 10840 ALTA MOUNT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf: 55098900)			No. Type		
			001 DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
Ila. 55098900 55034300					
Iib.					
Iic.					
Iid.					
CA 25137					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PCH# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month Day Year 10 14 02	
Printed/Typed Name <i>P. K. Orasco</i>				Signature <i>[Signature]</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month Day Year 10 14 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date Month Day Year	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date Month Day Year	
Printed/Typed Name				Signature	

NON-HAZARDOUS WASTE MANIFEST

GENERATOR

TRANSPORTER

FA

ITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308	Manifest Document No. 10022	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA		MAIL: ATTN: DAN BUSHNELL		
4. Generator's Phone ((310) 342-9856				
5. Transporter 1 Company Name General Services RJM	6. US EPA ID Number CA0982523433	A. State Transporter's ID 926 6346850		
7. Transporter 2 Company Name RJM Trucking	8. US EPA ID Number CA0600206475	B. Transporter 1 Phone (925) 449-1781		
9. Designated Facility Name and Site Address ALTMONT LANDFILL 10840 ALTMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0981382732	C. State Transporter's ID 5703 989-1781	
		D. Transporter 2 Phone (925) 449-6349		
		E. State Facility's ID		
		F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf: 55096900)		No. Type		
		001 DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above		
i1a. 55098900 55034800				
i1b.				
i1c.				
i1d. CA 19320				
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-016 PO# 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10/14/02	
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name ROSA		Signature <i>P. Rosa</i>	Date Month Day Year 10/14/02	
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10021	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858)		6. US EPA ID Number CAD 9825 23433		A. State Transporter's ID 925 6346850	
5. Transporter 1 Company Name Daaba		8. US EPA ID Number		B. Transporter 1 Phone () -	
7. Transporter 2 Company Name		10. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		11. WASTE DESCRIPTION		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
		12. Containers		13. Total Quantity	
		No. Type		Unit Wt./Vol.	
a. NON HAZ SOIL, (pf: 55098900)		001 DT		00018 Y	
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above Il. -55098900 55024300 Iib. CA 116 619 Iic. Iid. T# 215		H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POC 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month Day Year 10 14 02	
Printed/Typed Name AMRUK SINGH				Signature <i>Amrith Singh</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month Day Year 10 14 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10020	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name CUMMINGS	6. US EPA ID Number CAD 982523433	A. State Transporter's ID 925 634 6850		B. Transporter 1 Phone (925) 634 6850	
7. Transporter 2 Company Name Ban Wait	8. US EPA ID Number	C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTA MONT LANDFILL 10840 ALTA MONT PARK ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		E. State Facility's ID	
		F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit	
a. NON HAZ SOIL, (p# 55098900)		No. 001	Type DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above			
IIa. 55098900 55084300 IIb. TH 07050 IIc. IId. CA 109105					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POC 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature <i>Transporter Smith</i>		Date 10 14 02	
Printed/Typed Name		Signature		Date	
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date	
Printed/Typed Name		Signature		Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date	

GENERATOR

TRANSPORTER

CITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556300		Manifest Document No.	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA		MAIL: ATTN: DAN RUSHBELL			
4. Generator's Phone (714) 342-9858					
5. Transporter 1 Company Name LUMMINGS		6. US EPA ID Number CA 9829734333		A. State Transporter's ID 975 534 6553	
				B. Transporter 1 Phone () -	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
				D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAIRITE LANDFILL 10840 ALTAIRITE PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA 0901382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. ROW BASE SOIL, (pt: 5508900)			No. Type		
			00 DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
i. 5508900 55082300					
ii.					
iii.					
iv.					
CA 10115					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JUNE 503 018 PINE 09-13859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10 14 02	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name <i>[Signature]</i>				Month Day Year 10 14 02	
Signature <i>[Signature]</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name "				Month Day Year	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature					

GENERATOR

TRANSPORTER

FA

CITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10018	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858					
5. Transporter 1 Company Name Genings	6. US EPA ID Number Doaba	A. State Transporter's ID		B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name	8. US EPA ID Number	C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTADET LANDFILL 10840 ALTADET PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0981382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION		12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf: 55096980)		No.	Type		
		001	DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above			
i1a. 55096980 58084300					
i1b.					
i1c.					
i1d. T # 1					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10/14/01	
Printed/Typed Name SURINDER SINGH				Signature <i>Surinder Singh</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10/14/01	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date	
Printed/Typed Name				Signature	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date	
Printed/Typed Name				Signature	

GENERATOR'S CERTIFICATION

TRANSPORTER'S CERTIFICATION

FACILITY'S CERTIFICATION

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No CAD982823433	Manifest Document No. 10017	2. Page 1 of 1
3. Generator's Mailing Address HAMILTON AFB MUNATO, CA		ATTN: DAN BUSHNELL		
4. Generator's Phone (310) 342-9858				
5. Transporter 1 Company Name Dufford / Manuel Trucking	6. US EPA ID Number CAD982823433	A. State Transporter's ID 9256346850		
7. Transporter 2 Company Name Cummings Transportation	8. US EPA ID Number	B. Transporter 1 Phone		
9. Destination Facility Name and Site Address 10840 ALTIMONT PASS ROAD LIVERMORE, CA 94550		C. State Transporter's ID		
10. US EPA ID Number CAD981382732		D. Transporter 2 Phone		
		E. State Facility's ID		
		F. Facility's Phone (925) 449-6349		

11. WASTE DESCRIPTION	12. Containers		13. Total Quantity	14. Unit Wt./Vol.
	No.	Type		
a. NON HAZ WOLL, (PI: 55098900)	001	DT	00018	Y
b.				
c.				
d.				

G. Additional Descriptions for Materials Listed Above 11a. 55098900 55034300 11b. 11c. 11d.		H. Handling Codes for Wastes Listed Above
15. Special Handling Instructions and Additional Information EMERGENCY CONTACT (925) 449-6349 BILLARD JUNE 583-018 POF 09-33859		



16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10 14 02
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name FLORESCIO MANUEL		Signature <i>Florescio Manuel</i>	Date Month Day Year 10 14 02
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature	Date Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.		Date
Printed/Typed Name	Signature <i>Ken Brown</i>	Month Day Year 10 14 02

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10016	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA					
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name Dillard / Staffs		6. US EPA ID Number CA0981382732		A. State Transporter's ID 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone	
9. Designated Facility Name and Site Address ALTADET LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. MUN WAE SOIL, (pf: 55098900)			No. Type		
			001 DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
ILa. 55098900 IIb. IIc. IIId.					
T# 144					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POC# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name <i>Harold Holmes</i>		Signature <i>Harold Holmes</i>		Date Month Day Year 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR SIGNATURE

TRANSPORTER SIGNATURE

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308	Manifest Document No. 10015	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MURATO, CA		MAIL: 11/15 ATTN: DAN BUSHNELL	<i>Manifest</i>	
4. Generator's Phone ((300) 342-9858		5. Transporter 1 Company Name Dillards Shaff's	6. US EPA ID Number CA09813822732	A. State Transporter's ID 925834680
		7. Transporter 2 Company Name	8. US EPA ID Number CA09813822732	B. Transporter 1 Phone () -
		9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550	10. US EPA ID Number CA09813822732	C. State Transporter's ID
				D. Transporter 2 Phone
				E. State Facility's ID 925449-6349
				F. Facility's Phone (925) 449-6349
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf: 55096900)		No.		
b.		Type		
c.				
d.				
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above		
11a. 55098900 11b. 11c. 11d. T# 133				
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-016 PO# 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name <i>Robert Freund</i>		Signature <i>Robert Freund</i>	Date Month Day Year 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000756308		Manifest Document No. 10014	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: 10/15 ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858					
5. Transporter 1 Company Name Dillard shafts		6. US EPA ID Number CAD982523433		A. State Transporter's ID 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTIMONT LANDFILL 10840 ALTIMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
			No.	Type	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf: 55098900)			001	BT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
i1a. 55098900					
i1b.					
i1c. T# 143					
i1d.					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10 14 07	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name George Paquette				Date Month Day Year 10 14 07	
Signature <i>George Paquette</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Date Month Day Year	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature					

GENERATOR

TRANSPORTER

F

CITY

NON-HAZARDOUS WASTE MANIFEST

Please print on type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10013	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: <i>[Handwritten]</i>			
4. Generator's Phone ((310) 342-9856)		ATTN: DAN BUSHNELL			
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CA0981435621		A. State Transporter's ID 661 3871842	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10640 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
			No.	Type	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf: 55096900)			001	DT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
IIa. 55096900 55084300 IIb. IIc. T# 76 IId.					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOHN 563-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name <i>Clifford Fretwell</i>				Signature <i>Clifford Fretwell</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10 14 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	
				Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10017		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA				MAIL: _____ ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858)							
5. Transporter 1 Company Name Dillard		6. US EPA ID Number ICAD981382732		A. State Transporter's ID 925 6346850		B. Transporter 1 Phone () -	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number ICAD981382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION a. NOV HAZ SOIL, (pf: 55098900) b. _____ c. _____ d. _____				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
				No.	Type		
				001	DT	00018	Y
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. _____ IIc. _____ IId. T# 391				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POC 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Lance Finkbriant				Signature <i>Lance Finkbriant</i>		Date 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name				Signature		Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name		Date	
				Signature		Month Day Year	

GENERATOR INFORMATION

TRANSPORTER INFORMATION

FACILITY INFORMATION

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308	Manifest Document No. 42511	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA		ATTN: DAE BUSHWELL		
4. Generator's Phone ((310) 342-9858				
5. Transporter 1 Company Name Cummings	6. US EPA ID Number CA0981435621	A. State Transporter's ID 6613871842		
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone () -		
9. Designated Facility Name and Site Address ALTIMONT LANDFILL 10840 ALTIMONT PASS ROAD LIVERMORE, CA 94550		C. State Transporter's ID		
		D. Transporter 2 Phone		
		E. State Facility's ID		
		F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAS SOIL, (pf: 55098900)		No. Type		
		001 DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above IIa. 55098900 55034300 IIb. T# IIc. US IIId.		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DEVLARD JOB# 583-018 POF# 89-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name Dale Jamison		Signature <i>Dale Jamison</i>	Date Month Day Year 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR CONTAMINATION

TRANSPORTER FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10010	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA		MAIL: ATTN: DAN BUSHWELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name Cummings	6. US EPA ID Number CAD 981435021	A. State Transporter's ID 66138718R		B. Transporter 1 Phone ()	
7. Transporter 2 Company Name	8. US EPA ID Number	C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALAMONT LANDFILL 10840 ALAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		E. State Facility's ID	
		F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.	
a. NON HAZ SOIL, (p# 55098900)		No. 001 Type DT	00018	Y	
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 55084300 IIb. IIc. T# 72 IId.		H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date 10 / 02 Month Day Year	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Michael Bass		Signature <i>Michael Bass</i>		Date 10 / 02 Month Day Year	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Date Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date	
Printed/Typed Name		Signature		Month Day Year	

HIGHER QUALITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10009	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9658)					
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CAD 981435621		A. State Transporter's ID 661387184	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTAHONT LANDFILL 10840 ALTAHONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD 981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit
			No.	Type	WT./Vol.
a. NON HAZ SOIL, (p# 55098900)			001	BT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
IIa. 55098900 58084300 IIb. IIc. T# 77 IId.					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 POC 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month 10 Day 14 Year 02	
Printed/Typed Name Roger D Lawrence				Signature <i>Roger D Lawrence</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month 10 Day 14 Year 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

GENERATOR
TRANSPORTER
FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308	Manifest Document No. 10008	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		MAIL: ATTN: DAN BUSHWELL		
4. Generator's Phone ((310) 342-9858)				
5. Transporter 1 Company Name Cummings	6. US EPA ID Number CA0961435621	A. State Transporter's ID 6613871842		
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone () -		
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		C. State Transporter's ID		
10. US EPA ID Number CA0981382732		D. Transporter 2 Phone		
		E. State Facility's ID		
		F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAS SOIL, (pt: 55096900)		No. 001 Type DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above IIa. 55096900 55034300 IIb. IIc. IId. T# 37		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact: (925) 634-6850 BILLARD JOHN 583-018 POW 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month 10 Day 19 Year 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name Gary Flowers		Signature <i>Gary Flowers</i>	Date Month 10 Day 19 Year 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR TITLE CONTINUATION

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10007	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAW BUSHWELL			
4. Generator's Phone ((707) 342-9858		5. Transporter 1 Company Name Cummings		6. US EPA ID Number CA D 981425621	
6. US EPA ID Number CA D 981425621		7. Transporter 2 Company Name		A. State Transporter's ID 5613871842	
9. Designated Facility Name and Site Address ALTA MOUNT LANDFILL 10840 ALTA MOUNT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA D 981382732		B. Transporter 1 Phone	
				C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
a. HOW HAZ SOIL, (pf: 55098900)			No.	Type	14. Unit Wt./Vol.
			001	DT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 58034300 IIb. IIc. II d. T# 2			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 O'NEILLARD JIB# 583-016 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER			Signature <i>Edward Keller</i>		Date Month Day Year 10 14 02
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>Scott Ballard</i>		Date Month Day Year 10 14 02
Printed/Typed Name SCOTT BALLARD			Signature		Date Month Day Year
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date Month Day Year
Printed/Typed Name			Signature		Date Month Day Year
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

NON-HAZARDOUS WASTE

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10006	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA		ATTN: DAN BUSHMILL			
4. Generator's Phone ((310) 342-9858					
5. Transporter 1 Company Name Cummings	6. US EPA ID Number CAD981435621	A. State Transporter's ID 6113871842		B. Transporter 1 Phone () -	
7. Transporter 2 Company Name	8. US EPA ID Number	C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTA MONT LANDFILL 10840 ALTA MONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		E. State Facility's ID	
		F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION		12. Containers		13. Total Quantity	
		No. Type		Unit Wt./Vol.	
a. NOV HAS SOIL, (pf: 55098900)		001 DT		00018 Y	
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above			
11a. 55098900 68034300 11b. 11c. 11d. T# 34					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date 10/14/02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name Cino Lomonaco		Signature <i>Cino Lomonaco</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10005	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHWELL			
4. Generator's Phone ((300) 342-9858)					
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CAD 981435621		A. State Transporter's ID 661 3821842	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf: 55098900)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 55024300 IIb. IIc. II d. T # 23			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOSE 583-018 FOW 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10 14 07	
Printed/Typed Name JORGE CEJA				Signature <i>Jorge Ceja</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10 14 01	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10004	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		ATTN: DAVE BUSHNELL			
4. Generator's Phone ((310) 342-9858					
5. Transporter 1 Company Name Cummings	6. US EPA ID Number CAD 981436621	A. State Transporter's ID 661 3871842		B. Transporter 1 Phone ()	
7. Transporter 2 Company Name	8. US EPA ID Number	C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALAMOGITO LANDFILL 10840 ALAMOGITO PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A 0 9 8 1 3 8 2 7 3 2		E. State Facility's ID	
		F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.	
a. NOB GAS SULL, (pt: 55096900)		No. 001	Type DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above		H. Handling Codes for Wastes Listed Above			
11a. 55096900 11b. 55034300 11c. TH 11d. 40					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 503-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name DAVE EVANKOVICH		Signature <i>Dave Evankovich</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8	Manifest Document No. 10003	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		MAIL: ATTN: DAE BUSHMILL		
4. Generator's Phone ((300) 342-9858				
5. Transporter 1 Company Name Dillard / KUS	6. US EPA ID Number ICAD 982523433	A. State Transporter's ID 925 634 689		
7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone		
9. Designated Facility Name and Site Address ALTAHONT LANDFILL 10840 ALTAHONT PASS ROAD LIVERMORE, CA 94550		C. State Transporter's ID		
		D. Transporter 2 Phone		
		E. State Facility's ID		
		F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOE HAZ SOIL, (pf: 55098900)		No. 001 Type DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId. T# T284		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JUNE 583-018 POC 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name Thomas W. Johns		Signature <i>Thomas Johns</i>	Date Month Day Year 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10002	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOUNTAIN VIEW, CA		MAIL:			
4. Generator's Phone ((310) 342-9838)		ATTN: DAN BUSHWELL			
5. Transporter 1 Company Name Dillard / KUS	6. US EPA ID Number ICAD982523433	A. State Transporter's ID 9256346850		B. Transporter 1 Phone	
7. Transporter 2 Company Name	8. US EPA ID Number	C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTADETT LANDFILL 10840 ALTADETT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number ICAD981382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION		12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAN SOIL, (pf: 55096906)		No.	Type		
		001	DT	00016	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 55096900 11b. 11c. 11d. T # T263			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925)634-6850 DILLARD JOB# 583-018 POF 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date 10 / 14 / 02	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Randy McInerney		Signature <i>Randy McInerney</i>		Date 10 / 14 / 02	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date	

FEDERAL GOVERNMENT

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		Generator's US EPA ID No. C A 0 0 0 0 5 5 6 3 0 8		Manifest Document No. 10001	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone () (310) 342-9658					
5. Transporter 1 Company Name Dillard Environmental Services		6. US EPA ID Number CAD 982523433		A. State Transporter's ID 926 4496349	
7. Transporter 2 Company Name KVS		8. US EPA ID Number		B. Transporter 1 Phone () -	
9. Designated Facility Name and Site Address ALTAHMT LANDFILL 10840 ALTAHMT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD 981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf: 55098900)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d. T# T286			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POF 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date 10/14/02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature <i>Larry Brown</i>		Date 10/14/02	
Printed/Typed Name LARRY BROWN		Signature		Date	
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date	
Printed/Typed Name		Signature		Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 60839		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA				ATTN: DAN BUSHWELL			
4. Generator's Phone ((310) 342-9658)							
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS		6. US EPA ID Number CAD98252343		A. State Transporter's ID		B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAHMT LANDFILL 10840 ALTAHMT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number CAD981382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349			
11. WASTE-DESCRIPTION				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf:)				No. Type		Quantity	Wt./Vol.
				001 DT		00016	Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11a. 11b. 11c. 11d. T# T265				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOBS# 583-018 POF 09-33659							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 15 2002	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name GEORGE W. BURRELL		Signature <i>George W. Burrell</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
19. Discrepancy Indication Space				Printed/Typed Name		Signature	
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name		Signature	
						Date Month Day Year	

GENERATOR

TRANSPORTER

LIABILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 59859		2. Page 1 of 1					
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA				MAIL: ATTN: DAN BUSHNELL							
4. Generator's Phone ((340) 342-9858)											
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS		6. US EPA ID Number CAD98252343		A. State Transporter's ID							
				B. Transporter 1 Phone (925) 634-6850							
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID							
				D. Transporter 2 Phone							
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		E. State Facility's ID							
				F. Facility's Phone (925) 449-6349							
11. WASTE DESCRIPTION a. NON HAZ SOIL, (pf:)				12. Containers		13. Total Quantity		14. Unit Wt./Vol.			
				No.		Type					
				001		DT		00018		Y	
G. Additional Descriptions for Materials Listed Above i.e. 55098900 ii. iii. iv. T# T243				H. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOS# 583-018 PO# 09-33859											
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.											
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year					
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>George Shepherd</i>		Date Month Day Year					
Printed/Typed Name George Shepherd				Signature		Date Month Day Year					
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date Month Day Year					
Printed/Typed Name				Signature		Date Month Day Year					
19. Discrepancy Indication Space											
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature		Date Month Day Year					
Printed/Typed Name				Signature		Date Month Day Year					

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 5 8 8 5 9	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name BYLLARD ENVIRONMENTAL SVCS		6. US EPA ID Number CA 098252343	A. State Transporter's ID		
7. Transporter 2 Company Name		8. US EPA ID Number	B. Transporter 1 Phone (925) 634-6850		
9. Designated Facility Name and Site Address ALTA MOUNT LANDFILL 10840 ALTA MOUNT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA 0981382732	C. State Transporter's ID		
			D. Transporter 2 Phone		
			E. State Facility's ID		
			F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION		12. Containers No.	Type	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf:)		001	DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. II d. T# T247		H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BYLLARD JOSE 583-018 POK 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date Month 10 Day 14 Year 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name A BOSTICK		Signature <i>A Bostick</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.		Printed/Typed Name		Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. 57859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		MAIL: ATTN: DAN BUSHNELL		
4. Generator's Phone ((310) 342-9858)				
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS	6. US EPA ID Number CAD98252343	A. State Transporter's ID	B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name	8. US EPA ID Number	C. State Transporter's ID	D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732	E. State Facility's ID	
		F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION		12. Containers No.	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf:)		001	DT	00018
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above ll. 55098900 llb. llc. lld. T# T324		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDUARDO KELLER		Signature <i>Eduardo Keller</i>	Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name Mike Mead		Signature <i>Mike Mead</i>	Date Month Day Year 10 14 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

GENERATOR TRANSPORTER FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)


NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No: 56859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA				ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858)							
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS		6. US EPA ID Number KVS C A D 9 8 2 5 2 3 4 3		A. State Transporter's ID		B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAHMET LANDFILL 10840 ALTAHMET PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. HOW HAW SOIL, (pf:)				No. Type			
				001 DT		00018	Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId.				H. Handling Codes for Wastes Listed Above			
T# T264							
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POB 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 14 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name JERRY BRYANT		Signature <i>Jerry Bryant</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Date Month Day Year	
19. Discrepancy Indication Space				Signature		Date Month Day Year	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. 5 5 8 5 9	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		MAIL: ATTN: DAN BUSHNELL		
4. Generator's Phone ((714) 342-9858)				
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS.		6. KUS US EPA ID Number CA 09 8 2 5 2 3 4 3	A. State Transporter's ID	B. Transporter 1 Phone (925) 634-6850
7. Transporter 2 Company Name		8. US EPA ID Number	C. State Transporter's ID	D. Transporter 2 Phone
9. Designated Facility Name and Site Address ALCANTARA LANDFILL 10840 ALCANTARA PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA 09 8 1 3 8 2 7 3 2	E. State Facility's ID	F. Facility's Phone (925) 449-6349
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pt:)		No. 001 Type DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d. T# T361		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925)634-6850 DILLARD JOB# 583-016 JOB 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month 10 Day 14 Year 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name H.L. COPC		Signature <i>H.L. Copc</i>	Date Month 10 Day 14 Year 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 54859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFS HAMILTON AFB NOVATO, CA				4. Generator's Phone ((707) 342-9658)			
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS				6. US EPA ID Number CAD98252393		A. State Transporter's ID	
7. Transporter 2 Company Name				8. US EPA ID Number		B. Transporter 1 Phone (925) 634-6830	
9. Designated Facility Name and Site Address ALBRIGHT LANDFILL 10640 ALBRIGHT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number CAD981382732		C. State Transporter's ID	
						D. Transporter 2 Phone	
						E. State Facility's ID	
						F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
				No.	Type		
a. NOV WAS SOIL, (pt)				002	DT	00018	Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above LN 55098900 LN LN LN				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6830 DILLARD JUNE 197 015 018 00 1000							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Randy Melton		Signature <i>Randy Melton</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name		Signature	
						Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. 53859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA		MAIL: ATTC: DAN BUSHNELL		
4. Generator's Phone ((310) 342-9858)				
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS. KVS	6. US EPA ID Number CAD98252343	A. State Transporter's ID		
		B. Transporter 1 Phone (925) 634-6850		
7. Transporter 2 Company Name	8. US EPA ID Number	C. State Transporter's ID		
		D. Transporter 2 Phone		
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732	E. State Facility's ID	
		F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAN SOIL, (pf:)		No. Type		
		001 DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d. T# T244		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PO# 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name TOM R		Signature <i>TOM PORTER</i>	Date Month Day Year 10 11 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 5 2 8 5 9		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA				HAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858)							
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS. Dillard		6. US EPA ID Number CAD98252343		A. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 634-6850			
				C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address ALTMONT LANDFILL 10840 ALTMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		E. State Facility's ID			
				F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION a. NOV HAE SOIL, (pf:) b. c. d.				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
				No.	Type		
				001	DT	00018	Y
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d. T# 911				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>[Signature]</i>		Date Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>[Signature]</i>		Date Month Day Year 10 11 02	
Printed/Typed Name Joe Jo				Signature <i>[Signature]</i>		Date Month Day Year	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature		Date	
Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

LIABILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 5 1 8 5 9		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA				3. Generator's Name and Mailing Address HALL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((310) 342-9858)							
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS.		6. US EPA ID Number KVS C A D 9 8 2 5 2 3 4 3		A. State Transporter's ID		B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALCANTARA LANDFILL 10840 ALCANTARA PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity		14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf:)			No. Type				
			001 DT		00018		Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
IIa. 5509 8900 IIb. IIc. IIId. T# T243							
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month 10 Day 17 Year 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>George Shepherd</i>		Date Month 10 Day 17 Year 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature		Date	
Printed/Typed Name				Signature		Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST


Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 50859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA				ATTN: DAW BUSHWELL			
4. Generator's Phone ((310) 342-9858)							
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS. KVS		6. US EPA ID Number CAD98252343		A. State Transporter's ID		B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALAMONT LANDFILL 10840 ALAMONT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number CAD981382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity		14. Unit Wt./Vol.
a. NOV HAW SOIL, (pf:)			No. Type		Quantity		Wt./Vol.
			001 DT		00018		Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
11a. 55098800 11b. 11c. T# T265 11d.							
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name GEORGE W. BURKETT		Signature <i>George W. Burkett</i>	
						Date Month Day Year 10 11 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
						Date Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FILITY



NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 49859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA		MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone ((340) 342-9858)					
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS.		6. US EPA ID Number CAD98252343		A. State Transporter's ID	
				B. Transporter 1 Phone	(925) 634-6850
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
				D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		E. State Facility's ID	
				F. Facility's Phone	(925) 449-6349
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. MOW HAS SOIL, (pf:)			No. Type		
			001 DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above Ila. Ilb. Ilc. Ild. T# T286			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name LARRY BROWN		Signature <i>Larry Brown</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.		Printed/Typed Name		Signature	
				Date	

GENERATOR

TRANSPORTER

FA

LITY

7/23/02
 2347
 237

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 4 8 8 5 9	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		HALL:			
4. Generator's Phone ((310) 342-9858)		ATTN: DAN BUSHNELL			
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS.		6. US EPA ID Number KVS C A D 9 8 2 5 2 3 4 3		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 634-6650	
9. Designated Facility Name and Site Address ALYAMONT LANDFILL 10840 ALYAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf:)			No. Type		
			001 DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
IIa. IIb. IIc. IId.			T# T247		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6650 DILLARD JOB# 583-018 POC# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10 11 02	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name A BOSTICK				Month Day Year 10 11 02	
Signature <i>A Bostick</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Month Day Year	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature					

GENERATOR

TRANSPORTER

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 47859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		MAIL: ATTN: DAN BUSHWELL			
4. Generator's Phone ((310) 342-9658)					
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS. Hoyt		6. US EPA ID Number CAD982523433		A. State Transporter's ID	
7. Transporter 2 Company Name HOYT TRANSPORTATION INC.		8. US EPA ID Number CAD981925853		B. Transporter 1 Phone (925) 634-6850	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10640 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		C. State Transporter's ID	
				D. Transporter 2 Phone 909-734-3771	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. HOW HAZ SOIL, (pf:)			No. Type		
			001 DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
11a. 11b. 11c. 11d. T.# 160					
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOE 563-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name ROBERT L. MOORE		Signature <i>Robert L. Moore</i>		Date Month Day Year 10 11 02	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name		Signature		Date Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 46859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOUNTAIN VIEW, CA		MAIL: ATTN: DAN RUSHWELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS.		6. US EPA ID Number HOYT C A D 9 8 2 5 2 3 4 3		A. State Transporter's ID (925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone	
9. Designated Facility Name and Site Address ALTA MOUNT LANDFILL 10840 ALTA MOUNT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
			No.	Type	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf:)			001	DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. IIb. IIc. IId. T # 120			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POC 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name <i>Beau T. Freity</i>				Signature <i>Beau T. Freity</i>	
				Date 10 11 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Signature	
				Date Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

LIABILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 41859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOUNTAIN VIEW, CA				MAIL: ATTN: DAN BUSHWELL			
4. Generator's Phone (310) 342-9858				6. US EPA ID Number		A. State Transporter's ID	
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS.				8. US EPA ID Number CAD982523433		B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name				10. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550				11. WASTE DESCRIPTION CAD981382732		D. Transporter 2 Phone	
						E. State Facility's ID	
						F. Facility's Phone (925) 449-6349	
				12. Containers		13. Total Quantity	
				No. Type		Unit Wt./Vol.	
a. NO HAZ SOIL, (pf:)				001 DT		00018	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above LLa. 55098900 LLb. LLc. LLd. T# 391				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Lance Englebright</i>		Date Month Day Year 10 11 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature		Date	
Printed/Typed Name						Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 4 2 8 5 9	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA					
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS		6. US EPA ID Number C A D 9 8 2 5 2 3 4 3		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 634-6850	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
11. WASTE DESCRIPTION		12. Containers		13. Total Quantity	
a. HOW HAZ SOIL, (pf:)		No. Type		14. Unit Wt./Vol.	
		001 DT		00018 Y	
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. II d. T# 691				H. Handling Codes for Wastes Listed Above	
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOE# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10 11 02	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name JAMES GAINER				Month Day Year 10 11 02	
Signature <i>James Gainer</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Month Day Year	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date	
Printed/Typed Name				Month Day Year	
Signature					

GENERATOR

TRANSPORTER

F
L
I
T
Y

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. 43859	2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOUNTAIN CA		MAIL: ATTN: DAN RUSHWELL			
4. Generator's Phone () (310) 742-9858		6. US EPA ID Number	A. State Transporter's ID		
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS.		<i>Dillard</i>	B. Transporter 1 Phone	(925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number C A B 9 0 2 5 2 3 4 3 3	C. State Transporter's ID		
9. Designated Facility Name and Site Address ALTAHMT LANDFILL 10840 ALTAHMT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number C A B 9 0 1 3 0 2 7 3 2	D. Transporter 2 Phone		
11. WASTE DESCRIPTION		E. State Facility's ID		F. Facility's Phone (925) 449-6349	
a. HOW MANY SOIL, (pf:)		12. Containers		13. Total Quantity	
		No.		14. Unit Wt./Vol.	
		Type			
		001 BT		00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above ILa. 55098900 ILb. ILc. ILd. T # 191		H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name Steve M. Turner		Date Month Day Year 10 11 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature <i>Steve M. Turner</i>		Date Month Day Year 10 11 02	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. 44859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOUNTAIN VIEW, CA		MAIL: ATTN: DAN BUSHWELL		
4. Generator's Phone (310) 342-0858	5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS.	6. US EPA ID Number KUS	A. State Transporter's ID	
7. Transporter 2 Company Name	8. US EPA ID Number CAD98252343		B. Transporter 1 Phone (925) 634-6850	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550	10. US EPA ID Number CAD981382732		C. State Transporter's ID	
11. WASTE DESCRIPTION NOV HAZ SOIL, (pf:)		12. Containers No. 001	13. Total Quantity DT 00018	14. Unit Wt./Vol. Y
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d. T# T244		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JON 583-018 POW 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month 10 Day 02 Year 02	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature <i>[Signature]</i>	Date Month 10 Day 02 Year 02	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 45850	2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATIA, CA						
4. Generator's Phone (310) 342-0858						
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS				6. US EPA ID Number CAD00252743		
7. Transporter 2 Company Name				8. US EPA ID Number		
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number CAD981382732		
11. WASTE DESCRIPTION				12. Containers	13. Total Quantity	
a. NOV HAZ SOIL, (pf:)				No.	14. Unit Wt./Vol.	
				Type		
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above		
11a. 55098900 11b. 11c. 11d. T# T263						
15. Special Handling Instructions and Additional Information Emergency Contact (925)634-6850 BILLARD JOB# 583-018 PO# 09-33859						
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.						
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	Date Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name Randy Melton				Signature <i>Randy Melton</i>	Date Month Day Year 10 11 02	
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name				Signature	Date Month Day Year	
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.						
Printed/Typed Name				Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 40859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MURATO, CA		MAIL: ATTN: DAW BUSHNELL			
4. Generator's Phone (415) 342-0858		6. US EPA ID Number CA 08252343		A. State Transporter's ID	
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS		Dillard		B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address ALAMINET LANDFILL 10840 ALAMINET PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA 081382732		D. Transporter 2 Phone	
11. WASTE DESCRIPTION				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
a. NON HAZ SOIL, (pf:)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt./Vol.
		001	DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 55098900 TLA TLb TLc TLd TA 491			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 POC# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10 11 02	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Richard CRATCHEA				Date Month Day Year 10 11 02	
Signature <i>Richard Cratchea</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name				Date Month Day Year	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature					

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 39859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOUNTAIN VIEW, CA				MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone (310) 342-9858				6. US EPA ID Number		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard				7. Transporter 2 Company Name BILLARD ENVIRONMENTAL SVCS.		B. Transporter 1 Phone (925) 634-6850	
8. US EPA ID Number CAD981382732				9. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address ALCANTARA LANDFILL 10640 ALCANTARA PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number CAD981382732		D. Transporter 2 Phone	
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
a. NOV HAZ SOIL, (pf:)				No. Type		14. Unit Wt./Vol.	
				001 DT		00018 Y	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d. J# 891				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date 10/02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Jim Nunes		Signature <i>Jim Nunes</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name		Signature	
						Date	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. 38859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		MAIL: ATTN: DAN BUSHWELL		
4. Generator's Phone ((370) 342-9858)		5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS	6. US EPA ID Number CA 098252343	A. State Transporter's ID
		7. Transporter 2 Company Name	8. US EPA ID Number	B. Transporter 1 Phone (925) 634-6850
		9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550	10. US EPA ID Number CA 0981382732	C. State Transporter's ID
				D. Transporter 2 Phone
				E. State Facility's ID
				F. Facility's Phone (925) 449-6349
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOB HAS SOIL, (pf:)		No. 001	Type DT	00018
b.				Y
c.				
d.				
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId. T# 243		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JUG# 583-018 POF 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date 10/11/02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name <i>George Shepherd</i>		Signature <i>George Shepherd</i>	Date 10/11/02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date	

GENERATOR

TRANSPORTER

LITTY

NON-HAZARDOUS WASTE MANIFEST

type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest Document No.

2. Page 1

of

3. Generator's Name and Mailing Address

HAMILTON AND
HAMILTON BROS

HALL

4. Generator's Phone ()

(314) 382-9076

ATTN: DAN SHERIDAN

5. Transporter 1 Company Name

6. US EPA ID Number

A. State Transporter's ID

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter 1 Phone

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address

ALTAHMET LANDFILL
10640 ALTAHMET PASS ROAD
LIVERMORE, CA 94550

10. US EPA ID Number

E. State Facility's ID

F. Facility's Phone

11. WASTE DESCRIPTION

12. Containers

13. Total Quantity

14. Unit Wt./Vol.

a.

MOW MASH SOIL, (pH:)

NO T 00018 Y

b.

c.

d.

G. Additional Descriptions for Materials Listed Above

H. Handling Codes for Wastes Listed Above

11a. 55098900
11b.
11c.
11d.

T 2441

15. Special Handling Instructions and Additional Information

Emergency Contact: (925) 634-6050 DILLARD
PHONE 583-0100 FAX 09-33059

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Date

Printed/Typed Name

EDWARD KELLER

Signature

Edward Keller

Month Day Year

10 11 02

17. Transporter 1 Acknowledgement of Receipt of Materials

Date

Printed/Typed Name

Tom Porter

Signature

Tom Porter

Month Day Year

10 11 02

18. Transporter 2 Acknowledgement of Receipt of Materials

Date

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Date

Printed/Typed Name

Signature

Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 36859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA					
4. Generator's Phone ((707) 342-9858)				ATTN: DAN BUSHNELL	
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS		6. US EPA ID Number KUS CAD98252343		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 634-6850	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf:)			No.	Type	
			001	DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IIId. T# 263			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 POC 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month Day Year 10 11 02	
Printed/Typed Name <i>Randy Metton</i>				Signature <i>[Signature]</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month Day Year 10 11 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 35859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB EDWARD, CA				MAIL: ATTN: DAW BUSHWELL			
4. Generator's Phone: (310) 342-9850				6. US EPA ID Number		A. State Transporter's ID	
5. Transporter 1 Company Name: BILLARD ENVIRONMENTAL SVCS.				7. Transporter 2 Company Name: BILLARD ENVIRONMENTAL SVCS.		B. Transporter 1 Phone: (925) 634-6850	
6. US EPA ID Number: CAD08252343				8. US EPA ID Number: CAD081382732		C. State Transporter's ID	
7. Transporter 2 Company Name: BILLARD ENVIRONMENTAL SVCS.				9. Designated Facility Name and Site Address: ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		D. Transporter 2 Phone	
8. US EPA ID Number: CAD081382732				10. US EPA ID Number: CAD081382732		E. State Facility's ID	
9. Designated Facility Name and Site Address: ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550				11. WASTE DESCRIPTION		F. Facility's Phone: (925) 449-6349	
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
a. ROW HAS SOIL, (pf:)				No. Type		14. Unit Wt./Vol.	
				001 DT		00018 Y	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above: 11a. 55098900 11b. 11c. 11d. T# 243				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information: Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name: EDWARD KELLER				Signature: <i>Edward Keller</i>		Date: 10/11/02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name: George Shepherd		Signature: <i>George Shepherd</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name:		Signature:	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name:		Signature:	
						Date:	

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. 34859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA		MAIL: ATTN: DAVE BUSHMELL		
4. Generator's Phone (370) 342-0850		6. US EPA ID Number	A. State Transporter's ID	
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS		hoyt CAD08252343	B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name Hoyt Transportation Inc		8. US EPA ID Number CAD981425853	C. State Transporter's ID	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD081382732	D. Transporter 2 Phone 909-734391	E. State Facility's ID
			F. Facility's Phone (925) 449-6340	
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. ROW HAZ SOIL, (pf:)		No. Type		
		001 DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId.		H. Handling Codes for Wastes Listed Above T# 160		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POC 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name ROBERT L. MOORE		Signature <i>Robert L. Moore</i>	Date Month Day Year 10 11 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

Print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No. 33859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB CALIFORNIA		MAIL : ATTN: DAE BUSHNELL		
4. Generator's Phone (310) 342-9858	5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS.	6. US EPA ID Number Hoyt	A. State Transporter's ID	
7. Transporter 2 Company Name	8. US EPA ID Number CA 0962523433	B. Transporter 1 Phone (925) 634-6850	C. State Transporter's ID	
9. Designated Facility Name and Site Address ALTAHUNT LANDFILL 10840 ALTAHUNT PASS ROAD LIVERMORE, CA 94550	10. US EPA ID Number CA 0981382732	D. Transporter 2 Phone	E. State Facility's ID	
11. WASTE DESCRIPTION NON HAZ SOIL, (pf:)	12. Containers No. Type 001 DT	13. Total Quantity 00018	14. Unit Wt./Vol. Y	
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d. T# 120		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PO# 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Dean T. Freitag		Signature <i>Dean T. Freitag</i>	Date Month Day Year 10 11 02	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19. Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 32859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA				MAIL: ATTN: DAVE BUSHNELL			
4. Generator's Phone (370) 342-9858				6. US EPA ID Number		A. State Transporter's ID	
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS. <i>Dillard</i>				CAD08252343		B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name				8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address ALTA MINT LANDFILL 10840 ALTA MINT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number		D. Transporter 2 Phone	
						E. State Facility's ID	
						F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. #OW HAZ SOIL, (pE:)				No. Type			
				001 DT		00018	Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
11a. 55098900							
11b.							
11c.							
11d. T # 391							
15. Special Handling Instructions and Additional Information							
Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name				Signature		Date	
EDWARD KELLER				<i>Edward Keller</i>		Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Date	
Lance Englebright				<i>Lance Englebright</i>		Month Day Year 10 11 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date	
						Month Day Year	

GENERATOR

TRANSPORTER

LIABILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 31859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA				MAIL: ATTN: DAE BUSHNELL			
4. Generator's Phone ((310) 342-9858)				6. US EPA ID Number		A. State Transporter's ID	
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS				Dillard CA 098252343		B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name				8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address ALTAHMET LANDFILL 10840 ALTAHMET PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number CA 0981382732		D. Transporter 2 Phone	
						E. State Facility's ID	
						F. Facility's Phone (925) 449-6340	
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pf:)				No. Type			
				001 DT		00018	Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId. T# 691				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 11 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name JAMES GAINOR		Date Month Day Year 10 17 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature <i>James Gainor</i>		Date Month Day Year	
19. Discrepancy Indication Space				Printed/Typed Name		Date Month Day Year	
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FA

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 30859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFF HAMILTON AFF NOVATO, CA				MAIL: ATTN: DAN BUSHWELL			
4. Generator's Phone (714) 342-0858							
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS		6. US EPA ID Number CAD98252343		A. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 634-6850			
9. Designated Facility Name and Site Address ALTAHMT LANDFILL 10840 ALTAHMT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (925) 449-6369			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
a. NOV HAZ SOIL, (pf:)				No. Type		Unit Wt./Vol.	
				001 DT		00018 Y	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId. T# 124				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Travis Pablo SR		Signature <i>Travis Pablo SR</i>	
						Date Month Day Year 10 10 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
						Date Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 29859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA				MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone () (310) 347-9858				5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS.		A. State Transporter's ID	
				US EPA ID Number CA D 0 8 2 5 2 3 4 3		B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name				8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number CA D 0 8 1 3 8 2 7 3 2		D. Transporter 2 Phone	
						E. State Facility's ID	
						F. Facility's Phone (925) 439-6349	
11. WASTE DESCRIPTION a. NOV HAZ SOIL, (pf:)				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
				No.	Type		
				001	BT	00018	Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId.				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 JOB# 09-33859 T # 117							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 19 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Ron Yeley		Signature <i>Ron Yeley</i>	
						Date Month Day Year 10 19 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
						Date Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name		Signature	
						Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 28859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA				MAIL: ATTN: DAN BUSHNELL			
4. Generator's Phone (310) 342-9858							
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS		6. US EPA ID Number CA0008252343		A. State Transporter's ID			
7. Transporter 2 Company Name SHAFES		8. US EPA ID Number CA000090266		B. Transporter 1 Phone (925) 634-6850			
9. Designated Facility Name and Site Address ALTA MONT LANDFILL 10840 ALTA MONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA00081382732		C. State Transporter's ID		D. Transporter 2 Phone 661 391475	
				E. State Facility's ID			
				F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	
a. NON HAZ SOIL, (pf:)				No. Type		Unit Wt./Vol.	
				001 DT		00018 Y	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d. T# 114				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date 10/10/02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name DARREN MCKENZIE		Signature <i>Darren McKenzie</i>	
						Date 10/10/02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
						Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name		Signature	
						Date	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 27039		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB CALIFORNIA				4. Contact Person NAME: DAN BUSNELL ATTN: DAN BUSNELL			
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS.		6. US EPA ID Number Shaffs		A. State Transporter's ID		B. Transporter 1 Phone (925) 634-8850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number		E. State Facility's ID	
11. WASTE DESCRIPTION NON HAZ SOIL, (pt:)				12. Containers No. Type		13. Total Quantity	
a.				00 BT		00018 Y	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. T = 115 11d.				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 563-018 PO# 09-11859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>[Signature]</i>		Date Month Day Year 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name BLEN RUTLEDGE				Signature <i>[Signature]</i>		Date Month Day Year 10 10 02	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name				Signature		Date Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19. Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR
TRANSPORTER
FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 26859	2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA						
4. Generator's Phone () (925) 942-9858						
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS				6. US EPA ID Number CA0008252343		
7. Transporter 2 Company Name				8. US EPA ID Number		
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number CA00081382732		
11. WASTE DESCRIPTION				12. Containers	13. Total Quantity	
a. NOV HAZ SOIL, (pf:)				No.	14. Unit Wt./Vol.	
				Type		
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. T# 142 11d.				H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information EMERGENCY CONTACT (925)634-6850 BILLARD JOB# 583-016 POF 09-33859						
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.						
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	Date Month Day Year 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date		
Printed/Typed Name Arthur Wilson				Signature <i>Arthur Wilson</i>	Date Month Day Year 10 10 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date		
Printed/Typed Name				Signature	Date Month Day Year	
19. Discrepancy Indication Space						
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.						
Printed/Typed Name				Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 25855	2. Page 1 of 1		
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MILITARY CA							
4. Generator's Phone (714) 342-0858							
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS.				6. US EPA ID Number GA0000252313			
7. Transporter 2 Company Name				8. US EPA ID Number			
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number GA00001382732			
11. WASTE DESCRIPTION NON HAZ SOIL, (pf:)				12. Containers No. Type	13. Total Quantity Quantity	14. Unit Unit Wt./Vol.	
a.				001	DT	00016	Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above Ia. 55098900 Ib. Ic. T# 141 Ild.				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name DALE POOLE				Signature <i>D. Poole</i>		Date Month Day Year 10 10 02	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name				Signature		Date Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature		Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556302		Manifest Document No. 24859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOUNTAIN VIEW, CA					
4. Generator's Phone () (310) 342-0858					
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS		6. US EPA ID Number CA0000252343		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 634-6850	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA00001382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6340	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAZ SOIL, (pt:)			No. Type		
			001 DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId. TII 691			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOHN 583-018 PONG 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month Day Year 10 18 02	
Printed/Typed Name JAMES GAINES				Signature <i>James Gaines</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date Month Day Year	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTEE

LIITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No. 23859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA				MAIL: ATTN: DAV RUSHSELL			
4. Generator's Phone () (310) 342-9858				6. US EPA ID Number		A. State Transporter's ID	
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS				7. Transporter 2 Company Name		B. Transporter 1 Phone (925) 634-6850	
9. Designated Facility Name and Site Address ALTAJUNT LANDFILL 10840 ALTAJUNT PASS ROAD LIVERMORE, CA 94550				8. US EPA ID Number CAD981382732		C. State Transporter's ID	
11. WASTE DESCRIPTION				10. US EPA ID Number CAD981382732		D. Transporter 2 Phone	
a. WORK HAZ SOIL, (pf:)				12. Containers No. Type		13. Total Quantity	
				001 DT		00018	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above IIa. 5509890 IIb. IIc. T# 140 IId.				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POC# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Joe Wheeler				Signature <i>Joe Wheeler</i>		Date Month Day Year 10 10 02	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name				Signature		Date Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19. Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FA

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000 556308		Manifest Document No. 22859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA					
4. Generator's Phone (Area Code) (916) 442-9858				ATTN: DAN BUSHNELL	
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS		6. US EPA ID Number CA0000 252343		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 634-6850	
9. Designated Facility Name and Site Address ALAMONT LANDFILL 10840 ALAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0000 1382132		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit
a. NOV HAZ SOIL, (pf:)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId.			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JUL 6 583-018 PCH 09-33859 T# 144					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10 10 02	
Printed/Typed Name MARCO HOLMAN				Signature <i>Marco Holman</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10 10 02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 21859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA					
4. Generator's Phone () (410) 342-9858					
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS.				A. State Transporter's ID	
6. US EPA ID Number CA 0 0 8 2 5 2 7 3 2				B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name				C. State Transporter's ID	
8. US EPA ID Number				D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550				E. State Facility's ID	
10. US EPA ID Number CA 0 0 8 1 3 8 2 7 3 2				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf:)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above ILa. 5509890d ILb. ILc. ILd. Attach # 111			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name BRINDEN OBELL				Signature <i>Brinden Obell</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10/10/02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date	
Printed/Typed Name				Signature	

GENERATOR

TRANSPORTER

FA

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 20859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA					
4. Generator's Phone (415) 342-9858				ATTN: DAN BUSHNELL	
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS		6. US EPA ID Number CA0982523#3		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 634-6850	
9. Designated Facility Name and Site Address ALTA MOUNT LANDFILL 10840 ALTA MOUNT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOW HAS SOIL, (pf:)			No. 001	Type DT	00018 Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above Ila. 55098900 Iib. Iic. Iid.			H. Handling Codes for Wastes Listed Above Truck # 143		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 POC# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10 10 02	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name George Paquette				Month Day Year 10 10 02	
Signature <i>George Paquette</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Month Day Year	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature					

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA					
4. Generator's Phone (310) 342-0858					
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS / SHG				6. US EPA ID Number CA00002523433	
7. Transporter 2 Company Name				8. US EPA ID Number	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number CA0981382737	
11. WASTE DESCRIPTION NON HAZ SOIL, (pf:)				12. Containers No. 001 Type DT	13. Total Quantity 00018
				14. Unit Wt./Vol. Y	
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IIId.				H. Handling Codes for Wastes Listed Above Trucks # 133	
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD MOB# 503-018 FOM# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLETZ				Date Month 19 Day 19 Year 02	
Signature <i>Edward Keltz</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials				Date Month 10 Day 19 Year 02	
Printed/Typed Name Robert Frank					
Signature <i>Robert Frank</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name					
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date	
Printed/Typed Name					
Signature					

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 18859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOUNTAIN VIEW, CA					
4. Generator's Phone (916) 347-0858				ATTN: DAN BUSHWELL	
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS		6. US EPA ID Number CA0000252343		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 634-6850	
9. Designated Facility Name and Site Address ALAMONT LANDFILL 10840 ALAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0001382732		C. State Transporter's ID	
11. WASTE DESCRIPTION				D. Transporter 2 Phone	
a. MOW MASH SOIL, (pf:)		12. Containers No. Type 001 DT		13. Total Quantity 00016	
b.				14. Unit Wt./Vol. Y	
c.					
d.					
G. Additional Descriptions for Materials Listed Above Ilb. 55098900 Ilc. Truck# 130				H. Handling Codes for Wastes Listed Above	
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOE@ 583-018 POME 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 10/10/02	
Printed/Typed Name CYNTHIA WALLACE				Signature <i>Cynthia Wallace</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date 10/10/02	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date	
Printed/Typed Name				Signature	
				Month Day Year	

GENERATOR

TRANSPORTEE

LIABILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000 556 308		Manifest Document No. 17850	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA					
4. Generator's Phone (310) 442-9850					
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS.		6. US EPA ID Number CA 0 9 0 2 5 2 3 4 3		A. State Transporter's ID	
7. Transporter 2 Company Name HOYT TRANSPORTATION INC.		8. US EPA ID Number CA 0 9 8 1 4 2 5 8 5 3		B. Transporter 1 Phone (925) 634-6850	
9. Designated Facility Name and Site Address ALTAHMT LANDFILL 10840 ALTAHMT PASS ROAD LIVERMORE, CA 94550				C. State Transporter's ID	
				D. Transporter 2 Phone 909-774-7191	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6149	
11. WASTE DESCRIPTION		12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. BOW MAN SOIL, (pf:)		No.	Type		
		001	DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId.				H. Handling Codes for Wastes Listed Above	
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10 10 02	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name Robert L. Moore				Month Day Year 10 10 02	
Signature <i>Robert L. Moore</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Month Day Year	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature					

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 16859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOUNTAIN VIEW, CA					
4. Generator's Phone () (310) 342-9858				ATTN: DAN BUSHNELL	
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS		6. US EPA ID Number CA098252343		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (925) 634-6850	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0981382732		C. State Transporter's ID	
11. WASTE DESCRIPTION NOX HAZ SOIL, (pt:)				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
				12. Containers	
				No. Type	
				13. Total Quantity	
				14. Unit Wt./Vol.	
a. NOX HAZ SOIL, (pt:)				001 DT 00018 Y	
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d.				H. Handling Codes for Wastes Listed Above Truck #120	
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOSE 563-018 POF 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLERZ				Signature <i>Edward Kellerz</i>	
				Date Month Day Year 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name <i>Beau T. Freitag</i>				Signature <i>B T Freitag</i>	
				Date Month Day Year 10 10 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Signature	
				Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 16859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA					
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS. / Tam Tak		6. US EPA ID Number CA 098252343		A. State Transporter's ID	
				B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
				D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAHONT LANDFILL 10840 ALTAHONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA 0981382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. HOW HAS SOIL, (pf:)			No. Type		
			001 DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d.			H. Handling Codes for Wastes Listed Above		
			Truck # 602 P02		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOHN 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date 10/10/02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name TAM TAK		Signature <i>Tam Tak</i>		Date 10/10/02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	
				Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. MAIL: CA0000556308		Manifest Document No. 15859		2. Page 1 of 1	
3. Generator Name and Mailing Address HAMILTON AFB NOVATO, CA (310) 342-9858				ATTN: DAE KUSHNELL			
4. Generator's Phone ()		6. US EPA ID Number CA D 9 8 2 5 2 3 4 3		A. State Transporter's ID (925) 634-6850		B. Transporter 1 Phone	
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS/shaff		8. US EPA ID Number		C. State Transporter's ID		D. Transporter 2 Phone	
7. Transporter 2 Company Name		10. US EPA ID Number CA D 9 8 1 3 8 2 7 3 2		E. State Facility's ID		F. Facility's Phone (925) 449-6349	
9. Designated Facility Name and Site Address ALTA MOUNT LANDFILL 10840 ALTA MOUNT PASS ROAD LIVERMORE, CA 94550							
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. HOW RAW SOIL, (pt:)				No. Type		Quantity	Unit Wt./Vol.
				001 DT		00018	Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId.				H. Handling Codes for Wastes Listed Above			
				Truck # 118			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 PO# 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Jesse Biulla		Signature <i>Jesse Biulla</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Signature	
19. Discrepancy Indication Space							
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name		Signature	
						Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308	Manifest Document No. 14859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		ATTN: DAN BUSHNELL		
4. Generator's Phone ((310) 342-9858)				
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS.		6. US EPA ID Number CAD98252743	A. State Transporter's ID	(925) 634-6850
7. Transporter 2 Company Name		8. US EPA ID Number	C. State Transporter's ID	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732	D. Transporter 2 Phone	
		E. State Facility's ID		
		F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf:)		No. 001 Type DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d.		H. Handling Codes for Wastes Listed Above		
		Track #124		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 PCW 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date 10/10/02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name Travis Pablo SF		Signature <i>Travis Pablo SF</i>	Date 10/10/02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date	

GENERATOR

TRANSPORTER

FA

LI
TY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308	Manifest Document No. 12859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA		ATTN: DAN BUSHNELL		
4. Generator's Phone ((310) 352-9858)				
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS / SHAF		6. US EPA ID Number CAD98252343	A. State Transporter's ID	
		B. Transporter 1 Phone (925) 634-6850		
7. Transporter 2 Company Name SHAF's		8. US EPA ID Number CAR000090266	C. State Transporter's ID	
		D. Transporter 2 Phone 661 391 45 45		
9. Designated Facility Name and Site Address ALTA MOUNT LADE TIL 10840 ALTA MOUNT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732	E. State Facility's ID	
		F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. MOW HAN SOIL, (pf:)		No. Type		
		001 DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d.		H. Handling Codes for Wastes Listed Above		
		Truck # 114		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOHN 583-018 PGM 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date Month Day Year 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name DARRIN MCKENZIE		Signature <i>Darrin McKenzie</i>	Date Month Day Year 10 10 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature	Date Month Day Year	
19. Discrepancy Indication Space				
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 11859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MAYATO, CA		ATTN: DAW BUSHBELL			
4. Generator's Phone ((310) 342-9858)					
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS. / Shaft		6. US EPA ID Number CA098252343		A. State Transporter's ID (925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address ALAMONT LANDFILL 10840 ALAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0981382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit
a. NON HAZ SOIL, (pf:)			No. Type		WT./Vol.
			001 DT	00016	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId.			H. Handling Codes for Wastes Listed Above		
			Truck #115		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POC# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date 10/10/02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name BEN RUTLEDGE				Signature <i>BEN</i>	
				Date 10/10/02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Signature	
				Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 10859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		4. Generator's Phone (310) 342-9858		ATTN: DAE BUSHNELL	
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS. / shaft		6. US EPA ID Number CAD98252343		A. State Transporter's ID (925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone	
				C. State Transporter's ID	
				D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAHOT LANDFILL 10840 ALTAHOT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NON HAZ SOIL, (pf:)			No. Type		
			001 DT	00016	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d.			H. Handling Codes for Wastes Listed Above		
			Truck # 144		
15. Special Handling Instructions and Additional Information EMERGENCY CONTACT (925) 634-6850 DILLARD JOE@ 583-016 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>	
				Date Month Day Year 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name HAROLD HOLMAN				Signature <i>Harold Holman</i>	
				Date Month Day Year 10 10 02	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Signature	
				Date Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308	Manifest Document No. 09859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		ATTN: DAN BUSHNELL		
4. Generator's Phone ((310) 342-9858)				
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS	6. US EPA ID Number CAD98252343	A. State Transporter's ID		
		B. Transporter 1 Phone (925) 634-6850		
7. Transporter 2 Company Name	8. US EPA ID Number	C. State Transporter's ID		
		D. Transporter 2 Phone		
9. Designated Facility Name and Site Address ACTIVIST LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732	E. State Facility's ID	
		F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit
a. SOIL HAS SOIL, (pt:)		No. 001 Type DI	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId.		H. Handling Codes for Wastes Listed Above		
		Truck # 147		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD PHONE 703-016 FOR 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>	Date 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name DALE POOLE		Signature <i>D Poole</i>	Date 10 10 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature	Date	
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature	Date	

GENERATOR

TRANSPORTER

FA

LITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 08859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		ATTN: DAE BUSHNELL			
4. Generator's Phone (310) 342-9858					
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS. / shaft		6. US EPA ID Number CA098252343		A. State Transporter's ID	
				B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
				D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA0981382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOB HAZ SOIL, (pf:)			No. Type		
			001 DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 5508908 55098900 IIb. IIc. IIId.			H. Handling Codes for Wastes Listed Above		
			Truck 140		
15. Special Handling Instructions and Additional Information Emergency Contact: (925) 634-6850 DILLARD JOHN 583-018 POC 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER				Date Month Day Year 10 10 02	
Signature <i>Edward Keller</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name JOE WHEELER				Date Month Day Year 10 10 02	
Signature <i>Joe Wheeler</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Date Month Day Year	
Signature					
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature					

GENERATOR

TRANSPORTER

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 07859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		ATTN: DAN BUSWELL			
4. Generator's Phone (310) 342-9858					
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS / Staff		6. US EPA ID Number CAD98252343		A. State Transporter's ID	
				B. Transporter 1 Phone (925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
				D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALDENHILL LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. NOB HAZ SOIL, (pf:)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above Uls. 55098900 Ulv. Ulc. Uld.			H. Handling Codes for Wastes Listed Above		
			Truck # 142		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD PHONE 925-018 202 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name Harkan Wilson		Signature <i>Harkan Wilson</i>	
				Date 10 10 02	
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature	
				Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date	
				Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 06859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB NOVATO, CA		ATTN: DAE BUSHNELL			
4. Generator's Phone () (310) 342-9858					
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS. / Shaffer		6. US EPA ID Number CAD98252343		A. State Transporter's ID (925) 634-6850	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone	
9. Designated Facility Name and Site Address ALTAIR FILL LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. WOM HAS SOIL, (pF:)			No. Type		
			001 BT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above IIa. 55098906 IIb. IIc. IId.			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-016 POF 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date Month Day Year 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name George Pague-H		Signature <i>George Pague-H</i>		Date Month Day Year 10 10 02	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name		Signature		Date Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA 0000556308	Manifest Document No. 05859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWATO, CA		ATTN: DAN BUSHNELL		
4. Generator's Phone ((310) 342-9058)				
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS / Staff's	6. US EPA ID Number CAD98252343	A. State Transporter's ID		B. Transporter 1 Phone (925) 634-6850
7. Transporter 2 Company Name	8. US EPA ID Number	C. State Transporter's ID		D. Transporter 2 Phone
9. Designated Facility Name and Site Address ALTYARD LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550	10. US EPA ID Number CAD981382732	E. State Facility's ID		F. Facility's Phone (925) 449-6349
11. WASTE DESCRIPTION		12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. HOW HAZ SOIL, (pf:)		No. Type 001 DT	00018	Y
b.				
c.				
d.				
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. IId.		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 POF# 09-33859				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name EDWARD KELLER		Signature <i>Edward Keller</i>		Date Month Day Year 10 10 02
17. Transporter 1 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name Robert Frank		Signature <i>Robert Frank</i>		Date Month Day Year 10 10 02
18. Transporter 2 Acknowledgement of Receipt of Materials		Date		
Printed/Typed Name		Signature		Month Day Year
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FA

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308		Manifest Document No. 03859		2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON SVS HAMILTON AFB MOWAT, CA				ATTN: DAN BUSHWELL			
4. Generator's Phone ((310) 342-9858)							
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS / Hoyt		6. US EPA ID Number CAD98252343		A. State Transporter's ID (925) 634-6850		B. Transporter 1 Phone	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address ALTA MOUNT LANDFILL 10840 ALTA MOUNT PASS ROAD LIVERMORE, CA 94550				10. US EPA ID Number CAD981382732		E. State Facility's ID	
				F. Facility's Phone (925) 449-6349			
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
a. NOV HAS SOIL, (pf:)				No. Type		00018	Y
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above i. 55098900 ii. iii. iv.				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JUNE 583-018 PHS 09-33859							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 10 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Louy Sainz</i>		Date Month Day Year 10 10 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature		Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556308	Manifest Document No. 04859	2. Page 1 of 1
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA		ATTN: DAN BUSHWELL		
4. Generator's Phone (310) 342-9858				
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS.	6. US EPA ID Number CAD98252343	A. State Transporter's ID		
		B. Transporter 1 Phone (925) 634-6850		
7. Transporter 2 Company Name	8. US EPA ID Number	C. State Transporter's ID		
		D. Transporter 2 Phone		
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CAD981382732		E. State Facility's ID
		F. Facility's Phone (925) 449-6349		

11. WASTE DESCRIPTION	12. Containers		13. Total Quantity	14. Unit Wt./Vol.
	No.	Type		
a. TOP HAZ SOIL, (pf:)	001	DT	000.18	Y
b.				
c.				
d.				

G. Additional Descriptions for Materials Listed Above 11a. 55098900 11b. 11c. 11d.	H. Handling Codes for Wastes Listed Above
---	---

15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 BILLARD JOB# 583-018 POC# 09-33859
--



16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name EDWARD KELLER	Signature <i>Edward Keller</i>	Date Month Day Year 10 10 02
--	-----------------------------------	---

17. Transporter 1 Acknowledgement of Receipt of Materials		
Printed/Typed Name CYNTHIA WALLACE	Signature <i>Cynthia Wallace</i>	Date Month Day Year 10 10 02

18. Transporter 2 Acknowledgement of Receipt of Materials		
Printed/Typed Name	Signature	Date Month Day Year

19. Discrepancy Indication Space		
----------------------------------	--	--

20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.		
Printed/Typed Name	Signature	Date Month Day Year

GENERATOR'S CERTIFICATION

TRANSPORTER'S CERTIFICATION

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. MAIL: CA0000556308		Manifest Document No. 02859	2. Page 1 of 1
3. Generator Name and Mailing Address WILLIARD ENVIRONMENTAL SVCS 10840 ALTAMONT PASS ROAD LIVERMORE, CA		4. Generator's Phone (925) 442-9858		ATTN: DAW BUSHNELL	
5. Transporter 1 Company Name BILLARD ENVIRONMENTAL SVCS / Hoyt		6. US EPA ID Number CA D 9 8 2 5 2 3 4 3		A. State Transporter's ID (925) 634-6850	
7. Transporter 2 Company Name HOYT TRANSPORTATION INC		8. US EPA ID Number CA D 9 8 1 4 2 5 8 5 3		B. Transporter 1 Phone	
9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA D 9 8 1 3 8 2 7 3 2		C. State Transporter's ID	
				D. Transporter 2 Phone 909-734-3191	
				E. State Facility's ID	
				F. Facility's Phone (925) 449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit
a. NON HAZ SULL, (PE:)			No. Type		Unit
			001 01	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 55098900			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 WILLIARD JOB# 583-018 PO# 09-33859					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name EDWARD KELLER		Signature <i>[Signature]</i>		Date 10/10/07	
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name Robert L. Moore		Signature <i>[Signature]</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature <i>[Signature]</i>	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name		Signature		Date	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA0000556305		Manifest Document No. 01859	2. Page 1 of 1	
3. Generator's Name and Mailing Address HAMILTON AFB HAMILTON AFB MOWAT, CA						
4. Generator's Phone ((310) 342-9858)						
5. Transporter 1 Company Name DILLARD ENVIRONMENTAL SVCS.		6. US EPA ID Number CA D 9 8 2 5 2 3 4 3		A. State Transporter's ID		
				B. Transporter 1 Phone (925) 634-6850		
7. Transporter 2 Company Name Hoyt Transportation INC.		8. US EPA ID Number CA D 9 8 1 4 2 5 8 5 3		C. State Transporter's ID		
				D. Transporter 2 Phone 1-909-774-3191		
9. Designated Facility Name and Site Address ALTAHONT LANDFILL 10840 ALTAHONT PASS ROAD LIVERMORE, CA 94550		10. US EPA ID Number CA D 9 8 1 3 8 2 7 3 2		E. State Facility's ID		
				F. Facility's Phone (925) 449-6349		
11. WASTE DESCRIPTION a. NOV HAS SOIL, (pF:) b. c. d.			12. Containers		13. Total Quantity	14. Unit Wt./Vol.
			No.	Type		
			001	DT	00018	Y
G. Additional Descriptions for Materials Listed Above IIa. 55098900 IIb. IIc. II d.				H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Emergency Contact (925) 634-6850 DILLARD JOB# 583-018 POC 09-33859						
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.						
Printed/Typed Name EDWARD KELLER				Signature <i>Edward Keller</i>		Date Month Day Year 10 10 02
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>[Signature]</i>		Date Month Day Year 10 10 02
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature <i>Beau T. Frantz</i>		Date Month Day Year 10 10 02
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature		Date Month Day Year
Printed/Typed Name				Signature		Date Month Day Year

Class III Manifests

**NON-HAZARDOUS
WASTE MANIFEST**

1. Generator's US EPA ID No.
CA000556308

Manifest Document No.
01031

2. Page 1
of 1

Generator's Name and Mailing Address
**Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949**

Non-Haz Man# **01031**
NR

4. Generator's Phone (415) **833-6386** Attn: **Ed Keller**

5. Transporter 1 Company Name
Cummings

6. US EPA ID Number
CAD981435621

A. Transporter's Phone
661 387 1842

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address
**Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550**

10. US EPA ID Number
CAD981392732

C. Facility's Phone
925-449-6349

11. Waste Shipping Name and Description

12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
--------------------	------	--------------------	-----------------

a. **Non-hazardous waste solid (non-regulated soils)**

001	DT	00018	Y
------------	-----------	--------------	----------

b.

--	--	--	--

c.

--	--	--	--

d.

--	--	--	--

Additional Descriptions for Materials Listed Above
11a. 1xEnd Dump. Bulk. Profile# **5110800**
Transporter Co: **Dillard Cummings** (Delete non-applicable) **+ # 76**
Class 3 Soils

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
Caution: Wear appropriate protective clothing and respiratory protection when handling.
All Volumes are Estimated
Site pick up address: **Hamilton Airfield Novato CA**

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name
Ed Keller

Signature
Month **10** Day **17** Year **02**

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name
Clifford Fretwell

Signature
Month **10** Day **17** Year **02**

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature
Month . Day . Year .

19. Discrepancy Indication Space

Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature
Month . Day . Year .

TRANSPORTER #1

GENERATOR

TRANSPORTER

FACILITY

Y

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.
CA000556308

Manifest Document No.
01030

2. Page 1 of 1

3. Generator's Name and Mailing Address
**Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949**

Non-Haz Man# **01030**

4. Generator's Phone (415) **883-6386** Attn: **Ed Keller**

NR

5. Transporter 1 Company Name
Cummins Bros

6. US EPA ID Number
CAD981435621

A. Transporter's Phone
661 387 1842

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address
**Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550**

10. US EPA ID Number
CAD981392732

C. Facility's Phone
925-449-6349

11. Waste Shipping Name and Description
Class 3 Soils

12. Containers
No. Type

13. Total Quantity

14. Unit Wt/Vol

a. Non-hazardous waste solid (non-regulated soils)

001 DT

00018

Y

b.

c.

d.

Additional Descriptions for Materials Listed Above
1 a. 1x End Dump, Bulk, Profile# **55110800**
Transporter Co.: **Dillard Cummings** (Delete non-applicable)
Class 3 Soils **#45**

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
Caution: Wear appropriate protective clothing and respiratory protection when handling.
All Volumes are Estimated
Site pick up address **Hamilton Airfield Novato CA**

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name
Ed Keller

Signature
Month Day Year
10 16 02

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name
Dale Jamison

Signature
Month Day Year
10 16 02

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature
Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature
Month Day Year

GENERATOR

TRANSPORTER

FACI

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.
CA000556308

Manifest Document No.
01029

2. Page 1 of 1

3. Generator's Name and Mailing Address
Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949

Non-Haz Man# **01029**

4. Generator's Phone (**415 883-6386**) Attn: **Ed Keller**

NR

5. Transporter 1 Company Name
Cummings

6. US EPA ID Number
CAD981435621

A. Transporter's Phone
661 387 1842

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address
Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550

10. US EPA ID Number
CAD981392732

C. Facility's Phone
925-449-6349

11. Waste Shipping Name and Description

12. Containers
No. Type

13. Total Quantity

14. Unit Wt/Val

a. Non-hazardous waste solid (non-regulated soils)

001 DT

00018

Y

b.

c.

d.

Additional Descriptions for Materials Listed Above

11a. 1xEnd Dump, Bulk, Profile# **55110800**
Transporter Co.: Dillard **Cummings** (Delete non-applicable) **T#76**
Class 3 Soils

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

Caution: Wear appropriate protective clothing and respiratory protection when handling.
All Volumes are Estimated
Site pick up address: **Hamilton Airfield Novato CA**

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name
Ed Keller

Signature
Month Day Year
10/16/02

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name
Clifford Fretwell

Signature
Month Day Year
10/16/02

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature
Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature
Month Day Year

TRANSPORTER #1

GENERATOR

TRANSPORTER

FACI

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.
CA000556308

Manifest Document No.
01028

2. Page 1 of 1

Generator's Name and Mailing Address
Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949
4. Generator's Phone (415) 883-6385 Attn: Ed Keller

Non-Haz Man# 01028
NR

5. Transporter 1 Company Name
Cummings
6. US EPA ID Number
CAD78143962

A. Transporter's Phone
661 387 1842

7. Transporter 2 Company Name
.....
8. US EPA ID Number
.....

B. Transporter's Phone
.....

9. Designated Facility Name and Site Address
Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550
10. US EPA ID Number
CAD981392732

C. Facility's Phone
925-449-6349

11. Waste Shipping Name and Description

12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
001	DT	00018	Y
..	
..	
..	

a. Non-hazardous waste solid (non-regulated soils)

b.

c.

d.

Additional Descriptions for Materials Listed Above
11a. 1X End Dump, Bulk, Profile# 55110800
Transporter Co. Dillard (Zummins) (Delete non-applicable) T # 77
Class 3 Soils

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

Caution: Wear appropriate protective clothing and respiratory protection when handling.
All Volumes are Estimated
Site pick-up address: Hamilton Airfield, Novato, CA

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name
Ed Keller

Signature
Month Day Year
11.01.02

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name
Robert D. Cantore

Signature
Month Day Year
11.01.02

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature
Month Day Year

19. Discrepancy Indication Space

Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature
Month Day Year

TRANSPORTER #2

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.
CA000556308

Manifest Document No.
01027

2. Page 1 of 1

3. Generator's Name and Mailing Address
Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949

Non-Haz Man# **01027**

4. Generator's Phone (**415 883-6386**) Attn: **Ed Keller**

NR

5. Transporter 1 Company Name
Cummings

6. US EPA ID Number
CA.D98.1.4.35.6.21

A. Transporter's Phone
661 387 1842

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address
Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550

10. US EPA ID Number
CA.D98.1.3.9.2.7.3.2

C. Facility's Phone
925-449-6349

11. Waste Shipping Name and Description

12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
--------------------	------	--------------------	-----------------

a. **Non-hazardous waste solid (non-regulated soils)**

001	DT	00018	Y
------------	-----------	--------------	----------

b.

.	.	.	.
---	---	---	---

c.

.	.	.	.
---	---	---	---

d.

.	.	.	.
---	---	---	---

e.

.	.	.	.
---	---	---	---

f.

.	.	.	.
---	---	---	---

Additional Descriptions for Materials Listed Above
11a. 1xEnd Dump Bulk Profile# **55110800**
Transporter Co. **Oillard Cummings** (Delete non-applicable)
Class 3 Soils **1# 72**

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
Caution: Wear appropriate protective clothing and respiratory protection when handling.
All Volumes are Estimated
Site pick up address: **Hamilton Airfield Novato CA**

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name
Ed Keller

Signature
[Signature] Month Day Year **10 15 02**

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name
Mike Basso

Signature
[Signature] Month Day Year **10 16 02**

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature
Month Day Year

19. Discrepancy Indication Space

Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature
Month Day Year

TRANSPORTER #1

GENERATOR
TRANSPORTER
FACILITY

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.
. C.A.00556308

Manifest Document No.
01026

2. Page 1 of 1

3. Generator's Name and Mailing Address
Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949

4. Generator's Phone (415) **883-6386** Attn: **Ed Keller**

Non-Haz Man# **01026**

NR

5. Transporter 1 Company Name
Cummings

6. US EPA ID Number
C.A.D.98-1-4-3-5-6-2-1

A. Transporter's Phone
6613871842

B. Transporter's Phone

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address
Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550

C. Facility's Phone
925-449-6349

11. Waste Shipping Name and Description

a. **Non-hazardous waste solid (non-regulated soils)**

b.

c.

d.

12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
001	DT	00018	Y

Additional Descriptions for Materials Listed Above

11a. 1x End Dump. Bulk. Profile# **55110800**

Transporter Co.: Dillard **Cummings** (Delete non-applicable)

Class 3 Soils **T# 37**

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

Caution: Wear appropriate protective clothing and respiratory protection when handling.

All Volumes are Estimated

Site pick up address: **Hamilton Airfield Novato CA**

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name: **Ed Keller** Signature: _____ Month Day Year: **11-01-02**

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: **Gary Flowers** Signature: _____ Month Day Year: **11-01-02**

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name: _____ Signature: _____ Month Day Year: _____

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: _____ Signature: _____ Month Day Year: _____

GENERATOR
TRANSPORTER
FACILITY

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.
CA000556308

Manifest Document No.
01025

2. Page 1 of 1

Generator's Name and Mailing Address

**Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949**

Non-Haz Man# **01025**

4. Generator's Phone (415 883-6386 Attn: Ed Keller

NR

5. Transporter 1 Company Name

Cummings / RJM

6. US EPA ID Number

CA D981435621

A. Transporter's Phone

661 387 1842

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address

**Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550**

10. US EPA ID Number

CA D981392732

C. Facility's Phone

925-449-6349

11. Waste Shipping Name and Description

a. Non-hazardous waste solid (non-regulated soils)

12. Containers

No. Type

13. Total Quantity

14. Unit Wt/Vol

001

DT

00018

Y

Additional Descriptions for Materials Listed Above

11a. 1xEnd Dump, Bulk, Profile# *55110800*

E. Handling Codes for Wastes Listed Above

Transporter Co.: Dillard *Cummings* (Delete non-applicable)
Class 3 Soils *CA 193206*

15. Special Handling Instructions and Additional Information

Caution: Wear appropriate protective clothing and respiratory protection when handling

All Volumes are Estimated

Site pick up address: **Hamilton Airfield Novato CA**

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name

Ed Keller

Signature

Month Day Year

10/6/02

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

REDEN ROSA

Signature

J. ROSA

Month Day Year

10/6/02

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

1. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month Day Year

TRANSPORTER #1

GENERATOR

TRANSPORTER

FACILITY

**NON-HAZARDOUS
WASTE MANIFEST**

1. Generator's US EPA ID No.
. C A 0 0 5 5 6 3 0 8 .

Manifest Document No.
01024

2. Page 1 of 1

Generator's Name and Mailing Address
**Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949**

Non-Haz Man# **01024**
NR

4. Generator's Phone (**415 883-6386**) Attn: **Ed Keller**

5. Transporter 1 Company Name
Cummings

6. US EPA ID Number **621**
CA.D.9.8.1.4.35.1

A. Transporter's Phone
661 387 1842

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address
**Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550**

10. US EPA ID Number
C.A.D.9.8.1.3.9.2.7.3.2

C. Facility's Phone
925-449-6349

11. Waste Shipping Name and Description

12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
--------------------	------	--------------------	-----------------

a. **Non-hazardous waste solid (non-regulated soils)**

001	DT	.00018	Y
------------	-----------	---------------	----------

b.
c.
d.

Additional Descriptions for Materials Listed Above
11a. 1xEnd Dump, Bulk, Profile# **54110800**
Transporter Co.: Dillard **Cummings** (Delete non-applicable)
Class 3 Soils **T # 2**

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
Caution: Wear appropriate protective clothing and respiratory protection when handling.
All Volumes are Estimated
Site pick up address: **Hamilton Airfield Novato CA**

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name
Ed Keller

Signature
Ed Keller Month Day Year **10/6/02**

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name
SCOTT BALLARD

Signature
Scott Ballard Month Day Year **10/6/02**

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature Month Day Year

19. Discrepancy Indication Space

Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature Month Day Year

GENERATOR

TRANSPORTER

FACILITY

**NON-HAZARDOUS
WASTE MANIFEST**

1. Generator's US EPA ID No.
CA00556308

Manifest Document No.
01023

2. Page 1
of 1

Generator's Name and Mailing Address
**Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949**

Non-Haz Man# **01023**

4. Generator's Phone (**415 883-6386**) Attn: **Ed Keller**

NR

5. Transporter 1 Company Name **Cummings** 6. US EPA ID Number **KAD981435621**

A. Transporter's Phone **661 387 1842**

7. Transporter 2 Company Name 8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address
**Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550**

10. US EPA ID Number
CAD981392732

C. Facility's Phone
925-449-6349

11. Waste Shipping Name and Description

12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
--------------------	------	--------------------	-----------------

a. **Non-hazardous waste solid (non-regulated soils)**

001	DT	00018	Y
------------	-----------	--------------	----------

b.
c.
d.

Additional Descriptions for Materials Listed Above
11a. 1xEnd Dump, Bulk, Profile# **55110800**
Transporter Co.: Dillard **Cummings** (Delete non-applicable) **T# 44**
Class 3 Soils

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

Caution: Wear appropriate protective clothing and respiratory protection when handling.
All Volumes are Estimated
Site pick up address: **Hamilton Airfield Novato CA**

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name
Ed Keller

Signature _____ Month Day Year **10/16/02**

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name
MARK D. KIRK

Signature *Mark D. Kirk* Month Day Year **10/16/02**

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature _____ Month Day Year

19. Discrepancy Indication Space

Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature _____ Month Day Year

TRANSPORTER #1

GENERATOR
TRANSPORTER
FACILITY

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.
CA000556308

Manifest Document No.
01022

2. Page 1 of 1

3. Generator's Name and Mailing Address
**Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949**

Non-Haz Man# **01022**
NR

4. Generator's Phone (**415 883-6386**) Attn: **Ed Keller**

5. Transporter 1 Company Name **Cummings** 6. US EPA ID Number **CAD981435621**

A. Transporter's Phone **6613871842**

7. Transporter 2 Company Name 8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address
**Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550**

10. US EPA ID Number **CAD981392732**
C. Facility's Phone **925-449-6349**

11. Waste Shipping Name and Description

12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
--------------------	------	--------------------	-----------------

a. Non-hazardous waste solid (non-regulated soils)

001	DT	00018	Y
------------	-----------	--------------	----------

b.

.
-----------	-----------	-----------	-----------

c.

.
-----------	-----------	-----------	-----------

d.

.
-----------	-----------	-----------	-----------

Additional Descriptions for Materials Listed Above
11a. 1xEnd Dump, Bulk, Profile# **59110800**
Transporter Co.: Dillard **Cummings** (Delete non-applicable)
Class 3 Soils **#34**

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
Caution: Wear appropriate protective clothing and respiratory protection when handling.
All Volumes are Estimated
Site pick up address: **Hamilton Airfield Novato CA**

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name
Ed Keller

Signature _____ Month Day Year **10 16 02**

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name
Gino Lombardo

Signature _____ Month Day Year **10 16 02**

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name _____

Signature _____ Month Day Year

19. Discrepancy Indication Space

9. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name _____

Signature _____ Month Day Year

GENERATOR
TRANSPORTER
FACILITY

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.
CA000556308

Manifest Document No.
01021

2. Page 1 of 1

Non-Haz Man# **01021**

Generator's Name and Mailing Address
**Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949**

4. Generator's Phone (415) **883-6386** Attn: **Ed Keller**

NR

5. Transporter 1 Company Name

6. US EPA ID Number

A. Transporter's Phone

Cummings

CAD981436621

661387 1842

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address

10. US EPA ID Number

C. Facility's Phone

**Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550**

CAD981392732

925-449-6349

11. Waste Shipping Name and Description

12. Containers

13. Total Quantity

14. Unit Wt/Vol

a. Non-hazardous waste solid (non-regulated soils)

001

DT

00018

Y

Additional Descriptions for Materials Listed Above

E. Handling Codes for Wastes Listed Above

11a. 1xEnd Dump. Bulk. Profile# **55110800**

Transporter Co.: Dillard *Cummings* (Delete non-applicable) **T# 23**
Class 3 Soils

15. Special Handling Instructions and Additional Information

Caution: Wear appropriate protective clothing and respiratory protection when handling.
All Volumes are Estimated
Site pick up address: **Hamilton Airfield Novato CA**

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name

Signature

Month Day Year

Ed Keller

10/16/02

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

Jorge CETA

10/16/02

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

2. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month Day Year

TRANSPORTER #1

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.
CA000556308

Manifest Document No.
01020

2. Page 1 of 1

Generator's Name and Mailing Address
**Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949**

Non-Haz Man# **01020**

4. Generator's Phone (**415 883-6386**) Attn: **Ed Keller**

NR

5. Transporter 1 Company Name
Cummings

6. US EPA ID Number
C.A.D. 98.1.4.3.5.6.21

A. Transporter's Phone
661-387-1847

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address
**Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550**

10. US EPA ID Number
C.A.D. 98.1.3.9.2.7.3.2

C. Facility's Phone
925-449-6349

11. Waste Shipping Name and Description

12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
--------------------	------	--------------------	-----------------

a. Non-hazardous waste solid (non-regulated soils)

001	DT	00018	Y
------------	-----------	--------------	----------

GENERATOR

Additional Descriptions for Materials Listed Above
11a. 1x End Dump, Bulk, Profile# **55110800**

E. Handling Codes for Wastes Listed Above

Transporter Co.: Dillard **Cummings** (Delete non-applicable)
Class 3 Soils **T # 40**

15. Special Handling Instructions and Additional Information

Caution: Wear appropriate protective clothing and respiratory protection when handling.

All Volumes are Estimated

Site pick up address: **Hamilton Airfield Novato CA**

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name

Ed Keller

Signature

Month Day Year


10/15/02

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

DAVE EVANUQUILTA

Signature



Month Day Year

1-9-02

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month Day Year

TRANSPORTER

FACILITY

TRANSPORTER #1

**NON-HAZARDOUS
WASTE MANIFEST**

1. Generator's US EPA ID No.
CA000556308

Manifest Document No.
01019

2. Page 1
of 1

Generator's Name and Mailing Address

**Hamilton Army Airfield
1 Burma Road, Bldg 82 Novato CA 94949**

Non-Haz Man# **01019**

4. Generator's Phone (**415 883-6386**) Attn: **Ed Keller**

NR

5. Transporter 1 Company Name

Cummings

6. US EPA ID Number

CAD981435621

A. Transporter's Phone

661 387 1842

7. Transporter 2 Company Name

8. US EPA ID Number

B. Transporter's Phone

9. Designated Facility Name and Site Address

**Altamont Landfill & Resource Recovery Facility
10480 Altamont Pass Road
Livermore CA 94550**

10. US EPA ID Number

CAD981392732

C. Facility's Phone

925-449-6349

11. Waste Shipping Name and Description

a. **Non-hazardous waste solid (non-regulated soils)**

12. Containers
No. Type

001 DT

13. Total
Quantity

00018

14. Unit
Wt/Vol

Y

Additional Descriptions for Materials Listed Above

11a. 1xEnd Dump, Bulk, Profile# **55110800**

Transporter Co.: Dillard **Cummings** (Delete non-applicable) **#45**
Class 3 Soils

E. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

Caution: Wear appropriate protective clothing and respiratory protection when handling.

All Volumes are Estimated

Site pick up address: **Hamilton Airfield Novato CA**

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name

Ed Keller

Signature

Month Day Year

10/16/02

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Dale Jamison

Signature

Month Day Year

10/16/02

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month Day Year

TRANSPORTER #1

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000555308		Manifest Document No. 01018	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94549				Non-Haz Manifest NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID 387	
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CA0981436621		B. Transporter 1 Phone 661-387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CA0981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (nonregulated solids)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1x End Dump Bulk Prolined 55113800 Transporter Co. (Liaison) Cummings 76 Class 3 Soils T# 76			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling All Volumes are Estimated Site pick up address: Hamilton Airfield, Novato, CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Ed Keller				Signature	
				Date 10/16/02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name PLAIRD FECTWELL				Signature <i>Clifford Fectwell</i>	
				Date 10/16/02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Signature	
				Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

LIABILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01017	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Cummins		6. US EPA ID Number CAD 918 43502		B. Transporter 1 Phone 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD 981 392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (non-regulated soils)			No. 001	Type DT	00018
b.					Y
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55110800 Transporter Co. (Dillard Cummings) 77 Class 3 Soils T# 77			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Ed Keller			Signature		Date Month 10 Day 16 Year 02
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature		Date
Printed/Typed Name ROGER D LAWRENCE			Signature		Month 10 Day 16 Year 02
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date
Printed/Typed Name			Signature		Month Day Year
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01016	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man#	
4. Generator's Phone (415 883-6386) Attn: Ed Keller				NR	
5. Transporter 1 Company Name <i>Cummins</i>		6. US EPA ID Number CAD 981435621		A. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 661 3187 1842	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				E. State Facility's ID	
10. US EPA ID Number CAD981392732				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (non-regulated soils)			No. Type		
			001 DT	00018	Y
b.					
c.					
d.					
11a. Additional Descriptions for Materials Listed Above 1xEnd Dump. Bulk. Profile# 55110800 Transporter Co. (Dillard / Cummings) 72 Class 3 Soils ↑ # 72			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Ed Keller				Date Month Day Year 10 16 02	
Signature				Date Month Day Year 10 16 02	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <i>Mike Bass Sr</i>				Date Month Day Year 10 16 02	
Signature				Date Month Day Year	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name				Date Month Day Year	
Signature				Date Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date Month Day Year	
Signature				Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01015	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Cummings/RJM		6. US EPA ID Number CAD98143562		B. Transporter 1 Phone 661 3871842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (non-regulated soils)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
3. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk. Profile# 55110200 Transporter Co. (Dillard <u>Cummings</u>) Class 3 Soils CA193206			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Ed Keller				Signature <i>[Signature]</i>	
				Date 10 16 02	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name ROSA				Signature <i>[Signature]</i>	
				Date 10 16 02	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Signature	
				Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01014	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CA D981435621		B. Transporter 1 Phone 661 3871842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (non-regulated soils)			No. Type		
			001 DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk. Profile# 55110800 2 Transporter Co. (Dillard / Cummings) Class 3 Soils T # 2			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Ed Keller				Signature	
				Date Month Day Year 10 16 02	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name SCOTT BALLARD				Signature Scott Ballard	
				Date Month Day Year 10 16 02	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Signature	
				Date Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

GENERATOR

TRANSPORTER

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308	Manifest Document No. 01013	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949			Non Haz Man# NR	
4. Generator's Phone (415 883-6386) Attn: Ed Keller		6. US EPA ID Number CA0981435621	A. State Transporter's ID	
5. Transporter 1 Company Name Cummings		8. US EPA ID Number	B. Transporter 1 Phone 661 387 1842	
7. Transporter 2 Company Name		10. US EPA ID Number	C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		11. WASTE DESCRIPTION	D. Transporter 2 Phone	
		12. Containers	E. State Facility's ID	
		No.	F. Facility's Phone	
		Type	925-449-6349	
		13. Total Quantity		
		14. Unit Wt./Vol.		
a. Non-hazardous waste solid (non-regulated soils)		001	DT	00018
b.				Y
c.				
d.				
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk. Profile# 55110800 Transporter Co. (Dillard <u>Cummings</u>) Class 3 Soils T # 37		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name Ed Keller		Signature		Date 10 16 02
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name Gary Flowers		Signature <i>Gary Flowers</i>		Date 10 16 02
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature		Date
19. Discrepancy Indication Space				
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature		Date

GENERATOR

TRANSPORTER

FACILITY

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01012	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CAD 981435621		B. Transporter 1 Phone 661 387 1342	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD 981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (non-regulated soils)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
3. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk. Profile# <i>59110200</i> Transporter Co. (Dillard <i>Cummings</i>) Class 3 Soils <i>45</i> <i>7# 45</i>			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Ed Keller				Signature	
				Date 10/16/02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name Dale Jamison		Signature <i>Dale Jamison</i>		Date 10/16/02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308	Manifest Document No. 01011	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949			Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		
5. Transporter 1 Company Name <i>Cummings</i>	6. US EPA ID Number CAD981435621	A. State Transporter's ID		
7. Transporter 2 Company Name		B. Transporter 1 Phone 661 387 1842		
8. US EPA ID Number		C. State Transporter's ID		
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		D. Transporter 2 Phone		
10. US EPA ID Number CAD981392732		E. State Facility's ID		
11. WASTE DESCRIPTION		F. Facility's Phone 925-449-6349		
a. Non-hazardous waste solid (non-regulated soils)		12. Containers No. 001 Type DT	13. Total Quantity 00018	14. Unit Wt./Vol. Y
b.				
c.				
d.				
3. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# <i>55110800</i> Transporter Co. (Dillard / <u>Cummings</u>) <i>34</i> Class 3 Soils <i>T# 34</i>		H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA				
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.				
Printed/Typed Name Ed Keller		Signature		Date Month 10 Day 16 Year 02
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name <i>Gino Lomonaco</i>		Signature <i>Gino Lomonaco</i>		Date Month 10 Day 16 Year 02
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name <i>Gino Lomonaco</i>		Signature		Date
19. Discrepancy Indication Space				
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				
Printed/Typed Name		Signature		Date Month Day Year

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type. (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01010	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CAD 981435621		B. Transporter 1 Phone 661 397 1812	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD 981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity
			No.	Type	14. Unit Wt./Vol.
a. Non-hazardous waste solid (non-regulated soils)			001	DT	00018
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# <i>550 55110800</i> Transporter Co. (Dillard <i>Cummings</i>) Class 3 Soils <i>T# 23</i>				H. Handling Codes for Wastes Listed Above	
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Ed Keller				Signature	
				Date 10/15/02	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name JORGE CEJA				Signature <i>Jorge Ceja</i>	
				Date 10/16/02	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name				Signature	
				Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

LITTY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01009		2. Page 1 of 1					
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR							
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID							
5. Transporter 1 Company Name Cummings		6. US EPA ID Number CAD981435621		B. Transporter 1 Phone 6613871842							
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID							
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone		E. State Facility's ID					
				F. Facility's Phone 925-449-6349							
11. WASTE DESCRIPTION a. Non-hazardous waste solid (non-regulated soils)				12. Containers		13. Total Quantity					
				No.		Type		Unit			
								Wt./Vol.			
				001		DT		00018		Y	
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55110800 Transporter Co (Dillard, <u>Cummings</u>) 40 Class 3 Soils T#40				H. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA											
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.											
Printed/Typed Name Ed Keller				Signature		Date Month Day Year 10 16 02					
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature		Date					
Printed/Typed Name DAVE EVANKOVICH				Signature		Month Day Year 10 16 02					
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date					
Printed/Typed Name				Signature		Month Day Year					
19. Discrepancy Indication Space											
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.											
Printed/Typed Name				Signature		Date Month Day Year					

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01008	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CAD 981426671		B. Transporter 1 Phone 6613871542	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (non-regulated soils)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
11a. Additional Descriptions for Materials Listed Above 1x End Dump Bulk Profile# 55110300 Transporter Co. (Dillard / Cummings) 77 Class 3 Soils TH 77			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Ed Keller				Signature	
				Date 10/15/02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name <i>Robert D. Lawrence</i>		Signature <i>Robert D. Lawrence</i>		Date 10/16/02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01007	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID #	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CAD981435621		B. Transporter 1 Phone 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (non-regulated soils)			No. 001	Type DT	00018
b.					Y
c.					
d.					
3. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 5511080011			H. Handling Codes for Wastes Listed Above		
Transporter Co. (Dillard / <u>Cummings</u>) 76 Class 3 Soils T# 76					
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Ed Keller				Signature	
				Date 10 13 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name CLIFFORD FRETWELL		Signature <i>Clifford Fretwell</i>		Date 10 15 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Date	
19. Discrepancy Indication Space					
20. Facility Owner or Operator, Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01006		2. Page 1 of 1	
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR			
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID		B. Transporter 1 Phone 661 387 1842	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CAD 981435621		C. State Transporter's ID		D. Transporter 2 Phone	
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Facility's ID		F. Facility's Phone 925-449-6349	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550				10. US EPA ID Number CAD981392732			
11. WASTE DESCRIPTION a. Non-hazardous waste solid (non-regulated soils)				12. Containers		13. Total Quantity	14. Unit Wt./Vol.
				No. Type			
				001 DT		00018	Y
				b.			
				c.			
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55110800 III Transporter Co. (Dillard / <u>Cummings</u>) 44 Class 3 Soils # 44				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Ed Keller				Signature		Date Month Day Year 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name MARK D. KICK				Signature <i>Mark D. Kick</i>		Month Day Year 10 15 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FA

CITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01005	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name <i>Cummings</i>		6. US EPA ID Number CAD 981435621		B. Transporter 1 Phone 661 387 1842	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (non-regulated soils)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 5511030011 Transporter Co. (Dillard / <i>Cummings</i>) : 72 Class 3 Soils 7 # 72			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Ed Keller			Signature	Date Month Day Year 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials			Date		
Printed/Typed Name <i>Mike Basse Sr</i>			Signature <i>[Signature]</i>	Month Day Year 10 15 02	
18. Transporter 2 Acknowledgement of Receipt of Materials			Date		
Printed/Typed Name			Signature	Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature	Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01004	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard		6. US EPA ID Number ICAD982523433		B. Transporter 1 Phone 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (non-regulated soils)			No. 001 Type DT	00018	Y
b.					
c.					
d.					
3. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump. Bulk. Profile# 55110500 Transporter Co. (Dillard / Cummings) 691 Class 3 Soils ✓ # 691			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Ed Keller				Signature	
				Date Month Day Year 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name JAMES COLEMAN		Signature		Date Month Day Year 10 15 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Signature	
				Date Month Day Year	

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01003	2. Page 1 of 1
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR	
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID	
5. Transporter 1 Company Name Dillard		6. US EPA ID Number CAD 982523433		B. Transporter 1 Phone 925 634 6850	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD 981392732		D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone 925-449-6349	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a. Non-hazardous waste solid (non-regulated soils)			No. 001	Type DT	00018
b.					Y
c.					
d.					
11a. 1xEnd Dump, Bulk, Profile# 55110500			H. Handling Codes for Wastes Listed Above		
Transporter Co. (Dillard Cummings) : 091					
Class 3 Soils					
T# 091					
15. Special Handling Instructions and Additional Information					
Caution: Wear appropriate protective clothing and respiratory protection when handling.					
All Volumes are Estimated					
Site pick up address: Hamilton Airfield Novato CA					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Ed Keller				Date	
Signature				Month Day Year	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name Rudolph V. Zuo				Month Day Year	
Signature				10 15 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Month Day Year	
Signature				Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name				Date	
Signature				Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01002		2. Page 1 of 1	
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR			
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID			
5. Transporter 1 Company Name Dillard		6. US EPA ID Number CAD 982523433		B. Transporter 1 Phone 9256346850			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID			
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD981392732		D. Transporter 2 Phone		E. State Facility's ID	
				F. Facility's Phone 925-449-6349			
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity	14. Unit Wt./Vol.	
a. Non-hazardous waste solid (non-regulated soils)			001 DT		00018	Y	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55110500 Transporter Co. (Dillard / Cummings) : 191 Class 3 Soils				H. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Ed Keller				Signature		Date Month Day Year 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name Steve M. Turner				Signature <i>Steve M. Turner</i>		Date Month Day Year 10 15 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Date Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

FACILITY

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CA000556308		Manifest Document No. 01001		2. Page 1 of 1	
3. Generator's Name and Mailing Address Hamilton Army Airfield 1 Burma Road, Bldg 82 Novato CA 94949				Non-Haz Man# NR			
4. Generator's Phone (415 883-6386)		Attn: Ed Keller		A. State Transporter's ID			
5. Transporter 1 Company Name Dillard / Atchley		6. US EPA ID Number CAD 982523433		B. Transporter 1 Phone 925 634 6850			
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID			
9. Designated Facility Name and Site Address Altamont Landfill & Resource Recovery Facility 10480 Altamont Pass Road Livermore CA 94550		10. US EPA ID Number CAD 981392732		D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone 925-449-6349			
11. WASTE DESCRIPTION			12. Containers		13. Total Quantity	14. Unit Wt./Vol.	
a. Non-hazardous waste solid (non-regulated soils)			No. Type		00018	Y	
b.							
c.							
d. 55110500							
G. Additional Descriptions for Materials Listed Above 11a. 1xEnd Dump, Bulk, Profile# 55110500 Transporter Co. (Dillard / Cummings): Atchley Class 3 Soils			H. Handling Codes for Wastes Listed Above TH 105				
15. Special Handling Instructions and Additional Information Caution: Wear appropriate protective clothing and respiratory protection when handling. All Volumes are Estimated Site pick up address: Hamilton Airfield Novato CA							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Ed Keller				Signature		Date Month Day Year 10 15 02	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name Danny R Atchley				Signature <i>[Signature]</i>		Date Month Day Year 10 15 02	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Date Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date Month Day Year	

GENERATOR

TRANSPORTER

CITY

Waste Acceptance Forms

ALTAMONT LANDFILL WASTE ACCEPTANCE FORM

CUSTOMER: Cummings Transportation

CUSTOMER #: 0387262

GENERATOR: Hamilton Army Field

PROFILE #: 55034300

LIST WASTE SOURCE: (County/City Location) Novato

MATERIAL DESCRIPTION: CLASS II COVER SOIL

FLAG COLOR: YELLOW

The information listed above is necessary for acceptance of special waste at the Altamont Landfill.

- A copy of this form must be presented with each load to the Altamont Landfill scale house collector.
- This form is for Altamont Landfill waste tracking use and is not intended to serve as a customer shipping document.
- Drivers will receive a weight ticket for confirmation of disposal.
- An alternative shipping record may be used in lieu of this form if it includes the above information.
- If shipping form is a multiple part form, please notify landfill of which copies to return with the driver, if not otherwise noted on the form.

FOR ALTAMONT LANDFILL COLLECTOR USE ONLY:

FILL IN TAG# ASSOCIATED WITH LOAD (USE OUTBOUND# FOR UNTARED LOADS)

SCALE HOUSE TAG # - _____

DATE _____

TRUCK # _____

ALTAMONT LANDFILL WASTE ACCEPTANCE FORM **REVISED**

CUSTOMER: Cummings Transportation

CUSTOMER # 0387262

GENERATOR: Hamilton Army Airfield

PROFILE #: 55110800

LIST WASTE SOURCE: (County/City Location) Marin/Novato

MATERIAL DESCRIPTION: Class III Cover Soil

FLAG COLOR: Pink

The Information listed above is necessary for acceptance of special waste at the Altamont Landfill.

- A copy of this form must be presented with each load to the Altamont Landfill scale house collector.
- This form is for Altamont Landfill waste tracking use and is not intended to serve as a customer shipping document.
- Drivers will receive a weight ticket for confirmation of disposal.
- An alternative shipping record may be used in lieu of this form if it includes the above information.
- If shipping form is a multiple part form, please notify landfill of which copies to return with the driver, if not otherwise noted on the form.

FOR ALTAMONT LANDFILL COLLECTOR USE ONLY:

FILL IN TAG# ASSOCIATED WITH LOAD (USE OUTBOUND# FOR UNTARED LOADS)

SCALE HOUSE TAG # - _____

DATE _____

TRUCK # _____

ALTAMONT LANDFILL WASTE ACCEPTANCE FORM

CUSTOMER: DILLARD ENVIRONMENTAL

CUSTOMER #: 1892

GENERATOR: HAMILTON ARMY AIRFIELD

PROFILE #: 55098900

LIST WASTE SOURCE: (County/City Location) NOVATO

MATERIAL DESCRIPTION: CLASS II COVER SOIL

FLAG COLOR: YELLOW

The Information listed above is necessary for acceptance of special waste at the Altamont Landfill.

- A copy of this form must be presented with each load to the Altamont Landfill scale house collector.
- This form is for Altamont Landfill waste tracking use and is not intended to serve as a customer shipping document.
- Drivers will receive a weight ticket for confirmation of disposal.
- An alternative shipping record may be used in lieu of this form if it includes the above information.
- If shipping form is a multiple part form, please notify landfill of which copies to return with the driver, if not otherwise noted on the form.

FOR ALTAMONT LANDFILL COLLECTOR USE ONLY:

FILL IN TAG# ASSOCIATED WITH LOAD (USE OUTBOUND# FOR UNTARED LOADS)

SCALE HOUSE TAG # - _____

DATE _____

TRUCK # _____

ALTAMONT LANDFILL WASTE ACCEPTANCE FORM

CUSTOMER: Dillard Environmental
CUSTOMER # 0001892
GENERATOR: Hamilton Army Airfield
PROFILE #: 55110500
LIST WASTE SOURCE: (County/City Location) Marin/Novato
MATERIAL DESCRIPTION: Class III Cover Soil
FLAG COLOR: Pink

The Information listed above is necessary for acceptance of special waste at the Altamont Landfill

- A copy of this form must be presented with each load to the Altamont Landfill scale house collector.
- This form is for Altamont Landfill waste tracking use and is not intended to serve as a customer shipping document.
- Drivers will receive a weight ticket for confirmation of disposal.
- An alternative shipping record may be used in lieu of this form if it includes the above information.
- If shipping form is a multiple part form, please notify landfill of which copies to return with the driver, if not otherwise noted on the form.

FOR ALTAMONT LANDFILL COLLECTOR USE ONLY:

FILL IN TAG# ASSOCIATED WITH LOAD (USE OUTBOUND# FOR UNTARED LOADS)

SCALE HOUSE TAG # - _____

DATE _____

TRUCK # _____