

Kern River - right bank - Oildale  
Minimally Acceptable/ Active

Kern River - right bank - Oildale

Operations and Maintenance Manuals	A
Emergency Supplies and Equipment	A
Flood Preparedness and Training	A
Unwanted Vegetation Growth	U
Sod Cover	N/A
Encroachments	U
Closure Structures	N/A
Slope Stability	A
Erosion/Bank Caving	A
Settlement	A
Depressions/Rutting	M
Cracking	A
Animal Control	A
Culverts/Discharge Pipes	N/A
Riprap Revetments & Bank Protection	N/A
Revetments other than Riprap	N/A
Underseepage Relief Wells/Toe Drainage Systems	A
Seepage	A
<b>Overall Rating</b>	<b>M</b>

Item Rating Classification	Time to Fix Before Becoming Inactive
Likely to Prevent the system from performing as intended during the next flood event.	Red issues cause the system to become inactive immediately.
Serious deficiency noted in a past inspection has not been corrected within the established timelines.	Pink issues have already exceeded previous timeline for repair, causing the system to become inactive immediately.
Not likely to prevent the system from performing as intended during the next flood event.	2 years from date of this letter unless otherwise specified.

The worst rating is used to determine the overall segment and system ratings and PL 84-99 Rehabilitation Assistance Eligibility.