

**MA 09 - City of Sacramento, American River Left Bank Levee System  
Unacceptable-Inactive**

ARFCD - Unit 4, American River Left Bank  
ARFCD - Unit 5, Sacramento River  
City of Sacramento  
MA 09 - Sutterville Rd to Freeport  
MA 09 - Freeport to Hood  
MA 09 - Hood to Snodgrass Slough

Operations and Maintenance Manuals	M	M	M	M	A	A			
Emergency Supplies and Equipment	A	A	A	A	A	A			
Flood Preparedness and Training	A	A	A	A	A	A			
Unwanted Vegetation Growth	U	U	U	U	U	U			
Sod Cover	A	A	M	M	M	A			
Encroachments	U	U	U	U	U	U			
Closure Structures	N/A	N/A	N/A	N/A	N/A	N/A			
Slope Stability	M	A	M	M	M	M			
Erosion/Bank Caving	M	M	M	M	M	M			
Settlement	A	A	A	A	A	A			
Depressions/Rutting	M	A	A	M	A	A			
Cracking	A	A	A	A	A	A			
Animal Control	M	M	M	M	M	M			
Culverts/Discharge Pipes	N/A	N/A	N/A	N/A	N/A	N/A			
Riprap Revetments & Bank Protection	M	M	M	M	M	A			
Revetments other than Riprap	N/A	N/A	M	M	N/A	N/A			
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	N/A	N/A	N/A	N/A			
Seepage	A	A	A	A	A	A			
Flood Wall	U	N/A	U	A	N/A	N/A			

Segment & System Ratings/PL 84-99 Eligibility

Likely Prevents Performance In Next Flood Event

Serious deficiency noted in past inspections has not been corrected within the established timeframe

Not Likely to Prevent Performance In Next Flood Event

Legend

- A Acceptable
- M Minimally Acceptable
- U Unacceptable
- N/A Not Applicable

The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility

April 1, 2011