

RD 1000 - Natomas Unacceptable-Active								
	Unit 1, Sacramento River	Unit 2, American River	Unit 3 South, NEMDC	Unit 3 North, Cross Canal inflow	Unit 4, Natomas Cross Canal			
Operations and Maintenance Manuals	M	M	M	M	M			
Emergency Supplies and Equipment	A	A	A	A	A			
Flood Preparedness and Training	A	A	A	A	A			
Unwanted Vegetation Growth	U	U	U	U	U			
Sod Cover	A	A	A	A	A			
Encroachments	U	U	U	U	U			
Closure Structures	NA	NA	NA	NA	NA			
Slope Stability	M	A	M	A	M			
Erosion/Bank Caving	U	M	M	U	U			
Settlement	M	A	A	A	A			
Depressions/Rutting	A	A	M	M	A			
Cracking	M	A	M	A	A			
Animal Control	M	A	M	M	M			
Culverts/Discharge Pipes	NA	NA	NA	NA	NA			
Riprap Revetments & Bank Protection	M	NA	M	M	A			
Revetments other than Riprap	NA	NA	NA	NA	NA			
Underseepage Relief Wells/Toe Drainage Systems	NA	NA	NA	NA	NA			
Seepage	A	A	A	A	A			
Segment & System Ratings/PL 84-99 Eligibility						Legend		
Likely Prevents Performance In Next Flood Event						A	Acceptable	
Serious deficiency noted in past inspections has not been corrected within the established timeframe						M	Minimally Acceptable	
Likely Prevents Performance In Next Flood Event (Framework)						U	Unacceptable	
Not Likely to Prevent Performance In Next Flood Event						N/A	Not Applicable	
Not Likely to Prevent Performance In Next Flood Event (Framework)								
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility						July 6, 2010		