

RD 404 and Duck Creek right bank - Boggs Tract Unacceptable- Inactive	RD 404 - Unit 1 San Joaquin River Right Bank			RD 404 - Unit 2, French Camp Walker Slough			Duck Creek - Walker Slough right bank			
Operations and Maintenance Manuals	M	M	M							
Emergency Supplies and Equipment	M	M	M							
Flood Preparedness and Training	M	M	M							
Unwanted Vegetation Growth	U	U	U							
Sod Cover	N/A	N/A	N/A							
Encroachments	U	U	U							
Closure Structures	N/A	N/A	N/A							
Slope Stability	M	M	M							
Erosion/Bank Caving	U	U	M							
Settlement	U	A	A							
Depressions/Rutting	M	U	A							
Cracking	A	A	A							
Animal Control	U	U	M							
Culverts/Discharge Pipes	N/A	N/A	N/A							
Riprap Revetments & Bank Protection	U	N/A	M							
Revetments other than Riprap	N/A	N/A	N/A							
Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	N/A							
Seepage	A	M	A							
Segment & System Ratings/PL 84-99 Eligibility							<u>Legend</u>			
Likely Prevents Performance In Next Flood Event							A	Acceptable		
Serious deficiency noted in past inspections has not been corrected within the established timeframe							M	Minimally Acceptable		
Not Likely to Prevent Performance In Next Flood Event							U	Unacceptable		
							N/A	Not Applicable		
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Rehabilitation Eligibility										
									02/22/12	