

System RD 0341 - Sherman Island - Units 1&2 Unacceptable - Inactive		RD 0341 - Sherman - Unit 1, Three Mile Slough (SHM1)		RD 0341 - Sherman - Unit 2, Sacramento River (SHM2)									
General	Operations and Maintenance Manuals	A	A										
	Emergency Supplies and Equipment	A	A										
	Flood Preparedness and Training	A	A										
Levee Embankments	Unwanted Vegetation Growth	U	U										
	Sod Cover	NA	NA										
	Encroachments	U	U										
	Closure Structures	NA	NA										
	Slope Stability	A	U										
	Erosion/Bank Caving	U	U										
	Settlement	M	U										
	Depressions/Rutting	A	M										
	Cracking	A	A										
	Animal Control	A	A										
	Culverts/Discharge Pipes	NA	NA										
	Riprap Revetments & Bank Protection	NA	NA										
	Revetments other than Riprap	NA	NA										
	Underseepage Relief Wells/Toe Drainage Systems	NA	NA										
Seepage	A	A											
The lowest rating is used to determine the overall segment & system ratings and PL 84-99 Eligibility						<u>Legend</u>							
						Likely Prevents Performance In Next Flood Event/Inactive				A	Acceptable		
						Serious deficiency noted in past inspections has not been corrected within the established timeframe				M	Minimally Acceptable		
						Not Likely to Prevent Performance In Next Flood Event/Active				U	Unacceptable		
				N/A	Not Applicable								