

-
- (2) the occurrence of bank failures combined with fine-grained content of the streambanks (Figure 4-19).

In addition, results are shown graphically, displaying these data relative to distance above the stream mouth (Figure 4-20).




Figure 4-18. Results of rapid geomorphic assessments of the Upper Truckee River showing the relative contributions of channel- and side-slope indexes to the combined stability index, and critical erosion areas.