

Geomorphic interpretations made during the stream walk and evaluated during RGAs are further summarized spatially with maps depicting the:

- (1) combined-, channel-, and side-slope erosion indexes (Figure 4-24), and
- (2) the occurrence of bank failures combined with fine-grained content of the streambanks (Figure 4-25).

In addition, results are shown graphically, displaying these data relative to distance above the stream mouth (Figure 4-26).




Figure 4-23. Map of the relative contribution of fine sediment from streambank erosion for Blackwood Creek.