

Figure 4-46. Results of rapid geomorphic assessments of Logan House Creek showing the relative contributions of channel- and side-slope indexes to the combined stability index and critical erosion areas.