
Final

POL Hill AST-2 Area Corrective Action Plan

Prepared for
U.S. Army Corps of Engineers

February 2004

CH2MHILL
2485 Natomas Park Drive, Suite 600
Sacramento, CA 95833-2937



DEPARTMENT OF THE ARMY
BASE REALIGNMENT AND CLOSURE
ATLANTA FIELD OFFICE
BRAC ENVIRONMENTAL COORDINATOR
HAMILTON ARMY AIRFIELD
1 BURMA ROAD
NOVATO, CALIFORNIA 94949



February 20, 2004

DAIM-BO-A-HA

Subject: Forwarding the *POL Hill AST-2 Area Corrective Action Plan* for Hamilton Army Airfield; Novato, CA.

Ms. Naomi Feger
S.F. Bay Regional Water Quality Control Board
1515 Clay Street, Suite 1400
Oakland, CA 94612

Dear Naomi,

The Army is pleased to provide the *POL Hill AST-2 Area Corrective Action Plan* for Hamilton Army Airfield; Novato, CA for your files.

If you have any questions, please contact me at (415) 883-6386.

Sincerely,

Edward Keller, P.E.
BRAC Environmental Coordinator
Hamilton Army Airfield

Enclosure

Copies Furnished

R. Seraydarian (EPA)
D. Diebert (DTSC)
L. McMahan (DTSC)
M. Neilan (City of Novato)
D. Doak (USACE SF)
T. Gandesbery (CSCC)
Novato Library
BRAC Files

Final

POL Hill AST-2 Area Corrective Action Plan

Submitted to
U.S. Army Corps of Engineers

February 2004

CH2MHILL

Contents

Section	Page
Acronyms and Abbreviations	iv
Executive Summary	ES-1
1. Introduction.....	1-1
1.1 Site History and Problem Statement	1-1
1.2 Purpose and Objective	1-5
1.3 Regulatory Authority, Guidance, and Current Regulatory Status.....	1-6
1.4 Report Organization.....	1-7
2. Description of Site Conditions	2-1
2.1 HAAF Background and History	2-1
2.2 POL Hill AST-2 Area Description.....	2-2
2.3 Geology and Hydrogeology	2-2
2.4 Field Investigations and Environmental Studies Prior to the RI	2-3
2.4.1 Excavation and Sampling.....	2-6
2.4.2 Phase I and II Environmental Investigations.....	2-9
2.4.3 Supplemental Investigation	2-9
2.5 Remedial Investigations and Actions	2-10
2.6 Nature and Extent of Contamination.....	2-11
2.6.1 Determination of the Potential Chemicals of Concern.....	2-11
2.6.2 Extent of Contamination.....	2-13
2.7 Data Comparability	2-17
3. Corrective Action Objective Developments	3-1
3.1 COCs	3-1
3.2 Applicable Regulations.....	3-2
3.2.1 Chemical-Specific Applicable Requirements.....	3-2
3.2.2 Location-Specific Applicable Regulations.....	3-2
3.2.3 Action-Specific Applicable Regulations	3-2
3.2.4 Other Guidance Documents	3-3
3.3 Corrective Action Objective Development	3-3
3.3.1 Potential Exposure Pathways	3-4
3.3.2 Cleanup Criteria.....	3-4
3.3.3 Impacted Areas and Volumes	3-4
4. Identification of Corrective Action Technologies	4-1
4.1 Soil Technologies	4-1
4.2 Groundwater Technologies	4-1
4.2.1 Institutional Controls	4-1
4.2.2 In Situ Biodegradation	4-2
4.2.3 Monitored Natural Attenuation.....	4-2

5. Development of Corrective Action Alternatives	5-1
5.1 Corrective Actions Alternatives for Soil	5-1
5.2 Corrective Actions Alternatives for Groundwater	5-1
5.2.1 No Action	5-1
5.2.2 Institutional Controls	5-2
5.2.3 In Situ Biodegradation	5-2
5.2.4 Monitored Natural Attenuation.....	5-2
5.3 Analysis of Alternatives	5-3
6. Recommended Corrective Action Alternatives.....	6-1
6.1 Corrective Action for Soil.....	6-1
6.2 Corrective Action for Groundwater.....	6-1
7. Interim Monitoring Program and Strategy for Determining Suitability for Site Closure	7-1
7.1 Groundwater Monitoring Summary.....	7-1
7.2 Interim Groundwater Monitoring Plan.....	7-2
7.3 Strategy for Determining Suitability for Site Closure	7-4
8. References	8-1

Appendices

A	Recent Remedial Investigation Results
B	Boring Logs and Well Construction Diagrams
C	Well Development and Well Survey Data
D	Field Documentation
E	Validated Data
F	Aquifer Test Data
G	Cost Estimates
H	Monitored Natural Attenuation Summary
I	Groundwater Monitoring Report, August 2002

Tables

2-1	Previous Field Investigations and Engineering Studies Related to POL Hill AST-2
2-2	GSA Residential Cleanup Goals for Analytes Detected in Groundwater Beneath AST-2 Area
4-1	Total Petroleum Hydrocarbons and Benzene, Toluene, Ethylbenzene, and Xylenes in AST-2 Groundwater Samples
4-2	Estimated Half-Lives and Projected Cleanup Times
5-1	Corrective Action Alternative Analysis

Figures

- 1-1 Site Location Map
- 1-2 BRAC Property Location Map
- 1-3 Well Location Map

- 2-1 Total Petroleum Hydrocarbon Concentrations in Groundwater, March 1994
- 2-2 Total Petroleum Hydrocarbon Concentrations in Groundwater, February 1997
- 2-3 Total Petroleum Hydrocarbon Concentrations in Groundwater, March/April 1998
- 2-4 Total Petroleum Hydrocarbon Concentrations in Groundwater, January 1999

Acronyms and Abbreviations

µg/L	micrograms per liter
Army	U.S. Department of the Army
AST	aboveground storage tank
ASTM	American Society of testing and Materials
bgs	below ground surface
BRAC	Base Realignment and Closure
BTEX	benzene, toluene, ethylbenzene, and xylene
°C	degrees Celsius
CAP	corrective action plan
cm/sec	centimeters per second
COC	chemical of concern
CQC	Contractor Quality Control
DO	dissolved oxygen
DTSC	Department of Toxic Substances Control
EI	environmental investigation
EPA	U.S. Environmental Protection Agency
ESI	Engineering-Science, Inc.
gal	gallon
GC	gas chromatography
GSA	General Services Administration
HAAF	Hamilton Army Airfield
IR	infrared spectroscopy
JP-4	Jet Propellant 4
mL/min	milliliters per minute
MNA	monitored natural attenuation
NCP	National Contingency Plan
ND	nondetect

NHP	New Hamilton Partnership
PCB	polychlorinated biphenyls
PCOC	potential contaminants of concern
PNA	polynuclear aromatic hydrocarbon
POL	petroleum, oil, and lubricant
PQL	practical quantitation limits
RAO	remedial action objectives
RCG	residential cleanup goal
RI	remedial investigation
RWQCB	Regional Water Quality Control Board
SAP	Sampling and Analysis Plan
TPH	total petroleum hydrocarbon
TRPH	total recoverable petroleum hydrocarbons
URC	unit risk concentration
USACE	U.S. Army Corps of Engineers
USAF	U.S. Air Force
UST	underground storage tank
VOC	volatile organic compound
Weston	Roy F. Weston, Inc.