
Report

Final Environmental Baseline Survey Hospital Hill and POL Hill

Prepared for
Department of the Army



U.S. Army Corps of Engineers

November 2001

CH2MHILL
2485 Natomas Park Drive, Suite 600
Sacramento, California 95833

Contents

Section	Page
Acronyms and Abbreviations	v
Executive Summary	ES-1
Methodology.....	ES-1
Findings	ES-1
Property Categorization.....	ES-2
1.0 Introduction	1-1
1.1 Background	1-1
1.2 Authority for the EBS	1-3
1.3 Objective	1-3
1.3.1 DoD Property Classification.....	1-3
1.4 Organization of EBS.....	1-4
1.5 Limitations	1-4
2.0 Survey Methodology	2-1
2.1 Existing Investigation Documents.....	2-1
2.2 Federal, State And Local Government Regulatory Records	2-1
2.3 Aerial Photographs	2-2
2.4 Interviews.....	2-2
2.5 Visual Site Inspection	2-3
2.5.1 Visual Site Inspection Approach.....	2-3
2.5.2 Purpose of the Visual Site Inspection.....	2-3
2.5.3 Visual Site Inspection Summary Overview.....	2-3
2.5.4 VSIs of HAAF Adjacent Properties	2-3
2.6 Title Documents	2-4
3.0 Property Characterization	3-1
3.1 General Property Information	3-1
3.2 Description of Facilities	3-1
3.2.1 Hospital Hill.....	3-1
3.2.2 POL Hill.....	3-4
3.3 Property History.....	3-7
3.3.1 HAAF.....	3-7
3.3.2 Hospital Hill.....	3-8
3.3.3 POL Hill.....	3-8
3.4 Tenant Activities	3-9
3.5 Permitting Status.....	3-9
3.6 Surrounding Environment and Land Uses	3-10
3.6.1 Demographics.....	3-10

3.6.2 Climatology.....3-10

3.6.3 Hydrology3-11

3.6.4 Geology and Hydrogeology3-11

3.6.5 Sensitive Environments.....3-13

4.0 Investigation Results4-1

4.1 Categorization Factor Findings: New Areas Identified by
EBS Investigation4-1

4.2 Categorization Factor Findings: Previously Identified Sites.....4-1

4.2.1 Petroleum Use and Storage4-1

4.2.2 Petroleum Release4-2

4.2.3 Petroleum Remediation.....4-6

4.2.4 Hazardous Substances Use and Storage.....4-8

4.2.5 Hazardous Substances Release4-8

4.2.6 Hazardous Substances Remediation4-8

4.3 Adjacent or Surrounding Property Sources4-9

4.3.1 Visual Site Inspection Findings4-9

4.3.2 Record Search Findings.....4-9

4.4 Disclosure of Non-CERCLA Issues4-11

4.4.1 Asbestos.....4-11

4.4.2 Lead-Based Paint.....4-14

4.4.3 PCBs4-14

4.4.4 Radon.....4-17

4.4.5 Ordnance4-17

4.4.6 Radionuclides4-17

4.4.7 Surface Water and Storm Water Issues.....4-18

4.4.8 Sanitary Sewer System4-18

4.4.9 Waste Management4-19

4.4.10 RCRA Facilities/SWMUs.....4-20

5.0 CERFA Letter Report5-1

5.1 Executive Summary5-1

5.2 Summary of Findings5-2

5.2.1 CERFA Uncontaminated Parcels5-2

5.2.2 Non-CERFA Parcels.....5-2

5.2.3 Disclosure Factors5-5

5.3 Data Gaps5-5

6.0 References.....6-1

Appendices

- A List of Documents Reviewed
- B Summary of VISTA Report
- C Real Estate Map HAAF 1948

Tables

ES-1 DoD Environmental Condition Categories for Hospital Hill and POL Hill..... ES-2

3-1 Total Acreage of Hospital Hill and POL Hill3-1

3-2 List of Past and Present Structures at Hospital Hill3-4

3-3 List of Past and Present Structures at POL Hill3-7

4-1 List of Fuel Storage Tanks at Hospital Hill.....4-1

4-2 List of Fuel Storage Tanks at POL Hill.....4-2

4-3 Potential Areas of Environmental Concern Identified by Records Review.....4-10

4-4 Asbestos Findings at Hospital Hill4-12

4-5 Asbestos Findings at POL Hill4-13

4-6 Lead-Based Paint Findings4-14

4-7 Transformers Identified at Hospital Hill4-15

5-1 DoD Environmental Condition Categories5-1

5-2 CERFA Map Summary5-4

5-3 Summary of Disclosure Factors5-5

Figures

ES-1 EBS Property Categorization..... ES-3

1-1 Location Map Hospital Hill and POL Hill..... 1-2

3-1 Site Location Map.....3-2

3-2 Site Map of Hospital Hill3-3

3-3 Site Map of POL Hill.....3-5

3-4 POL Hill Tank Farm Area.....3-6

5-1 CERFA Map5-3

Acronyms and Abbreviations

AMEDD	Army Medical Department
AST	Aboveground Storage Tank
ASTM	American Society for Testing and Materials
BCP	BRAC Cleanup Plan
BRAC	Base Realignment and Closure
Cal EPA	California Environmental Protection Agency
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
CERCLIS	Comprehensive Environmental Response and Contamination Liability Act List
CERFA	Community Environmental Response Facilitation Act
CSM	Coastal Salt Marsh
DoD	Department of Defense
DTSC	Department of Toxic Substances Control
EA	Environmental Assessment
EBS	Environmental Baseline Survey
ERNS	Emergency Response Notification System
ESD	Explanation of Significant Differences
GSA	General Services Administration
HAAF	Hamilton Army Airfield
LUST	Leaking Underground Storage Tank
NEPA	National Environmental Policy Act
NFRAP	No Further Remedial Action Planned
NHP	New Hamilton Partners
NPL	National Priorities List
PCB	polychlorinated biphenyl
POL	Petroleum, Oil, and Lubricant
RCG	Residential Cleanup Goal

RCRA	Resource Conservation and Recovery Act
RCRIS-LQG	Resource Conservation and Recovery Information System—Large Quantity Generators
RCRIS-SQG	Resource Conservation and Recovery Information System—Small Quantity Generators
RCRIS-TSD	Resource Conservation and Recovery Information System—Treatment, Storage, and Disposal Facilities
ROD	Record of Decision
RWQCB	Regional Water Quality Control Board
SCL	California Sites Database
SPL	Sites Priorities List
SS Line	Sanitary Sewer Line
SWLF	Solid Waste Landfills
SWMU	Solid Waste Management Unit
SWPPP	Storm Water Prevention Plan
TPH	Total Petroleum Hydrocarbons
USACE	US Army Corps of Engineers
USAEC	U.S. Army Environmental Center
USAF	US Air Force
USC	United States Code
USEPA	U.S. Environmental Protection Agency
UST	Underground Storage Tanks
VSI	Visual Site Inspection
WMUDS	Waste Management Unit Data System